



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date: 9/3/2020
Vehicle: SLP1482J
Make / Model: TOYOTA AXIO
Chassis: NZ260-3029205

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	BONNET	1	\$ 809.00	\$ 809.00
2	FRONT BUMPER	1	\$ 425.00	\$ 425.00
3	FRONT BUMPER REINFORCEMENT	1	\$ 305.00	\$ 305.00
4	FRONT BUMPER SIDE RETAINER LH	1	\$ 52.00	\$ 52.00
5	FRONT HEADLAMP LH	1	\$ 600.00	\$ 600.00
6	FRONT FENDER LH	1	\$ 718.00	\$ 718.00
7	FRONT FENDER INNER SEAL LH	1	\$ 180.00	\$ 180.00
8	FRONT SUPPORT PANEL	1	\$ 870.00	\$ 870.00
				\$ 3,959.00
			Less 25%	\$ 989.75
			Total	\$ 2,969.25
S/Nett items:				
1	FRONT BUMPER CLIPS	1 SET	\$ 80.00	\$ 80.00
2	FRONT FENDER INNER SEAL CLIPS LH	1 SET	\$ 80.00	\$ 80.00
3	FRONT SOPRT RIM LH	1	\$ 220.00	\$ 220.00
4	FRONT TYRE LH	1	\$ 125.00	\$ 125.00
				\$ 505.00
Labour to:				
1	TO CHECK REAR ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
2	TO RESPRAY UNDERCOATING	1	\$ 100.00	\$ 100.00
3	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 120.00	\$ 120.00
4	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
5	PANEL BEATING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
				\$ 1,900.00
			Parts Replacement Amount	\$ 3,474.25
			Total Amount for Labour	\$ 1,900.00
			Total Amount	\$ 5,374.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 2741571
WP
10/3/2020 320.
0 4 days
Lump sum
Resurvey after repair.
s Taufik@lkkauto.com.