



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 645G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BALANCER HANDLE	SCRATCHED	55.00	55.00
1	BOARD FLOOR SET WITH SLIDER BLACK	CUT	150.00	150.00
1	BOARD, FOOTREST 2	CUT	13.00	13.00
1	BOARD, FOOTREST, 1	CUT	13.00	13.00
1	BOX REAR (KAPPA) K42N W/O LIGHT BLACK	CUT	191.00	191.00
1	COVER BOX FILTER AIR	CUT	11.00	11.00
1	COVER COWLING LH	CUT	28.00	28.00
1	COVER COWLING RH	NOT NECESSARY	31.00	-
1	COVER DELTA BOX	* CHECK	26.00	-
1	COVER FRONT BOX FILTER AIR	CUT	5.00	5.00
1	COVER PANEL 2	* CHECK	10.00	-
1	COVER PANEL LH	CUT	10.00	10.00
1	COVER SIDE 1	* CHECK	10.00	-
1	COVER SIDE 1	* CHECK	20.00	-
1	COVER, CRANKCASE 3	CUT	20.00	20.00
1	COVER, SIDE 2	CUT	20.00	20.00
1	DAMPER COVER SIDE 2	* CHECK	3.00	-
1	DAMPER COVER SIDE 3	* CHECK	2.00	-
1	DAMPER COVER SIDE 4	* CHECK	5.00	-
1	DAMPER SIDE COVER	* CHECK	5.00	-
1	EXHAUST SLIDER	TORN	121.00	121.00
1	FOOTREST SIDE COVER RH	DISTORTED	10.00	10.00
1	GASKET EXHAUST PIPE	NOT NECESSARY	13.00	-
1	INNER FENDER COVER	* CHECK	20.00	-
1	LEGSHIELD 1, MATT BLACK	CUT	26.00	26.00
1	LEVER BRAKE LH	CUT	13.00	13.00
1	SET MIRROR	CUT	38.00	38.00
1	MUDGUARD FRONT	CUT	38.00	38.00
1	MUFFLER ASSY	NOT NECESSARY	360.00	-
1	PROTECTOR MUFFLER	CUT	31.00	31.00
5	RIVET @\$2.00	* CHECK	10.00	-

Report Ref No. CS/AGI20003891/Usf3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
4	SCREW (VISOR) @\$3.00	* CHECK	12.00	-
1	STAND MAIN ASSY	TO REPAIR SEE LABOUR	13.00	-
1	STAND SIDE BIG FOOT	* CHECK	54.00	-
1	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT	NECESSARY	20.00	10.00
1	VISOR	BROKEN	35.00	35.00
	LESS 10% DISCOUNT		-	-83.80
			1,442.00	754.20
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	STICKER (SN)	NECESSARY	3.00	3.00
1	STICKER (SN)	NECESSARY	3.00	3.00
			6.00	6.00
	<b><u>LABOUR</u></b>			
	LABOUR. INCLUSIVE OF THE REPAIR OF STAND MAIN ASSY.		552.00	250.00
			552.00	250.00
<b>GRAND TOTAL</b>			<b>2,000.00</b>	<b>1,010.20</b>
<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$159.30 NETT)</b>				<b>1,010.20</b>

Report Ref No. CS/AGI20003891/Usf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.