

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20003892/R1TF3E2

Date: 11/03/2021

REFERENCE

Insured/Claimant:	CHEN YIN LIANG	Policy No:	1900081739	
Date of Loss:	09/03/2020	Nature of Claim:	OD	Claim No: 8585271960SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDP9000J		
Make & Model:	AUDI A4, 2.0 TFSI QU S-TRONIC (A)	Engine No:	CVK077188
Reg. Date:	28/03/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF46KA042260
Colour:	Grey	Odometer:	14389 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$129,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35ZR19	Rear Tyre Size:	245/35ZR19
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,379.00	8,569.00	11,810.00	57.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,442.00	2,522.00	4,920.00	66.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	27,821.00	11,091.00	16,730.00	60.13
+ GST 7.00/7.00% (S\$)	1,947.47	776.37	1,171.10	60.13
Nett Amount (S\$)	29,768.47	11,867.37	17,901.10	60.13

INSPECTION

Date of Assignment:	12/03/2020		
Date Inspected:	11/03/2020	Inspected At:	24 BENOI SECTOR Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$7,582.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,068.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	553.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	Not Necessary	34.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	198.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE-LH	Not Necessary	59.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	127.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION-LH	Not Necessary	34.00 FS	*- FS
8	1		*FRONT FENDER-LH	Bent	722.00 FS	*722.00 FS
9	1		*FRONT FENDER CLOSING ELEMENT-LH	Not Necessary	47.00 FS	*- FS
10	1		*FRONT FENDER ATTACHMENT PARTS	Necessary	190.00 FS	*190.00 FS
11	1		*FRONT FENDER BRACKET-LH	*Check	33.00 FS	*- FS
12	1		*FRONT FENDER BRACKET DEFORMATION ELEMENT-LH	*Check	46.00 FS	*- FS
13	1		*FRONT FENDER BRACE-LH	*Check	112.00 FS	*- FS
14	1		*FRONT WHEEL HOUSING LINER-LH	*Check	226.00 FS	*- FS
15	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-LH	Necessary	219.00 FS	*219.00 FS
16	1		*FRONT WHEEL SPOILER	Cracked	69.00 FS	*69.00 FS
17	1		*FRONT FENDER MOLDING TRIM-LH	Not Necessary	33.00 FS	*- FS
18	1		*FRONT STONE CHIP GUARD-LH	Necessary	48.00 FS	*48.00 FS
19	1		*FRONT FENDER COVER-LH	*Check	21.00 FS	*- FS
20	1		*LED HEADLIGHT-LH	Scratched	7,321.00 FS	*7,321.00 FS
21	1		*LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM-LH	Not Necessary	198.00 FS	*- FS
22	1		*FRONT WISHBONE LINK-LH	*Check	507.00 FS	*- FS
23	1		*FRONT SUSPENSION GUIDE-LH	*Check	887.00 FS	*- FS
24	1		*FRONT SUSPENSION UPPER CONTROL ARM-LH	*Check	480.00 FS	*- FS
25	1		*FRONT TRACK CONTROL ARM-LH	*Check	480.00 FS	*- FS
26	1		*FRONT WHEEL BEARING HOUSING-LH	*Check	912.00 FS	*- FS
27	1		*FRONT SWIVEL JOINT	*Check	182.00 FS	*- FS
28	1		*FRONT WHEEL HUB-LH	*Check	460.00 FS	*- FS
29	1		*FRONT WHEEL BEARING-LH	*Check	237.00 FS	*- FS
30	1		*FRONT SUSPENSION FORKS-LH	Not Necessary	249.00 FS	*- FS
31	1		*FRONT COUPLING ROD-LH	Not Necessary	125.00 FS	*- FS
32	1		*FRONT DRIVE SHAFT-LH	Not Necessary	2,498.00 FS	*- FS
33	1		*FRONT GAS SHOCK ABSORBER-LH	Not Necessary	284.00 FS	*- FS
34	1		*FRONT TIE ROD END-LH	*Check	186.00 FS	*- FS
35	1		*FRONT TRACK ROD-LH	*Check	93.00 FS	*- FS
36	1		*FRONT STEERING GEAR GREASE	Not Necessary	41.00 FS	*- FS
37	1		*FRONT RIM-LH (NPA)	Scratched	0.00 FS	*- FS
38	1		*SUNDRIES	*Check	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 20,379.00 8,569.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY *Check	New	1,800.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,450.00	750.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	1,100.00
5	TO RENEW LHS FRONT RIM.TO CARRY OUT PRE-WHEEL ALIGNMENT AND POST-WHEEL ALIGNMENT TEST *Check	New	520.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			7,442.00	2,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >