

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP :32413

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0264/2020/GW
Date	:	11-Mar-20

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Chen Yin Liang
Address	:	Blk 293 Ocean Dive #03-17 Singapore 098533
Telephone	:	HP +65 96821911
Type of Claim	:	Own Damage Claims
Policy No.	:	1900081739
Vehicle No	:	SDP 9000 J
Model Code	:	Audi A4 Sedan 2.0 TFSI
Model / Year	:	Sep-18
Engine No	:	CVK077188
Chassis No	:	WAUZZZF46KA042260
Mileage	:	
Date In	:	28-Mar-19
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	09-Mar-20
Place of Accident	:	Junction of Coleman ST.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDP 9000 J

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$ 480.00 /	
2	To remove and renew lhs front wheel suspension assy.	S/N	\$ 1,800.00 ?	
3	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise crash menagement components. Reinstall all parts removed.		\$ 2,450.00 750	
4	To respray front bumper and lhs front fender.		\$ 2,000.00 1100	
5	To renew lhs front rim. To carry out pre-wheel alignment and post- wheel alignment test.	S/N	\$ 520.00 ?	
6	To carry out diagnostic check.	S/N	\$ 192.00 /	
TOTAL LABOUR CHARGES		:	<u>\$ 7,442.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDP 9000 1

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Repair</i>	\$ 2,068.00	
2	FRONT BUMPER FIXING PARTS <i>X</i> nn	\$ 553.00	
3	FRONT BUMPER SECURING STRIP <i>X</i> nn	\$ 34.00	
4	FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE <i>X</i> nn	\$ 198.00	
5	FRONT BUMPER AIR GUIDE-LH <i>X</i> nn	\$ 59.00	
6	FRONT BUMPER AIR GUIDE GRILLE-LH <i>X</i> nn	\$ 127.00	
7	FRONT BUMPER GUIDE SECTION-LH <i>X</i> nn	\$ 34.00	
8	FRONT FENDER-LH <i>4</i>	\$ 722.00	
9	FRONT FENDER CLOSING ELEMENT-LH <i>X</i> nn	\$ 47.00	
10	FRONT FENDER ATTACHMENT PARTS <i>ner</i>	\$ 190.00	
11	FRONT FENDER BRACKET-LH <i>?</i>	\$ 33.00	
12	FRONT FENDER BRACKET DEFORMATION ELEMENT-LH <i>?</i>	\$ 46.00	
13	FRONT FENDER BRACE-LH <i>?</i>	\$ 112.00	
14	FRONT WHEEL HOUSNG LINER-LH <i>?</i>	\$ 226.00	
15	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-LH <i>ner</i>	\$ 219.00	
16	FRONT WHEEL SPOILER <i>cm</i>	\$ 69.00	
17	FRONT FENDER MOLDING TRIM-LH <i>X</i> nn	\$ 33.00	
18	FRONT STONE CHIP GUARD-LH <i>ner</i>	\$ 48.00	
19	FRONT FENDER COVER-LH <i>?</i>	\$ 21.00	
20	LED HEADLIGHT-LH <i>scr</i>	\$ 7,321.00	
SUB-TOTAL SPARE PARTS CHARGES		: \$ 12,160.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDP 90001

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	LIGT CYLINDER FOR HEADLIGHT WASHER SYSTEM-LH X nn	\$	198.00
22	FRONT WISHBONE LINK-LH ?	\$	507.00
23	FRONT SUSPENSION GUIDE-LH ?	\$	887.00
24	FRONT SUSPENSION UPPER CONTROL ARM-LH ?	\$	480.00
25	FRONT TRACK CONTROL ARM-LH ?	\$	480.00
26	FRONT WHEEL BEARING HOUSING-LH ?	\$	912.00
27	FRONT SWIVEL JOINT ?	\$	182.00
28	FRONT WHEEL HUB -LH ?	\$	460.00
29	FRONT WHEEL BEARING-LH ?	\$	237.00
30	FRONT SUSPENSION FORKS-LH X nn	\$	249.00
31	FRONT COUPLING ROD -LH X nn	\$	125.00
32	FRONT DRIVE SHAFT -LH X nn	\$	2,498.00
33	FRONT GAS SHOCK ABSORBER-LH X nn	\$	284.00
34	FRONT TIE ROD END-LH ?	\$	186.00
35	FRONT TRACK ROD-LH ?	\$	93.00
36	FRONT STEERING GEAR GREASE X nn	\$	41.00
37	FRONT RIM-LH sca /		TBC
38	SUNDRIES ?	\$	400.00
TOTAL SPARE PARTS CHARGES		:	\$ 20,379.00
TOTAL LABOUR CHARGES		:	\$ 7,442.00
GRAND TOTAL		:	\$ 27,821.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Rasul - Hp 90010068

Surveyed Date

: 11/03/2020 @ 1645

Authorised Date

: 4 days

Excess Cost

:

Liability

:

Remarks

:

EXCESS : TBA

Resurvey

Resurvey before paint

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant