



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/AAP20003898/R1sf3e2

C/O:AREDA ADJUSTERS PL

50 RAFFLES PLACE #05-01/06 SINGAPORE LAND Date : 16-03-2020

TOWERSINGAPORE 398007



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	GBF 7013L
Policy No.	2095055/DK	Coverage (\$)	0.00
Claim No.	CLBD2000020	Excess (\$)	0.00
Assign From	DERRICK KWEH	Assign Date	12/03/2020

2. Vehicle Particulars & Condition

Make & Model	NISSAN CABSTAR 3.0 5M/T	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JN1SC2F24Z0859180	Colour	GOLD
Odometer	98279	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	DUNLOP	6 mm
L/H Front Tyre	195 R15C	DUNLOP	6 mm
R/H Rear Tyre	155 R13 (D)	DUNLOP	5/5 mm
L/H Rear Tyre	155 R13 (D)	DUNLOP	5/5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE ROOFTOP PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/02/2020	Inspection Date	13/03/2020
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		

5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIR.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------