

parts 4299.90
 parts less 10%
 3869.91
 196 ✓ 930
 4799.91

AIGAsia Insured's Veh No : SMG5479D

Date of Accident : 08 March 2020

4/s less 20%
 total 3839.92
 4/s amt → \$3850
 Messrs BIS Motoring Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification to be carried out
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

Date : 09 March 2020

Estimate To Repair SML5729G - Renault Grand Scenic IV 1.5 DCI AT EU6

Chassis No : VF1RFA00762894733

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	front bumper ✓ CNA	\$ 1,550.00
02	1 pc	n/s front bumper side garnish ✓ CNA 1/H	\$ 117.20
03	1 pc	front bumper lower grille X (svc)	\$ 427.40
04	1 pc	front bumper absorber foam X (svc)	\$ 180.00
05	1 pc	front bumper reinforcement X (svc)	\$ 624.20
06	4 pc	front bumper lower air guide clip @ \$3.50 X (svc)	\$ 14.00
07	1 pc	front bumper lower lip ✓ SCN	\$ 436.00
08	1 pc	n/s front bumper fog lamp X (svc)	\$ 222.60
09	1 pc	n/s front bumper fog lamp outer chrome ✓ SCN 1/H	\$ 234.10
10	1 pc	n/s front bumper fog lamp trim cover 1/H ✓ SCN	\$ 234.10
11	2 ps	n/s front bumper parking sensor @ \$560.00 1/H only ✓ short	\$ 1,120.00
12	1 pc	n/s front bumper base X	\$ 363.30
13	1 pc	radiator grille X (svc)	\$ 427.40
14	1 pc	radiator grille outer chrome ✓ SCN	\$ 261.10
15	1 pc	radiator grille garnish X (svc)	\$ 266.40
16	1 pc	radiator grille top bracket X (svc)	\$ 112.30
17	1 pc	n/s headlamp 1/H ✓ CNA	\$ 980.00
18	1 pc	n/s headlamp bracket ✓ BT 1/H	\$ 112.30
19	1 pc	n/s front fender ✓ 1/H CNA	\$ 615.20
20	1 pc	n/s front fender inner cowling ✓ CNA 1/H	\$ 250.40
21	3 ps	n/s front fender inner cowling clip @ \$5.00 ✓ SCN	\$ 15.00
22	1 pc	front support panel top garnish X (svc)	\$ 393.30
Less 10 %			\$ 8,956.30
			\$ 895.63
			\$ 8,060.67
<u>LABOUR & MISC. CHARGES</u>			
01		To check electrical lighting concerned.	\$ 80.00
02		To rust-proofing of the affected areas.	\$ 120.00
03		To reinstall of front bumper parking sensor.	\$ 50.00
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 750.00
05		Putty and spray painting of the affected portion.	\$ 700.00
			\$ 1,700.00
Total			\$ 9,760.67

11/3/20
 85311883 / 67418434
 3.00pm
 ANN@LKKAuto.com

Approved
 H ANN
 3.40pm