

Vehicle number	SLB37955
Make / Model	HONDA/ODYYSEY 2.4 EXV
Chassis number	JHMRC1890GC203000
Accident date	08 March 2020
Reference	2003-21

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT RH FENDER	617.55 R
1	FRONT RH FENDER INNER SHIELD	135.00 ?
1	FRONT GRILLE ASSY	189.75 x
1	FRONT GRILLE MOULDING	355.35 x
1	FRONT LOWER GRILLE	247.25 x
1	FRONT LOWER GRILLE MOULDING	288.60 x
1	FRONT BUMPER	819.40 de
2	FRONT BUMPER RETAINER	86.00 RH new
1	FRONT BUMPER SIDE GRILLE RH	90.00 wtr
1	FRONT BUMPER FOG LAMP RH	300.15 ?
1	FRONT BUMPER LOWER GRILLE RM	89.70 xat
1	FRONT BUMPER REINFOCEMENT	299.00 ?
1	FRONT RH HEADLAMP	2572.55 ?
1	WIPER WASHER TANK	173.10 x
		6263.40
Less 20%		1252.68
Subtotal		5010.72
Balance C/F		5010.72
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1 SET	FRONT BUMPER CLIP	30.00 net
1 SET	FRONT GRILLE CIIP	20.00 x
1SET	FRONT LH FENDER INNER TRIM CLIP	20.00 ?
Subtotal		70.00
Balance C/F		5080.72
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
Balance B/F		5080.72
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 30
2	COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT	150.00 x
3	PANEL BEATING ON AFFECTED ARERAS	800.00 400
4	SPRAY PAINTING ON AFFECTED AREAS	800.00 400
5	APPLY ANTI RUST ON AFFECTED AREAS	100.00 30
Subtotal		1910.00
Grand total		6990.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97495749 WP
Lumpsum
Resurvey after repair
10/3/20
Tanpin Khanthan