

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG20003907/UPA3Q2**Date:** 03/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993998
<b>Claimant Vehicle No :</b>	YP4012J	<b>Insured Vehicle No :</b>	GBJ7296R
Date of Loss:	06/03/2020	Nature of Claim:	TP
		Claim No:	9213112203SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>YP4012J</b>		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU) (M)	Engine No:	4P10C34956
Reg. Date:	21/09/2016 (Man. Year: 2016)	Chassis No:	FEB21EA20936
Colour:	White	Odometer:	11904 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15 (D)
Front Left Side:	Austone 6 mm	Rear Left Side:	Austone 6/6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Austone 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,734.00	2,693.75	1,040.25	27.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	710.00	340.00	32.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,784.00</b>	<b>3,403.75</b>	<b>1,380.25</b>	<b>28.85</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>4,784.00</b>	<b>2,700.00</b>	<b>2,084.00</b>	<b>43.56</b>
<b>+ Loss of Use (4.0 x S\$80.00/day) (S\$)</b>		320.00		
		<b>(S\$)</b>		
		3,020.00		
<b>Liabile Amount (50.00%) (S\$)</b>		<b>1,510.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>1,517.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,500.00</b>		

**INSPECTION**

Date of Assignment:	12/03/2020	
Date Inspected:	12/03/2020 Inspected At:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT Singapore 417883
Estimated Period of Repair:	3.0 days	

**Adjuster:** MARCUS CHUA

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR SIDEGATE (N/S)	Dented / Bent	2,840.00 F	*2,840.00 FL	
2	1		*REAR WHEEL FENDER (N/S)	Grazed	694.00 F	*485.00 FL	
3	1		*REAR CORPORATE ADVERTISEMENT & ARTWORK (N/S)	Necessary	200.00 FS	*200.00 FS	
					<b>Sub Total (S\$)</b>	<b>3,734.00</b>	<b>3,525.00</b>
					<b>- List Item Discount on L Items 0.00/25.00% (S\$)</b>	0.00	831.25
					<b>Total Parts (S\$)</b>	<b>3,734.00</b>	<b>2,693.75</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	400.00	300.00
2	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA	New	600.00	380.00
3	TO APPLY RUST PROOFING RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	50.00	30.00
			<b>Gross Labour Cost (\$\$)</b>	<b>710.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >