

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: YP4012|200306

Estimate**Customer**

Name: AIG Asia Pacific Insurance Pte Ltd

Date: 11-03-20

Address Motor Claims Department

Vehicle No: YP4012J

78 Shenton Way #07-16

Model/Make: Mitsubishi

AIG Building

Singapore 079120

Canter FEB21ER4SDEB (CBU)

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Sidegate <i>NS</i>	\$2,840.00	
2	Wheel Fender <i>NS</i>	\$ 694.00	
3	"Corporate" Advertisement & Artwork <i>NS</i>	\$ 200.00	
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 400.00	300
	To putty & spray painting & including touch up paint on accident affected area	\$ 600.00	380
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 50.00	30

Total Parts & Labour of estimate for damaged vehicle

\$4,784.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

*not Authorised**L/S 2700
3 days.**12/3/20
take photo After Repair*

*P-3328
257
P-209378
S.N-200.00
L-700.00
36038
202
2773*

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: