



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

INV No. AC2003617
INV Date 04/05/2020
Reference CS/SMO20003913/Bqf3n2
Code SMO



PROFESSIONAL SERVICE FEE

Vehicle No. SGH 7712H
Insured Veh. FBP 929M
Claim No. CMTD2001103/AGC
Policy No.
Accident Date 11/03/2020
Inspection Date 12/03/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20003913/Bqf3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 04-05-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBP 929M	Veh. Inspected	SGH 7712H
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2001103/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	12/03/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JHMFD16206S208287	Colour	WHITE
Odometer	116885	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 ZR16	MICHELIN	5 mm
L/H Front Tyre	205/55 ZR16	MICHELIN	5 mm
R/H Rear Tyre	205/55 ZR16	MICHELIN	5 mm
L/H Rear Tyre	205/55 ZR16	MICHELIN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/03/2020	Inspection Date	12/03/2020
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGH 7712H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID	TO REPAIR SEE LABOUR	736.70	-
1	BOOTLID LOGO	NECESSARY	155.00	42.80
1	BOOTLID EMBLEM "CIVIC"	NECESSARY	132.00	52.20
1	BOOTLID EMBLEM "1.8"	NECESSARY	156.00	52.20
1	BOOTLID EMBLEM "I-VTEC"	NECESSARY	173.00	54.30
1	BOOTLID INNER LOCK	NOT DAMAGED	181.70	-
1	BOOTLID LOCK STRICKER	NOT DAMAGED	55.00	-
1	BOOTLID HINGE	NOT DAMAGED	155.00	-
1	BOOTLID INNER TRIM BOARD	NO SUCH PARTS	197.70	-
1	BOOTLID WEATHERSTRIP	NOT DAMAGED	285.00	-
1	BOOTLID LAMP RH	BROKEN	285.00	195.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	583.90	-
1	REAR AIR VENTS RH	NOT DAMAGED	45.60	-
1	REAR BUMPER	CUT	758.00	638.00
2	REAR BUMPER SIDE RETAINER @\$85.60	NECESSARY	171.20	88.20
2	REAR BUMPER BRACKET @\$68.80	BENT (1 PC ONLY)	137.60	27.80
1	REAR FENDER INNER TRIM BOARD RH	NOT DAMAGED	258.00	-
1	TAILLAMP RH	BROKEN	485.60	299.60
1	TAILLAMP LOWER BRACKET RH	NOT NECESSARY	149.50	-
1	TAILLAMP BASE PANEL RH	NOT NECESSARY	184.30	-
1	EXHAUST PIPE	NOT DAMAGED	881.40	-
1	EXHAUST PIPE MOUNTING	NOT DAMAGED	58.00	-
	LESS 20% DISCOUNT		-1,245.04	-290.02
			4,980.16	1,160.08
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NOT NECESSARY	80.00	-
1	BOOTLID SEALANT (SN)	NECESSARY	80.00	30.00
1	BOOTLID LAMP SEAL (SN)	NOT NECESSARY	50.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	80.00	-

Report Ref No. CS/SMO20003913/Bqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOTLID INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	TAILLAMP SEAL (SN)	NOT NECESSARY	50.00	-
1	TAILLAMP BASE PANEL (SN)	NOT NECESSARY	60.00	-
2	REVERSE SENSOR WITH CONTROL MODULE @\$200.00 (SN)	DISLODGE	400.00	200.00
1	REAR FENDER INNER TRIM BOARD (SN)	NOT NECESSARY	50.00	-
			950.00	260.00
	LABOUR			
	R&R REVERSE SENSOR.		80.00	60.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF BOOTLID AND REAR END PANEL.		1,000.00	600.00
	R&R BOOTLID COMPONENT.		150.00	50.00
	R&R EXHAUST PIPE.	NOT NECESSARY	150.00	-
	CHECK WIRING.		60.00	30.00
	R&R UPHOLSTERY.	NOT NECESSARY	80.00	-
	RUST PROOFING.		100.00	30.00
	SPRAY PAINTING.		1,000.00	600.00
			2,620.00	1,370.00
GRAND TOTAL			8,550.16	2,790.08
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,200.00

Report Ref No. CS/SMO20003913/Bqf3n2

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGH 7712H

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGH 7712H

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

