

Merimen

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: **\$500**
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **\$143K**
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **07/8/20** days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SKC8777T** Yr Regn: **2017 / June**
 Type: **M.Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Audi Q5** c.c. **1984**
 Colour: **Grey** A/C: **Insured / Std / NI / NA**
 Sp. Reading: **32827** T/Radio: **Insured / Std / NI / NA**
 Eng/No: _____
 C/No: **WAUZZZFySH2024581**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **Inorder** / Jammed / Leaked / Burnt or
 Brake: **Inorder** / Jammed / Leaked / Burnt or
 Modi: **Nil** / S/Rim / STD A/Rim or
 Tyre Size: F: **235/55R19**
 R: **235/55R19**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / **PIR** / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. **26** mm R/Bal. **26** mm
 L/Bal. **96** mm L/Bal. **06** mm
 D.O.A. _____ D.O.I. **12/03/20**
 Survey held at **Premium**
 Des. of Damages: **Frt** / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	ODAIG
	SKC8777T-CE3/A1917019849/Ahb392
13/3	Pending Estimate
	13/3 Revert Via Merimen
	MV: 26/3 Supp Approval + 3 day
	PV: 17/8 Confirm final Fig \$14533-84
	Nett: Sent by email (Red \$18453-16, 55%)
16/3	Approval Mandate by Victor
16/3	Sent email to Workshop Authorise

Date/Time, File Pass to? ☐ : Prel. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) **24/8/20 Typist**

Report Format :

Lump Sum / LBJ: **PIP \$14533-84**

Days Of Repair: **7**

Resurvey No. of Trip: **3**

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

3 + RS \$

Photos

Others

TOTAL

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lim, Sheng Yang

Date: 25 Mar 2020

Preliminary Advice

Vehicle No	: SKC8777T	Accident Date	: 12/03/2020
Make	: AUDI Q5 SPORT	Policy No.	: 2100510229
Assignment Date	: 13/03/2020	Excess	: S\$500.00
Date of Inspection	: 12/03/2020	Est. Duration of Repair	: 7.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	30,987.00 (Includ supp \$4,018.00)
Revised Amount	:S\$	14,186.00 (Includ supp \$4,018.00)
Check Items (Estimated)	:S\$	2,193.00
Total	:S\$	16,379.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	143,000.00
COE / PARF Rebate	:S\$	79,157.00
Salvage Value	:S\$	
Margin for Repair	:S\$	63,843.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gan, Hunchung

Date: 13 Mar 2020

Preliminary Advice

Vehicle No	: SKC8777T	Accident Date	: 12/03/2020
Make	: AUDI Q5 SPORT	Policy No.	: 2100510229
Assignment Date	: 13/03/2020	Excess	: S\$0.00
Date of Inspection	: 12/03/2020	Est. Duration of Repair	: 4.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	26,969.00
Revised Amount	:S\$	10,168.00
Check Items (Estimated)	:S\$	2,193.00
Total	:S\$	12,361.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	143,000.00
COE / PARF Rebate	:S\$	79,157.00
Salvage Value	:S\$	
Margin for Repair	:S\$	63,843.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Monday, March 16, 2020 5:45 PM
To: Claims; SUR
Subject: RE: OD CLAIM FOR SKC 8777 T ON 12/3/2020

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKC8777T (excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne.wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Thursday, March 12, 2020 5:54 PM
To: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: OD CLAIM FOR SKC 8777 T ON 12/3/2020

Dear All,

Kindly register OD claim for this vehicle. Attached is the GIA report, DL and CI for your reference.

We will forward you the estimate once it is available.

Survey has been carried out by Adrian.

Best Regards,
Syafiq
Claims Admin Assistant

View Received Message

This mail is associated with :

***SKC8777T (4655100244SG)**

OD

Mar 12 2020 9:00AM

[DANIEL THAM CHEE MENG]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 26/03/2020 14:30 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$14186.00) - SKC8777T - Claim Handler: Lim, Sheng Yang

Approved:14186.00:Supplementary and additional 3 working days - ok. Re-inspection to be done for damage check and supplementary items / labour with clear photos.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SKC8777T (4655100244SG)**

OD

Mar 12 2020 9:00AM

[DANIEL THAM CHEE MENG]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 16/03/2020 14:52 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$10168.00) - SKC8777T - Claim Handler: Gan, Hunchung

Approved:10168.00:Authorise repair. Re-inspection to be done for damage check and supplementary items / labour with clear photos.

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/03/2020 15:01
Date Of Accident	12/03/2020 09:30
Exact Location Of Accident	SLIP ROAD FROM JALAN EUNOS TO PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC8777T
Insured/Policyholder	
Name Of Registered Owner	DANIEL THAM CHEE MENG
NRIC No	SXXXX143G
Email Address	DANTCM@YAHOO.COM
Mobile Phone No	(LOCAL) +65-98170628
Alternative Phone No	OFFICE-98170628

Vehicle Particulars

Manufacturer	AUDI
Model	AT Q5 SPORT 2.0 TFSI QU
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100510229-02
Cover Note Number	

Driver

Name of Driver	DANIEL THAM CHEE MENG
NRIC No	SXXXX143G
Date Of Birth	06/09/1970
Occupation	INDOOR
Date Of Driving Pass	18/06/1998
Driving Experience	21 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98170628
Fax Number	
Contact Number	OFFICE-98170628
E-Mail Address	DANTCM@YAHOO.COM

Address	126 KOON SENG ROAD #05-02
Postcode	427059
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AT ABOUT 0930HRS, TURNING FROM SLIP ROAD TO PIE AT JALAN EUNOS, HIT VEHICLE IN FRONT SLS 5247 E (HONDA CIVIC CHAMPAGNE COLOUR) WITH OWN CAR SKC 8777 T. NO INJURY TO THEIR CAR DRIVER AND PASSENGER, CONFIRM BY ASKING BOTH OF THEM

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS5247E
Vehicle Make/Model/Colour	HONDA CIVIC(CHAMPAGNE)
Details Of Properties	GRAB CAR
Vehicle Category	PRIVATE HIRE
Name of Driver	FRANCIS
NRIC/Passport Number	
Contact Number	98562993
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 12/3/20

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:


NRIC/FIN No.:



Tony Fong
6224882

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AT about 0930hrs, turning from Slip Road
to PIE at JALAN ENOUS, Hit vehicle in front
SLS 5247E (Honda Civic - champagne color)
with own car 3KC 8777T. No injury to
other car driver and passenger, confirm by asking
both of them.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time: 12/3/20

Copyright © 2002 by John Wiley & Sons, Inc.

Driver's Signature _____

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name: _____

NRIC/FIN No.:

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S7031143G**
Name
DANIEL THAM CHEE MENG

Birth Date **06 Sep 1970**
Issue Date **27 Dec 2011**

D02030130J



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 3 Motor Cars \leq 3000kg with \leq 7 passengers, exclusive of the driver; and other motor vehicles \leq 2500kg	18 Jun 1998

NP 428A

Licence No: S7031143G



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : DANIEL THAM CHEE MENG
Period of Insurance : 20 Jul 2019 To 19 Jun 2020
Engine No. : DZX005680
Chassis No. : WAUZZZF5H2024581

Vehicle No. : SKC8777T
Policy No. : 2100510229-02
Endorsement No. :
Issued Date : 23 May 2019

ABOUT THE COVER

Make/Model : AUDI Q5 Sport 2.0 TFSI qu
Engine Capacity/Tonnage : 1,984.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PAF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$1000 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Josephine Sugianto - \$1000 (Own Damage), DANIEL THAM CHEE MENG - \$1000 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125211

PREMIUM LEASING - NC

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSPSHA

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	143G
Vehicle Details	
Vehicle No.:	SKC8777T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	13 Mar 2020
Vehicle Make:	AUDI
Vehicle Model:	Q5 SPORT 2.0 TFSI QU S TRONIC (PSR)
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	DAX005680
Chassis No.:	WAUZZZFY5H2024581
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$46,423.00
Original Registration Date:	20 Jun 2017
First Registration Date:	20 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$56,993.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jun 2027
PARF Rebate Amount:	\$42,744.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jun 2027 ✓
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,110.00
COE Rebate Amount:	\$36,413.00
Total Rebate Amount:	\$79,157.00

The information contained herein is correct as at 13 Mar 2020

OK

O.O.A. 12/3/2020
Bal: 7 yrs 3.2m
M.V. \$143,000
28,496

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 32607

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/027/2020/NS
Date : 13-Mar-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Daniel Tham Chee Meng
Address : 126 Koon Seng Road
#05-02
Singapore 427059
Telephone : HP +65 98170628
Type of Claim : Own Damage Claim
Policy No. : 2100510229-02
Vehicle No : **SKC 8777 T**
Model Code : Audi Q5 Sport 2.0 TFSI qu
Model / Year : Jun-17
Engine No : DAX 005680
Chassis No : WAUZZZF5H2024581
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 12-Mar-20
Place of Accident : Slip Road From Jalan Eunos To PIE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKC 8777 T

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	\$480-00
2	<i>Bumper 500, Bonnet Rep's 250 Headlight Bracket 250</i> To dismantle and renew front bumper and lhs headlight. To repair bonnet. Re-organise crash management components.	\$ 2,400.00 ✓	<i>250 1000 \$100</i>
3	To respray front bumper, front bumper lower spoiler, bonnet and both front wheel arch trims.	<i>1500</i> \$ 4,000.00 ✓	<i>2x550 = 1100</i> <i>7m x 2 = 14m</i> <i>\$1500-00</i>
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	<i>\$192-00 1500</i>
TOTAL LABOUR CHARGES		: \$ 7,072.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKC 8777 T

S/N	Parts Description	Damage Parts & Prices		
		S/Nett		Remarks
1	FRONT BUMPER <i>Deformed.</i>	\$	2,445.00 ✓	\$1910-00
2	FRONT BUMPER FIXING PARTS <i>Neu</i>	\$	254.00 x	
3	FRONT BUMPER SECURING STRIP - LH <i>2 Neu</i>	\$	35.00 x	
4	FRONT BUMPER CLOSING ELEMENT - LH	\$	105.00 x	
5	FRONT BUMPER GRILLE - CENTRE <i>Deformed, Neu</i>	\$	134.00 ✓	
6	FRONT BUMPER FRONT SPOILER <i>Neu torn</i>	\$	709.00 ✓	\$567-20
7	FRONT BUMPER UNDERRUN BAR <i>Neu</i>	\$	447.00 x	
8	FRONT BUMPER CLOSING ELEMENT <i>Neu torn</i>	\$	161.00 ✓	\$128-00
9	RADIATOR GRILLE <i>crushed</i>	\$	3,327.00 ✓	\$8-00 2661-60
10	QUATTRO INSCRIPTION <i>Neu</i>	\$	90.00 ✓	\$2661-60 8-00
11	RADIATOR GRILLE STRIKER PLATE <i>crushed.</i>	\$	230.00 ?	\$71-76
12	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Deformed.</i>	\$	537.00 ?	\$183-60
13	FRONT BUMPER END CAP - LH <i>Neu</i>	\$	86.00 x	
14	FRONT BUMPER CARRIER <i>Neu</i>	\$	857.00 x	
15	FRONT BUMPER FOAM FILLER PIECE <i>crushed.</i>	\$	269.00 ✓	\$214-80
16	FOAM FILLER PIECE COVER <i>Neu</i>	\$	120.00 x	
17	FRONT BUMPER GUIDE SECTION - LH <i>Neu</i>	\$	36.00 x	
18	CAUTION SIGN STICKER <i>2</i>	NEC \$	13.00 x	
19	AIRCON STICKER <i>Neu</i>	NEC \$	18.00 x	
20	HORN - LH LOW TONE	\$	184.00 x	
SUB TOTAL SPARE PARTS CHARGES		:	\$ 10,057.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKC 8777 T

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
21	HEADLIGHT MOUNTING - LH <i>new cranked</i>	\$	112.00 ✓	\$89-20
22	LED HEADLIGHT - LH	\$	7,462.00 ✗	
23	LIFT CYLINDER - LH <i>He m</i>	\$	132.00 ✗	
24	LIFT CYLINDER HOSE	\$	118.00 ✓	
25	RADIATOR AIR GUIDE - LH <i>He m</i>	\$	53.00 ✗	
26	RADIATOR AIR GUIDE - CENTRE	\$	40.00 ✗	
27	RADIATOR AIR GUIDE - UPPER / LOWER	2 \$	90.00 +	
28	BONNET IMPACT PROTECTION - CENTRE	\$	26.00 ✗	
29	BONNET IMPACT PROTECTION - LH	\$	26.00 ✗	
30	BONNET IMPACT PROTECTION - RH <i>HSP</i>	\$	26.00 ✗	
31	BONNET RELEASE ELEMENT <i>NR</i>	\$	54.00 ✗	
32	WHEEL SPOILER - LH <i>cranked</i>	\$	151.00 ✓	\$120-40
33	FRONT WHEEL COVER - LH / RH <i>NR</i>	2 \$	1,190.00 ✓	\$952-00
34	FRONT NO PLATE <i>NR</i>	S/N \$	60.00 ✓	\$60-00
35	SUNDRIES <i>NR</i>	\$	300.00 ?	\$32-64
TOTAL SPARE PARTS CHARGES		:	\$ 19,897.00	
TOTAL LABOUR CHARGES		:	\$ 7,072.00	
GRAND TOTAL		:	\$ 26,969.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Admin Lj
Surveyed Date : 13/03/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 07 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/027/2020/NS

Date

24-Mar-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SKC 8777 T

Model No

Audi Q5 Sport 2.0 TFSI qu

Quantity Description

Unit Price Amount

Parts

1	Headlight mounting RHS <i>cm</i> ✓	\$ 112.00 ✓	\$89-20
2	Lock carrier support RHS <i>X</i>	\$ 50.00 ✓	
3	Lock carrier support LHS <i>cm</i> ✓	\$ 50.00 ✓	\$39-84
4	Lock carrier <i>cm</i> ✓	\$ 1,206.00 ✓	\$964-80

Labours

1	To remove and reinstall aircond condenser, charged air cooler and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	1400 ✓	\$1400-00
2	To renew front lock carrier and align to position.	\$	3,200.00 ✓	1250 \$1250-00

TOTAL

\$ 6,018.00

For Premium Automobiles Pte Ltd

Authorised Signature

add 3 days of repairs.

Subject to insurance approval
Bonnet dent
refer to Adrian

Paul

24/03/2020

[Signature]

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKC 8777 T

S/N Parts Description

Damage Parts & Prices
S/Nett Remarks

VSK	1	FRONT BUMPER <i>Delomed.</i>	\$	2,445.00 ✓	
	2	FRONT BUMPER FIXING PARTS <i>Neu</i>	\$	254.00 ✗	
	3	FRONT BUMPER SECURING STRIP - LH <i>Neu</i>	\$	35.00 ✗	
	4	FRONT BUMPER CLOSING ELEMENT - LH	\$	105.00 ✗	
VSK	5	FRONT BUMPER GRILLE - CENTRE <i>Delomed.</i>	\$	134.00 ✓	
	6	FRONT BUMPER FRONT SPOILER <i>Neu</i> / <i>BR</i>	\$	709.00 ✗	
	7	FRONT BUMPER UNDERRUN BAR <i>Neu</i>	\$	447.00 ✗	
	8	FRONT BUMPER CLOSING ELEMENT <i>Neu</i>	\$	161.00 ✗	
	9	RADIATOR GRILLE <i>Delomed.</i>	\$	3,327.00 ✓	
	10	QUATTRO INSCRIPTION <i>Neu</i>	\$	90.00 ✓	
VSK	11	RADIATOR GRILLE STRIKER PLATE ?	\$	230.00 ?	
	12	FRONT BUMPER AIR GUIDE GRILLE - LH ?	\$	537.00 ?	
	13	FRONT BUMPER END CAP - LH <i>Neu</i>	\$	86.00 ✗	
VSK	14	FRONT BUMPER CARRIER ?	\$	857.00 ?	
VSK	15	FRONT BUMPER FOAM FILLER PIECE ?	\$	269.00 ?	
	16	FOAM FILLER PIECE COVER <i>Neu</i>	\$	120.00 ✗	
	17	FRONT BUMPER GUIDE SECTION - LH <i>Neu</i>	\$	36.00 ✗	
	18	CAUTION SIGN STICKER ?	NEC \$	13.00 ✗	
	19	AIRCON STICKER <i>Neu</i>	NEC \$	18.00 ✗	
	20	HORN - LH LOW TONE	\$	184.00 ✗	

Steve
25/3/20

SUB TOTAL SPARE PARTS CHARGES

: \$ 10,057.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1181

Telefax

Estimated Labour Charges for Accident Vehicle. SKC 8777 T

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper and lhs headlight. To repair bonnet. Re-organise crash managment components.	\$ 2,400.00 750	
3	To respray front bumper, front bumper lower spoiler, bonnet and both front wheel arch trims.	\$ 4,000.00 1500	2 x 550 = 1100 750 x 2 = 200 x 2 = 400
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 7,072.00	1500 + 550

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/027/2020/NS 24-Mar-20 Glory Tan 1 of 1 SKC 8777 T Audi Q5 Sport 2.0 TFSI qu
Quantity	Description	Unit Price	Amount
Parts			
1	Headlight mounting RHS <i>cracked</i>	\$ 112.00	\$ 89.20 ✓
2	Lock carrier support RHS <i>Not in</i>	\$ 50.00	\$ X
3	Lock carrier support LHS <i>cracked</i>	\$ 50.00	\$ 39.84 ✓
4	Lock carrier <i>cracked</i>	\$ 1,206.00	\$ 964.80 ✓
5	Coolant <i>elec</i>	\$ 86.00	\$ 68.80 ✓
		\$ 1,504.00	\$ 1,162.64
Labours			
1	To remove and reinstall aircond condenser, charged air cooler and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas. S/N	1400	\$ 1,400.00 ✓
2	To renew front lock carrier and align to position.	\$ 3,200.00	\$ 1,250.00 ✓
3	To respray bonnet	\$ 800.00	\$ 550.00
Labour		\$ 5,400.00	\$ 3,200.00
Materials		\$ 1,504.00	\$ 1,162.64
TOTAL		\$ 6,904.00	\$ 4,362.64

Adrian Ling
[Signature]

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 32607

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/027/2020/NS
Date : 13-Mar-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

*7 days exclude 1 Sunday - ok - jb
20-Apr-20*

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Daniel Tham Chee Meng
Address : 126 Koon Seng Road
#05-02
Singapore 427059
Telephone : HP +65 98170628
Type of Claim : Own Damage Claim
Policy No. : 2100510229-02
Vehicle No : **SKC 8777 T**
Model Code : Audi Q5 Sport 2.0 TFSI qu
Model / Year : Jun-17
Engine No : DAX 005680
Chassis No : WAUZZZFY5H2024581
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 12-Mar-20
Place of Accident : Slip Road From Jalan Eunus To PIE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKC 8777 T

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00 ✓
2	To dismantle and renew front bumper and lhs headlight. To repair bonnet. Re-organise crash management components.	\$ 2,400.00	\$ 1,000.00 ✓
3	To respray front bumper, bonnet and both front wheel arch trims.	\$ 4,000.00	\$ 1,500.00 ✓
3a	Added labour charges - see attached	\$ 5,400.00	\$ 3,200.00 ✓
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 12,472.00	\$ 6,372.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKC 8777 T

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 2,445.00	\$ 1,910.00 ✓
2	FRONT BUMPER FIXING PARTS	\$ 254.00	
3	FRONT BUMPER SECURING STRIP - LH	\$ 35.00	
4	FRONT BUMPER CLOSING ELEMENT - LH	\$ 105.00	
5	FRONT BUMPER GRILLE - CENTRE	\$ 134.00	
6	FRONT BUMPER FRONT SPOILER	\$ 709.00	\$ 567.20 ✓
7	FRONT BUMPER UNDERRUN BAR	\$ 447.00	
8	FRONT BUMPER CLOSING ELEMENT	\$ 161.00	\$ 128.00 ✓
9	RADIATOR GRILLE	\$ 3,327.00	\$ 2661-60 -8.00 ✓
10	QUATTRO INSCRIPTION	\$ 90.00	\$ 8.00 2,661.00 ✓
11	RADIATOR GRILLE STRIKER PLATE	\$ 230.00	\$ 71.76 ✓
12	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 537.00	\$ 183.60 ✓
13	FRONT BUMPER END CAP - LH	\$ 86.00	
14	FRONT BUMPER CARRIER	\$ 857.00	
15	FRONT BUMPER FOAM FILLER PIECE	\$ 269.00	\$ 214.80 ✓
16	FOAM FILLER PIECE COVER	\$ 120.00	
17	FRONT BUMPER GUIDE SECTION - LH	\$ 36.00	
18	CAUTION SIGN STICKER	NEC \$ 13.00	
19	AIRCON STICKER	NEC \$ 18.00	
20	HORN - LH LOW TONE	\$ 184.00	
SUB TOTAL SPARE PARTS CHARGES		: \$ 10,057.00	\$ 5,744.96

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKC 8777 T

S/N	Parts Description	c/f	<u>Damage Parts & Prices</u>	
			S/Nett	Remarks
			\$	5,744.96
21	HEADLIGHT MOUNTING - LH		\$ 112.00	\$ 89.20 ✓
22	LED HEADLIGHT - LH		\$ 7,462.00	
23	LIFT CYLINDER - LH		\$ 132.00	
24	LIFT CYLINDER HOSE		\$ 118.00	
25	RADIATOR AIR GUIDE - LH		\$ 53.00	
26	RADIATOR AIR GUIDE - CENTRE		\$ 40.00	
27	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 90.00	
28	BONNET IMPACT PROTECTION - CENTRE		\$ 26.00	
29	BONNET IMPACT PROTECTION - LH		\$ 26.00	
30	BONNET IMPACT PROTECTION - RH		\$ 26.00	
31	BONNET RELEASE ELEMENT		\$ 54.00	
32	WHEEL SPOILER - LH		\$ 151.00	\$ 120.40 ✓
33	FRONT WHEEL COVER - LH / RH	2	\$ 1,190.00	\$ 952.00 ✓
34	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00 ✓
34a	Added parts - see attached		\$ 1,504.00	\$ 1,162.64 ✓
35	SUNDRIES		\$ 300.00	\$ 32.64 ✓
TOTAL SPARE PARTS CHARGES			: \$ 21,401.00	\$ 8,161.84
TOTAL LABOUR CHARGES			: \$ 12,472.00	\$ 6,372.00
GRAND TOTAL			: \$ 33,873.00	\$ 14,533.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/027/2020/NS 24-Mar-20 Glory Tan 1 of 1 SKC 8777 T Audi Q5 Sport 2.0 TFSI qu
Quantity	Description	Unit Price	Amount
Parts			
1	Headlight mounting RHS	\$ 112.00	\$ 89.20 ✓
2	Lock carrier support RHS	\$ 50.00	
3	Lock carrier support LHS	\$ 50.00	\$ 39.84 ✓
4	Lock carrier	\$ 1,206.00	\$ 964.80 ✓
5	Coolant	\$ 86.00	\$ 68.80 ✓
		\$ 1,504.00	\$ 1,162.64
Labours			
1	To remove and reinstall aircond condenser, charged air cooler and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N 1400	\$ 1,400.00 ✓
2	To renew front lock carrier and align to position.	\$ 3,200.00	\$ 1,250.00 ✓
3	To respray front lower spoiler.	\$ 800.00	\$ 550.00 ✓
	Labour	\$ 5,400.00	\$ 3,200.00
	Materials	\$ 1,504.00	\$ 1,162.64
	TOTAL	\$ 6,904.00	\$ 4,362.64

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant