

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 32607

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/027/2020/NS
Date	:	13-Mar-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Daniel Tham Chee Meng
Address	:	126 Koon Seng Road #05-02 Singapore 427059
Telephone	:	HP +65 98170628
Type of Claim	:	Own Damage Claim
Policy No.	:	2100510229-02
Vehicle No	:	SKC 8777 T
Model Code	:	Audi Q5 Sport 2.0 TFSI qu
Model / Year	:	Jun-17
Engine No	:	DAX 005680
Chassis No	:	WAUZZZF5H2024581
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	12-Mar-20
Place of Accident	:	Slip Road From Jalan Eunos To PIE

my

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKC 8777 T

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	\$480-00
2	Bumper 500, Bonnet Rep's 250 Headlight Bracket 250 To dismantle and renew front bumper and lhs headlight. To repair bonnet. Re-organise crash management components.	\$ 2,400.00 ✓ 1500	2500 - 1000 = 1500 \$1000
3	To respray front bumper, front bumper lower spoiler, bonnet and both front wheel arch trims.	\$ 4,000.00 ✓ 1500	2 x 550 = 1100 7m x 2 = 200 x 2 = 400 \$1500-00
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	\$192-00 1500.
TOTAL LABOUR CHARGES		: <u>\$ 7,072.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKC 8777 T

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER <i>Deformed.</i>	\$	2,445.00 ✓	<i>\$1910-00</i>
2	FRONT BUMPER FIXING PARTS <i>Neu</i>	\$	254.00 x	
3	FRONT BUMPER SECURING STRIP - LH <i>2 Neu</i>	\$	35.00 x	
4	FRONT BUMPER CLOSING ELEMENT - LH	\$	105.00 x	
5	FRONT BUMPER GRILLE - CENTRE <i>Deformed Neu</i>	\$	134.00 ✓	
• 6	FRONT BUMPER FRONT SPOILER <i>Neu torn</i>	\$	709.00 ✓	<i>\$567-20</i>
7	FRONT BUMPER UNDERRUN BAR <i>Neu</i>	\$	447.00 x	
• 8	FRONT BUMPER CLOSING ELEMENT <i>Neu torn</i>	\$	161.00 ✓	<i>\$128-00</i>
9	RADIATOR GRILLE <i>encl d</i>	\$	3,327.00 ✓	<i>\$8-00 2661-60</i>
10	QUATTRO INSCRIPTION <i>Neu</i>	\$	90.00 ✓	<i>\$2661-60 8-00</i>
• 11	RADIATOR GRILLE STRIKER PLATE <i>encl d.</i>	\$	230.00 ?	<i>\$71-76</i>
• 12	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Deformed.</i>	\$	537.00 ?	<i>\$183-60</i>
13	FRONT BUMPER END CAP - LH <i>Neu</i>	\$	86.00 +	
14	FRONT BUMPER CARRIER <i>Neu</i>	\$	857.00 ✓	
• 15	FRONT BUMPER FOAM FILLER PIECE <i>encl d.</i>	\$	269.00 ✓	<i>\$214-80</i>
16	FOAM FILLER PIECE COVER <i>Neu</i>	\$	120.00 x	
17	FRONT BUMPER GUIDE SECTION - LH <i>Neu</i>	\$	36.00 x	
18	CAUTION SIGN STICKER <i>2</i>	NEC \$	13.00 +	
19	AIRCON STICKER <i>2 Neu</i>	NEC \$	18.00 x	
20	HORN - LH LOW TONE	\$	184.00 x	
SUB TOTAL SPARE PARTS CHARGES		:	<u>\$ 10,057.00</u>	

premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKC 8777 T

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
• 21	HEADLIGHT MOUNTING - LH <i>non could</i>	\$	112.00 ✓	\$89-20
22	LED HEADLIGHT - LH	\$	7,462.00 ✗	
23	LIFT CYLINDER - LH <i>Mem</i>	\$	132.00 ✗	
24	LIFT CYLINDER HOSE	\$	118.00 ✓	
25	RADIATOR AIR GUIDE - LH <i>Mem</i>	\$	53.00 ✗	
26	RADIATOR AIR GUIDE - CENTRE	\$	40.00 ✗	
27	RADIATOR AIR GUIDE - UPPER / LOWER	2 \$	90.00 ✗	
28	BONNET IMPACT PROTECTION - CENTRE	\$	26.00 ✗	
29	BONNET IMPACT PROTECTION - LH	\$	26.00 ✗	
30	BONNET IMPACT PROTECTION - RH	\$	26.00 ✗	
31	BONNET RELEASE ELEMENT	\$	54.00 ✗	
• 32	WHEEL SPOILER - LH <i>could</i>	\$	151.00 ✓	\$120-40
33	FRONT WHEEL COVER - LH / RH <i>Nec</i>	2 \$	1,190.00 ✓	\$952-00
34	FRONT NO PLATE <i>Nec</i>	S/N \$	60.00 ✓	\$60-00
35	SUNDRIES <i>Nec</i>	\$	300.00 ✓	\$32-64
TOTAL SPARE PARTS CHARGES		:	\$ 19,897.00	
TOTAL LABOUR CHARGES		:	\$ 7,072.00	
GRAND TOTAL		:	\$ 26,969.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 13/03/20
Authorised Date :
Excess Cost : P.S.
Liability : 07 Days
Remarks : Not Authorised, 08 Days.

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/027/2020/NS 24-Mar-20 Glory Tan 1 of 1 SKC 8777 T Audi Q5 Sport 2.0 TFSI qu
Quantity	Description	Unit Price	Amount
Parts			
1	Headlight mounting RHS <i>cracked</i>	\$ 112.00	\$ 89.20 ✓
2	Lock carrier support RHS <i>NE new</i>	\$ 50.00	\$ 39.84 ✓
3	Lock carrier support LHS <i>cracked</i>	\$ 50.00	\$ 39.84 ✓
4	Lock carrier <i>cracked</i>	\$ 1,206.00	\$ 964.80 ✓
5	Coolant <i>xlec</i>	\$ 86.00	\$ 68.80 ✓
		\$ 1,504.00	\$ 1,162.64
Labours			
1	To remove and reinstall aircond condenser, charged air cooler and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N 1400	\$ 1,400.00 ✓
2	To renew front lock carrier and align to position.	\$ 3,200.00	\$ 1,250.00 ✓
3	To respray bonnet	\$ 800.00	\$ 550.00
Labour		\$ 5,400.00	\$ 3,200.00
Materials		\$ 1,504.00	\$ 1,162.64
TOTAL		\$ 6,904.00	\$ 4,362.64

Adrian Ling
[Signature]

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

WIP : 32607

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/027/2020/NS
Date : 13-Mar-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

*7 days exclude 1 Sunday - ok - jb
20-Apr-20*

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Daniel Tham Chee Meng
Address : 126 Koon Seng Road
#05-02
Singapore 427059
Telephone : HP +65 98170628
Type of Claim : Own Damage Claim
Policy No. : 2100510229-02
Vehicle No : **SKC 8777 T**
Model Code : Audi Q5 Sport 2.0 TFSI qu
Model / Year : Jun-17
Engine No : DAX 005680
Chassis No : WAUZZZF5H2024581
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 12-Mar-20
Place of Accident : Slip Road From Jalan Eunus To PIE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKC 8777 T

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To dismantle and renew front bumper and lhs headlight. To repair bonnet. Re-organise crash management components.	\$ 2,400.00	\$ 1,000.00
3	To respray front bumper, front bumper lower spoiler, bonnet and both front wheel arch trims.	\$ 4,000.00	\$ 1,500.00
3a	Added labour charges - see attached	\$ 5,400.00	\$ 3,200.00 ✕
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 12,472.00	\$ 6,372.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKC 8777 T

		<u>Damage Parts & Prices</u>	
S/N	Parts Description	S/Nett	Remarks
1	FRONT BUMPER	\$ 2,445.00	\$ 1,910.00
2	FRONT BUMPER FIXING PARTS	\$ 254.00	
3	FRONT BUMPER SECURING STRIP - LH	\$ 35.00	
4	FRONT BUMPER CLOSING ELEMENT - LH	\$ 105.00	
5	FRONT BUMPER GRILLE - CENTRE	\$ 134.00	
6	FRONT BUMPER FRONT SPOILER	\$ 709.00	\$ 567.20
7	FRONT BUMPER UNDERRUN BAR	\$ 447.00	
8	FRONT BUMPER CLOSING ELEMENT	\$ 161.00	\$ 128.00
9	RADIATOR GRILLE	\$ 3,327.00	\$ 2,661.60
10	QUATTRO INSCRIPTION	\$ 90.00	\$ 8 2,681.00
11	RADIATOR GRILLE STRIKER PLATE	\$ 230.00	\$ 71.76
12	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 537.00	\$ 183.60
13	FRONT BUMPER END CAP - LH	\$ 86.00	
14	FRONT BUMPER CARRIER	\$ 857.00	
15	FRONT BUMPER FOAM FILLER PIECE	\$ 269.00	\$ 214.80
16	FOAM FILLER PIECE COVER	\$ 120.00	
17	FRONT BUMPER GUIDE SECTION - LH	\$ 36.00	
18	CAUTION SIGN STICKER	NEC \$ 13.00	
19	AIRCON STICKER	NEC \$ 18.00	
20	HORN - LH LOW TONE	\$ 184.00	
SUB TOTAL SPARE PARTS CHARGES		: \$ 10,057.00	\$ 5,744.96

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKC 8777 T

		Damage Parts & Prices	
S/N	Parts Description	S/Nett	Remarks
		\$	5,744.96
21	HEADLIGHT MOUNTING - LH	\$ 112.00	\$ 89.20
22	LED HEADLIGHT - LH	\$ 7,462.00	
23	LIFT CYLINDER - LH	\$ 132.00	
24	LIFT CYLINDER HOSE	\$ 118.00	
25	RADIATOR AIR GUIDE - LH	\$ 53.00	
26	RADIATOR AIR GUIDE - CENTRE	\$ 40.00	
27	RADIATOR AIR GUIDE - UPPER / LOWER	2 \$ 90.00	
28	BONNET IMPACT PROTECTION - CENTRE	\$ 26.00	
29	BONNET IMPACT PROTECTION - LH	\$ 26.00	
30	BONNET IMPACT PROTECTION - RH	\$ 26.00	
31	BONNET RELEASE ELEMENT	\$ 54.00	
32	WHEEL SPOILER - LH	\$ 151.00	\$ 120.40
33	FRONT WHEEL COVER - LH / RH	2 \$ 1,190.00	\$ 952.00
34	FRONT NO PLATE	S/N \$ 60.00	\$ 60.00
34a	Added parts - see attached	\$ 1,504.00	\$ 1,162.64
35	SUNDRIES	\$ 300.00	\$ 32.64
TOTAL SPARE PARTS CHARGES		: \$ 21,401.00	\$ 8,161.84
TOTAL LABOUR CHARGES		: \$ 12,472.00	\$ 6,372.00
GRAND TOTAL		: \$ 33,873.00	\$ 14,533.84

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.