

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. SMN 2690 S

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assv and front parking aid.	S/N \$ 480.00	✓ ✓
2	To dismantle and renew front bumper and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ <del>1,600.00</del>	500 ✓
3	To respray front bumper, front bumper spoiler and both front wheel arch trims.	\$ <del>2,800.00</del>	1200 ✓ Bumper 550 Spoiler 280
4	To carry out diagnostic check.	S/N \$ 192.00	✓ ✓ Wheel Arc 200x25400. <u>1200</u>
<b>TOTAL LABOUR CHARGES</b>		<b>: <u>\$ 5,072.00</u></b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No SMN 2690 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <del>Revised</del> Repair	\$	2,445.00 +
2	REAR BUMPER FIXING PARTS New	\$	254.00 +
3	FRONT BUMPER SECURING STRIP - RH New	\$	35.00 +
4	FRONT BUMPER CLOSING ELEMENT - RH New	\$	105.00 x
5	FRONT BUMPER GRILLE - CENTRE New	\$	134.00 +
6	FRONT BUMPER FRONT SPOILER Repair	\$	709.00 +
7	FRONT BUMPER UNDERRUN BAR New	\$	447.00 +
8	FRONT BUMPER CLOSING ELEMENT New	\$	161.00 +
9	RADIATOR GRILLE } New	\$	3,327.00 +
10	QUATTRO INSCRIPTION } New	\$	90.00 +
11	RADIATOR GRILLE STRIKER PLATE New	\$	230.00 +
12	FRONT BUMPER AIR GUIDE GRILLE - RH Missing	\$	537.00 ✓ 429.60
13	FRONT BUMPER END CAP - RH New	\$	86.00 +
14	FRONT BUMPER CARRIER New	\$	857.00 +
15	FRONT BUMPER FOAM FILLER PIECE New	\$	269.00 +
16	FRONT BUMPER GUIDE SECTION - RH New	\$	36.00 +
17	HORN - RH HIGH TONE New	\$	184.00 +
18	FRONT PARKING AID SENSOR - INNER / OUTER New 2		TBC +
19	FRONT PARKING AID SEAL RING New	4 \$	14.00 +
20	HEADLIGHT MOUNTING - RH New	\$	112.00 +
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 10,032.00</b>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No SMN 2690 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	LED HEADLIGHT - RH <i>new</i>	\$ 7,462.00	+
22	LIFT CYLINDER - RH <i>new</i>	\$ 132.00	+
23	WHEEL SPOILER - RH <i>new</i>	\$ 146.00	+
24	FRONT WHEEL COVER - LH / RH <i>new</i>	2 \$ 1,190.00	✓ 952.00
25	RADIATOR AIR GUIDE - RH <i>new</i>	\$ 53.00	+
26	RADIATOR AIR GUIDE - CENTRE <i>new</i>	\$ 40.00	+
27	FRONT NO PLATE <i>new</i>	S/N \$ 60.00	+
28	SUNDRIES ?	\$ ✓ 300.00	21
<b>TOTAL SPARE PARTS CHARGES</b>		<b>: \$ 19,415.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 5,072.00</b>	
<b>GRAND TOTAL</b>		<b>: \$ 24,487.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian King  
Surveyed Date : 12/03/20  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised, 03 Days.

**Please Note** : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant