



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2005640
INV Date 17/08/2020
Reference CC3/EQI20003917/Qga3q2
Code EQI



PROFESSIONAL SERVICE FEE

Vehicle No. SHB 5192R
Insured Veh. SGU 2339S
Claim No. DM20HO00581/SG
Policy No. DMPPHQ19-002257
Accident Date 07/03/2020
Inspection Date 10/03/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC3/EQI20003917/Qga3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX SINGAPORE 069110

Date : 17-08-2020



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGU 2339S	Veh. Inspected	SHB 5192R
Policy No.	DMPPHQ19-002257	Coverage (\$)	0.00
Claim No.	DM20HO00581/SG	Excess (\$)	0.00
Assign From		Assign Date	10/03/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKN36U205768720	Colour	MAROON
Odometer	400333	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FIRENZA	5 mm
L/H Front Tyre	195/65 R15	FIRENZA	5 mm
R/H Rear Tyre	195/65 R15	FIRENZA	5 mm
L/H Rear Tyre	195/65 R15	FIRENZA	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/03/2020	Inspection Date	10/03/2020
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5192R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	PIXEL STICKER (SN)	NECESSARY	60.00	60.00
1	MOULDING BODY ,RH	SERVICEABLE	673.60	-
1	FENDER LINER RR/RH	SERVICEABLE	141.30	-
1	TYRE	SERVICEABLE	126.74	-
1	BUMPER REAR	SERVICEABLE	458.60	-
1	BUMPER SEAL ,RR RH	SERVICEABLE	65.70	-
1	BUMPER SIDE RETAINER RR/RH	SERVICEABLE	94.80	-
1	PIXEL STICKER	SERVICEABLE	60.00	-
1	DOOR RR/RH	TO REPAIR SEE LABOUR	954.50	-
1	FENDER RR/RH	TO REPAIR SEE LABOUR	766.80	-
1	WHEEL DISC	TO REPAIR SEE LABOUR	1,490.20	-
1	ADVERTISEMENT STICKER (SN)	NECESSARY	593.76	296.88
			5,515.40	386.28
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF DOOR RR/RH,FENDER RR/RH AND WHEEL DISC .		507.00	300.00
	SPRAY PAINT.		1,494.00	450.00
	TO CHECK WIRING AND SYSTEM FUNCTION .	NOT NECESSARY	80.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
	TO DO WHEEL ALIGNMENT /TYRE BALANCING		120.00	20.00
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).		120.00	20.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM .	NOT NECESSARY	60.00	-
			2,581.00	790.00
	GRAND TOTAL		8,096.40	1,176.28

Report Ref No. CC3/EQI20003917/Qga3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,150.00
---	--	--	----------

Report Ref No. CC3/EQI20003917/Qga3q2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 5192R

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 5192R

RE-INSPECTION

