

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Mar 2020 Edit Reg		11 Mar 2020 00:00 Edit Adj Rpt	S\$1,789.51 Edit Estimates	S\$1,789.51 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: KOH GEK KIEW , ID: S1257585H, Tel: +6599999999									
Main Claimant: SMRT TAXIS PTE LTD									
Vehicle Reg. No.: SHF330X		Date of Loss: 10/03/2020 13:00 - :59 [26 Months and 25 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 8268005879SG		Policy/Cover Note No.: 1900164692 (Comprehensive)							
Vehicle Reg. No. (Insured): SCH3223B		Policy No. (Claimant): D-19093197MFSH							
		Excess:							
Repairer: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah]									
Claimant's Insurer: MS First Capital Insurance Ltd (HQ) - Tel: 62222311									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by OI SUN PIN] ... [Final Rpt due 23/03/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (12/08/2020): Alert - Adj Mandate Approved (S\$2334.32) - SHF330X - Claim Handler: MdNoor, Nors... - AIG_SG (13/03/2020): No Policy Found									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHF330X (8268005879SG)
[SCH3223B]
TP
SMRT TAXIS PTE LTD
Mar 10 2020 1:55PM
[KOH GEK KIEW]
SMRT Automotive Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View View in Browser ▼

Letters/Correspondences

1 per page ▼
✓

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit	

Photos/Images

3 per page ▼
✓

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/03/20 09:22	Chassis Number		Load JPG	✓
2	20/03/20 09:22	Odometer Reading		Load JPG	✓
3	20/03/20 09:22	General View		Load JPG	✓
4	20/03/20 09:22	General View		Load JPG	✓
5	20/03/20 09:22	General View		Load JPG	✓
6	20/03/20 09:22	General View		Load JPG	✓
7	20/03/20 09:22	General View		Load JPG	✓
8	20/03/20 09:22	General View		Load JPG	✓
9	20/03/20 09:22	General View		Load JPG	✓
10	20/03/20 09:22	General View		Load JPG	✓
11	20/03/20 09:22	General View		Load JPG	✓
12	20/03/20 09:22	General View		Load JPG	✓
13	20/03/20 09:22	General View		Load JPG	✓
14	20/03/20 09:22	General View		Load JPG	✓
15	20/03/20 09:22	General View		Load JPG	✓
16	20/03/20 09:22	General View		Load JPG	✓
17	20/03/20 09:22	General View		Load JPG	✓
18	20/03/20 09:22	General View		Load JPG	✓
19	20/03/20 09:22	General View		Load JPG	✓
20	20/04/20 23:36	After Repair Photo		Load JPG	✓
21	20/04/20 23:36	After Repair Photo		Load JPG	✓
22	20/04/20 23:36	After Repair Photo		Load JPG	✓

Documentation

1 per page ▼
✓

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/03/20 15:58	TP ESTIMATE - MARKED		Load PDF	
2	12/03/20 15:58	TP GIA REPORT		Load PDF	
3	19/03/20 14:24	LETTER TO OI		Load PDF	
4	04/06/20 17:30	LOD		Load PDF	
5	22/06/20 12:33	3YEARS NOA		Load PDF	
6	20/08/20 14:54	Authorisation to Act		Load PDF	
7	20/08/20 14:54	INCOME TAX		Load PDF	
8	20/08/20 14:54	LTA SEARCH		Load PDF	
9	20/08/20 14:54	Release Voucher		Load PDF	
10	20/08/20 14:54	RENTAL MILEAGE		Load PDF	
11	20/08/20 14:54	RENTAL RECEIPT		Load PDF	
12	20/08/20 14:54	WORKSHOP INVOICE		Load PDF	

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	16/03/20 14:25	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SCH3223B (Insd veh)	Model:	TOYOTA PRIUS HYBRID 1.8
	SHF330X (TP veh)		CVT (A)
Date of Accident:	10/03/2020		

Global Sum Settlement	:	☒ [X] Yes	☐ [] No	
Repair Estimate	:	\$		13,898.04
Final Repair Cost	:	\$		2,330.00
Loss of Use	:	\$		3.00 days at \$67.99 per day
Rental (if any)	:	\$		3 days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (GLOBAL SUM)	:	\$		2,330.00

Is Third Party Workshop GIA Registered?				[] YES [X] NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability			_____100_____ (%)
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No			BOLA Scenario No: _____
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)			
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>					
Remarks _____					

Payment Instruction: Payee's Breakdown			
1)	SMRT TAXIS PTE LTD	: \$	2,330.00
2)		: \$	
3)		: \$	
4)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

20 Aug
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20003918/QEA3S2**Date:** 20/08/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900164692
Claimant Vehicle No :	SHF330X	Insured Vehicle No :	SCH3223B
Date of Loss:	10/03/2020	Nature of Claim:	TP
		Claim No:	8268005879SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHF330X		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Engine No:	2ZR8259485
Reg. Date:	14/12/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU303576548
Colour:	Maroon	Odometer:	144408 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,599.04	799.51	9,799.53	92.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,299.00	990.00	2,309.00	69.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	13,898.04	1,789.51	12,108.53	87.12
+ Loss of Use (3.0 x S\$67.99/day) (S\$)		203.97		
+ Car Rental (3.0 x S\$111.28/day) (S\$)		333.84		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		2,334.32		
Global Sum Settlement (S\$)		2,330.00		

INSPECTION

Date of Assignment:	11/03/2020	
Date Inspected:	11/03/2020	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	3.0 days	

Adjuster: OI SUN PIN**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER SUB-ASSY, FR, RH (DISC 25%)	Dented	933.10 F	*699.83 F
2	1		*EMBLEM, SIDE PANEL (HYBRID) (DISC 25%)	Necessary	52.90 F	*39.68 F
3	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
4	10		*CLIPS PIECE, FRT & RR BUMPER	Serviceable	15.00 F	*- F
5	1		*LAMP ASSY, FOG, RH	Serviceable	910.20 F	*- F
6	1		*SUPPORT, FR BUMPER RH	Serviceable	76.90 F	*- F
7	1		*UNIT HEADLAMP, RH	Serviceable	2,558.90 F	*- F
8	1		*LINER, FR FENDER, RH	Serviceable	198.40 F	*- F
9	1		*TYRE	Serviceable	126.74 F	*- F
10	1		*WHEEL, DISC FRONT	Serviceable	1,555.10 F	*- F
11	1		*MOULDING ASSY, BODY ROCKER PANEL, RH	Serviceable	576.00 F	*- F
12	1		*HINGE ASSY, FRONT DOOR, LOWER RH	Serviceable	92.10 F	*- F
13	1		*HINGE ASSY, FRONT DOOR, UPPER RH	Serviceable	82.10 F	*- F
14	1		*CHECK ASSY, FRONT DOOR	Serviceable	153.50 F	*- F
15	1		*MIRROR ASSY, OUTER REAR VIEW, RH	Serviceable	1,373.50 F	*- F
16	1		*COVER, OUTER MIRROR, RH	Serviceable	89.50 F	*- F
17	1		*COVER, FR BUMPER	Repair	495.50 F	*- F
18	1		*PANEL SUB-ASSY, FRONT DOOR RH	Repair	1,249.60 F	-
F=Franchise part.						
					Total Parts (S\$)	10,599.04 799.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK.	New	845.00	300.00
2	SPRAY PAINT.	New	1,674.00	650.00
3	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	0.00
4	TO APPLY RUST-PROOFING AFFECTED AREA.	New	100.00	0.00
5	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	New	120.00	20.00
6	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	20.00
7	TO REMOVE AND REFIT WIRE HARDESS.	New	200.00	0.00
8	TO REPLACE SUNDRY PARTS.	New	100.00	0.00
9	TO WASH AND VACUUM.	New	60.00	0.00
Gross Labour Cost (S\$)			3,299.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >