

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 9 Mar 2020

ASSESSMENT FOR REPAIR: HONDA NM4-02 ABS - FBJ8060Y

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front fender	\$495.00 / SCR
1 pc	• Bracket comp front fender	/ BT \$165.00 ?
1 pc	• Front wheel axle	\$214.00 / XSVK
1 pc	• Front left fork assy	\$1,050.00 / XPR
1 pc	• Front brake disk	\$440.00 / XSVK
1 pc	• Steering stem bearings @ \$45.00	\$90.00 / XSVK
1 pc	• Front fork steering stem	\$490.00 / XSVK
1 pc	Left side mirror assy	\$650.00 / BT
1 pc	• Left side fairing inner bracket	\$245.00 / BT
1 pc	Left side fairing assy	\$495.00 / CLK
1 pc	Left middle fairing gloss black	\$345.00 / CLK
1 pc	• Centre lower cover assy	\$345.00 / CLK
1 pc	• Centre upper cover assembly	\$325.00 / CLK
1 pc	• Steering handle	\$250.00 / BT
1 pc	• Brake lever	SR \$115.00 / XNL BT
1 pc	Right handle balancer	\$65.00 / XNL SCR
1 pc	Rear brake pedal comp	\$245.00 / XNL SCR
1 pc	Left front footrest	\$385.00 / DEF
1 pc	• Left front footrest bracket holder	\$375.00 / DEF
1 pc	Right front footrest	\$385.00 / XNL SCR
1 pc	Right front footrest bracket holder	\$375.00 / XNL SCR
1 pc	Left rear footrest side cover	\$335.00 / DEF
1 pc	Side stand	\$295.00 / SUR
1 pc	Left side case assembly	\$1,595.00 / DEF
1 pc	Exhaust assy	\$1,750.00 / XNL SCR
		\$11,519.00
	Less discount 10%	\$1,151.90
		\$10,367.10
	<u>Special nett items</u>	
1 pc	Front sport rim	\$880.00 / XNL / SCR
1 pc	Rear number plate	\$30.00 / BT
1)	• Towing charges	\$150.00 X
	Replace, realign and adjust above	
	damaged parts, check wiring and	
	lighting system	\$800.00 450 600
2)		
	Sport rim repair	\$280 \$150

- 3) To replace and balance front wheel rim
 - 4) To knock, straighten chassis & body balancing
 - 5) To remove/refit, replace (if damage) check and straighten front fork tubes.
 - 6) Decals — request no decal. change to spray painting. same amount.
- Total Estimate**

\$150.00 ~~X 100~~ 50.
 \$380.00 ~~X NN~~
 \$180.00 ~~mod ?~~
 \$700.00 ~~370~~ 150

\$13,637.10
 13,837.10

Note: The above estimate is subjected to the prevailing GST of 7%

18/3/2020
 WAZ LKK
 12/3/2020 1400
 L/S
 4 days

For Bike Production Pte Ltd



17,897.20

CHECK ITEM PHOTOS
 AFTER REPAIR PHOTOS

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

