

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chan, Yoke Shi

Date: 11 Aug 2020

## **Preliminary Advice**

Vehicle No	: FBJ8060Y	Accident Date	: 04/02/2020
Make	: HONDA NM4-02 A	Policy No.	: 1900084777
Assignment Date	: 12/03/2020	Excess	: S\$750.00
Date of Inspection	: 12/03/2020	Est. Duration of Repair	: 4
Inspection At	: BIKE PRODUCTION PTE LTD (HQ) 610 SERANGOON ROAD SINGAPORE 218216		

### **Point of Impact / General Description of Damages**

Parts claimed are not consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,870.70 INCLUSIVE OF SUPPLEMENTARY
Revised Amount	:S\$	12,271.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	12,271.60
Lump Sum Repair	:S\$	9500.00

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	13,000.00
COE / PARF Rebate	:S\$	2,196.00
Salvage Value	:S\$	
Margin for Repair	:S\$	10,804.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :