



新福德車廠私人有限公司

AG  
CKK ADRIAN

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

KHEW KIM MEI

12-03-2020

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

TP AIG

VIL

Accident date: 03-03-2019

Estimated repair cost for vehicle no: SLH9529Z BMW 216 D 1.5 A '16

CHASSIS: WBA2B32070V791421

S/n	Qty	Items	U/price	Amount
1	1	Front Bumper <i>Defamed</i>		\$1,045.00 ✓
2	10	Front Bumper Clip <i>Nec</i>	\$8.00	<del>\$80.00</del> 30
3	1	Front Bumper Number Plate <i>3 NP</i>		\$50.00 X
4	1	Front Bumper Lower Grille <i>3 nec</i>		\$225.00 X.
5	1	Front Bumper Inner Foam <i>included.</i>		\$110.00 ✓
6	1	Front Bumper Reinforcement <i>Nec Nec</i>		\$530.00 X
7	2	Front Bumper Sensor <i>Nec Nec</i>	\$268.00	\$536.00 X
9	1	Front L/H Bumper Side Retainer <i>Nec Nec</i>		\$28.00 X
10	1	Front L/H Bumper Fog Lamp <i>included.</i>		\$286.00 ✓
11	1	Front L/H Bumper Fog Lamp Cover <i>Defamed</i>		\$380.00 128
12	1	Front L/H Grille <i>3 NP</i>		\$180.00 +
13	6	Front L/H Grille Clip <i>3 nec</i>	\$8.00	\$48.00 +
14	1	Front L/H Head Lamp <i>included.</i>		\$2,590.00 ✓
15	1	Front L/H Head Lamp Lower Bracket <i>Nec Nec</i>		\$355.00 X
16	1	Front L/H Fender <i>3 NP</i>		\$580.00 X
17	1	Front L/H Fender Cowling <i>3 nec</i>		\$190.00 X

Subtotal :- \$7,213.00

4189

3979.55

Labour charges

To remove & refit front sensor		<del>\$120.00</del> 50
To check wiring		<del>\$80.00</del> 30
Tuff kote	780	\$150.00 X
Panel beating		<del>\$800.00</del> 300
Spray painting		<del>\$800.00</del> 250
To detach bumper spoiler	<del>250</del> 150	

Subtotal :- \$1,950.00

Total:- \$9,163.00

total = 4759.55

1/S: 38K.

03Days

3.81c

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: