

320 UBI ROAD 3 SINGAPORE 408649

	ACCIDENT RE	PAIR ESTIMATES	
Our Ref:			
Type of Claim :	ГР	Vehicle No.	SLV9429E
		Make & Model	VOLKSWAGEN TIGUAN
		Year of Manufacture	2014
		Chassis No.	WVGZZZ5NZFW053419
Ins Company :		Engine No.	CCZ470803
Excess :		Policy No.	
Date of Accident :19/0	1/2020	Time of Accident	08.35
Suggested Days of Repair :		In-house Vehicle Asse	essor
Repair Estimates		Case Owner	
Parts (a) Cost / List Price Items	\$ 3,546.00	Signature	
		Contact No	
	\$ 354.60	68485725 - JOHARI	
Total of Cost / List	\$ 3,191.40		
(b) Nett Price Items	\$ -		
Less			
Total of Nett Item			
(c) Special Nett Items	\$		
Total Parts Cost (Appendix A)	\$ 3,191.40		
Labour (Appendix B)	\$ 1,400.00		
Total Repair Cost	\$ 4,591.40		
The above total will be subjected to	7% G.S.T.		
Name of Surveyor	:-		

Name of Surveyor	: <u></u>		
Company			
Survey conducted on	:	at	
Remarks By Surveyor			
(a) The repair of this vehicle is	authorized / is not authorized	ed until further notice.	
(a) The repair of this vehicle is (b) Recommended Days of Re		ed until further noticeday(s)	
		day(s)	
(b) Recommended Days of Re	epair :	day(s)	

Spark Car Care

ComfortDelGro Engineering Pte Ltd 320 UBI ROAD 3 SINGAPORE 408649 TEL:68438723/68438736 Fax:67436072

Spare Parts

Vehicle No	:	SLV9429E	Case Owner		JOHARI - UBI	
Make & Model	:	VOLKSWAGEN TIGUAN	Year Manufac	cture	2014	
Chassis No	:	WVGZZZ5NZFW053419	Engine No		CCZ470803	
HV	:		Supplier			
Order By	:		Type of Clain	n	: <u>TP</u>	

S/No	Part Description	QTY	Cos Pric			List Price	Nett Price	S/N	Disposition By Surveyor
1	LHF BUMPER ARCH	1	FIIC		\$		Ser-	Ont	Curveyer
2	LHF FENDER ARCH	1			\$	1,776.00			
3	LHF FENDER	1			\$	1,176.00	×(R)		
4	SPORT RIM ORIGINAL	1		-	Φ	1,170.00			
				-	-		SCY		
5	TYRE (255 /40R19)	1		-	_		XW		
6		-		-					
7				-	_				
8				-	_				
9					_				
10					_				
11									
12									
13									
14									
15	LKK Auto Consultants hence	notify		1					
16	the Repairer of the following:	noury							
17	 To resurvey before/after spray pair 	ting							
18	To display damaged part(s) during Parts prices are subject to confirm	resurve	У						
19	Third party survey is on a "Without		re" hasis						
20	No illegal modification(s) is allowe		00010						
21	 Supplementary item(s) must be re is subject to final approval from Ins 	urveye	and	+					
22	is subject to final approval from ins	urance	Company		_				
23	Acknowledged by Repairer				_				
24	Signature:				_				
	Date:			-	_				
25				-	_				
26				-	_				
27									
28									
29									
30									

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care ComfortDelGro Engineering Pte Ltd

ComfortDelGro Engineering Pte Ltd 320 UBI ROAD 3 SINGAPORE 408649 Tel: 68438723/68438736 FAX: 67436072

	_	ı_	_		_
L	а	ם	o	u	r

Vehicle No. :	SLV9429E	Case Owner			
Make & Model:	VOLKSWAGEN TIGUAN	Year of Manufacture	11:	2014	

S/No	Labour Description	Esimated Price	Adjusted Price
1	To check and re-adjust wheel alignment	\$100.00	980
2	To repair front bumper , LH front door and affacted area .	\$500.00	\$400
3	To putty & spray paint front bumper , LHF fender , LHF door aaand affacted area .	\$800.00	#450
	Ram	(LXK)	30 200000000000000000000000000000000000
	23/03/7	.020	40.0
	LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting To resurvey		(LIS)
	To display damaged part(s) during resurvey Parts prices are subject to confirmation Party survey is on a "Without Prejudice" basis Third party survey is on a "Without Prejudice" basis	2015	>
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" hasis • Third party survey is on a "Without Prejudice" hasis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	4	
H	Acknowledged by Repairer		
	Signature: Date:		

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.