

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 11/03/2020

To : INDIA INTERNATIONAL INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTHCVE000175

Accident Date : 14/01/2020

Vehicle No : GBF-5171-B

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	REAR BUMPER	793.80	de ✓
2	REAR BUMPER RETAINER	57.20	?
10	REAR BUMPER CLIPS	30 50.00	rel ✓
1	REAR BUMPER REINFORCEMENT	206.40	?
1	TAILGATE	2,338.00	bb ✓
1	TAILGATE LOCK	337.50	?
1	TAILGATE WEATHERSTRIPE	137.50	ent ✓
2	TAILLAMP RH/LH	525.00	LH-x, RH-va ✓
1	END PANEL → photo	581.30	bb ✓

Date : 11/03/2020

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTHCVE000175

Accident Date : 14/01/2020

Vehicle No : GBF-5171-B

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	5026.70	
	Discount 30% On Parts	(1508.01)	
	<u>Special Nett Item</u>		
1	REVERSE SENSOR	220.00	<i>Zoom</i>
1	8 PAX - STICKER	10.00	<i>he</i>
1	70 KM/HR - STICKER	10.00	<i>he</i>
1	REAR WINDSCREEN SEALANT	50.00	<i>he</i>
1	REAR ADVERTISEMENT STICKER PANEL	350.00	<i>✓</i>

Date : 11/03/2020

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTHCVE000175

Accident Date : 14/01/2020

Vehicle No : GBF-5171-B

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	640.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILITATE REPAIR	1,100.00	6700.
	TO RESPRAY AFFECTED AREAS	800.00	700
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	120.00	✓
	TO REMOVE AND TRANSFER TAILGATE COMPONENTS	120.00	60.
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	50.00	30.
	RUST PROOFING	50.00	30.

Date : 11/03/2020

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTHCVE000175

Accident Date : 14/01/2020

Vehicle No : GBF-5171-B

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	2240.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6,398.69

Remarks:

SUB TOTAL

GST 7.0 % 447.91

TOTAL 6,846.60

Surveyor's name:

Tan Jiah 97495749

Principal's name: ETHOZ Group Ltd

Survey Date & Time:

12/3/20 @ 4:50pm

06 days.
Insurance
Resurvey after repair
Tan Jiah @ 11/03/2020