



Automobile Integrated Management Pte Ltd

Automobile Integrated Management Pte Ltd

Co. & G.S.T. Reg no. 201605297G

Office: 28 Sin Ming Lane #07-147 Midview City Singapore

573972

Workshop: 23 Kaki Bukit Ave 5 #04-01 (South Wing) Singapore

415933

Email: automim.claim@gmail.com Tel: 9119 8371

ESTIMATE

Our Ref: AC2020020/TP/SFR78777Z-10.03.2020

WDC 1569432J326893

Vehicle number: SFR8777Z

Vehicle Made & Model: MERCEDES-BENZ GLA200

Not Authorized
Main
2/5 @ 10,000/
The shop always
5 days.

Items	Qty	List Items	Amount \$
1	1	Front bumper	1,381.13 ✓
2	1	Front bumper PDC sensor - RH	11 363.03 X
3	1	Front bumper side grille - RH	11 89.95 X
4	1	Front bumper lower lip	gross 412.50 ✓
5	2	Front bumper side retainers - L/R @ 68.55	11 137.10 X
6	1	Front door - RH 2120.35	DD/Bent 2,655.60 ✓
7	1	Front door glass outer moulding	11 260.42 X
8	1	Front door glass run channel	11 281.50 X
9	1	Front door w/strip 248.50	net 260.90 ✓
10	1	Front fender - RH 885.10	DD/Bent gross 991.50 ✓
11	1	Front fender wheel arch garnish	gross 481.35 ✓
12	1	Front fender inner shield	De/ton 181.30 ✓
13	1	Front shock absorber - RH	su 680.95 X
14	1	Front shock absorber top mount	11 211.50 X
15	1	Front top arm - RH	11 460.90 X
16	1	Front lower arm - RH	su 665.90 X
17	1	Front knuckle arm - RH	su 1,385.50 ✓
18	1	Front wheel hub bearing 425.30	net 581.70 ✓
19	1	Front stabilizer bar	11 441.50 X
20	1	Front stabilizer bar link	11 110.20 X
21	1	Rear door - RH 2022.14	DD/Bent 2,635.50 ✓
22	1	Rear door striker	11 120.30 X
23	1	Rear door glass outer moulding	11 261.50 X
24	1	Rear door glass run channel	11 293.50 X
25	1	Rear door 1/4 glass rubber	11 89.96 X
26	1	Rear door checker	11 89.50 X
27	1	Rear door w/strip 248.50	net 263.50 ✓
28	1	Rear fender wheel arch garnish	gross 499.35 ✓
29	1	Rear top arm - RH	11 360.90 X

30	1	Rear	lower arm	17	560.50	X
31	1	Rear	shock absorber	17	299.60	X
32	1	Rear	knuckle arm	17	1,361.50	X
33	1	Rear	wheel hub bearing	17	655.10	X
34	1	Side	sill panel garnish - RH	17	1,260.20	X
35	1	Side	sill panel garnish moulding - RH	17	681.90	X
Sub-total					21,467.24	
Less 10%					2,146.72	
Total List					19,320.52	

Special Nett Items

36	1	Front	sport wheel - AMG '19 inch'	10/12/17	1,500.00	850
37	1	Front	tyre	8/11	650.00	X
38	1	Rear	sport wheel - AMG '19 inch'	10/12/17	1,500.00	850
39	1	Rear	tyre	17	650.00	X
40	1 set	F/R	door revet plug	17	120.00	X
Total Special Nett					4,420.00	

Labour charges

41	To check front electrical wiring	80.00	20
42	To remove, refix front undercarriage	350.00	120
43	To respray undercoating	150.00	80
44	To remove, refix rear undercarriage	350.00	X
45	To check wheel alignment	120.00	80
46	To respray painting and etc	1,400.00	800
47	Panel beating, cut, weld remove & replacing above parts	1,600.00	500
Total Labour		4,050.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

27,790.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 10291-02
 102
 P- 9261-91
 S- 1700-00
 L- 1600-00
 12561-91
 202
 10049.

	P	SN	L	
\$	1,381.13	\$ 850.00	\$	20.00
\$	412.50	\$ 850.00	\$	120.00
\$	2,120.35		\$	80.00
\$	248.50		\$	80.00
\$	885.10		\$	800.00
\$	481.35		\$	500.00
\$	181.30			
\$	1,385.50			
\$	425.30			
\$	2,022.14			
\$	248.50			
\$	499.35			
\$	10,291.02			
	x90%			
\$	9,261.92	\$ 1,700.00	\$ 1,600.00	\$ 12,561.92
				x80%
				\$ 10,049.53
			<u>L/sum</u>	<u>\$ 10,000.00</u>