




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20003939/T1da3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 19-05-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9093Y	Veh. Inspected	FBM 8580Y	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D20001235MFSH/1	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	11/03/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CB400X	c.c	399	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JH2NC4794HK200038	Colour	GREY	
Odometer	30065	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70 R17	METZELER	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	160/60 R17	METZELER	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/02/2020	Inspection Date	12/03/2020	
Survey held at	LEONG SENG MOTOR PTE LTD BLK 1006, BUKIT MERAH LANE 2 #01-08 ALEXANDRA VILLAGE SINGAPORE 159762.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		