

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

13th March 2020

CARRO LEASING PTE LTD
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

TPAIG
Jia Le

Accident date: 11th March 2020

Estimated repair cost for vehicle no: SLF3718U Honda Vezel 1.5A '2016

S/n	Qty	Items	U/price	Amount	
				\$1,020.00	✓
1	1	Rear Boot Lid <i>Distorted</i>		\$430.00	+
2	2	Rear Boot Lid Hinges <i>Neu</i>	\$215.00	\$55.00	✓
3	1	Rear boot lid emble logo <i>Neu</i>		\$38.10	✓
4	1	Rear boot lid Vezel logo <i>Neu</i>		\$716.00	✓
5	2	Rear Boot Lid side reflector <i>ut</i>	\$358.00	\$237.00	✓
6	1	Rear boot lid inner rubber <i>ut</i>		\$284.20	✓
7	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$50.00	X
8	1	Rear Boot Lid Number Plate <i>3 NE</i>		\$122.20	X
9	2	Rear Boot Lid Number Plate Lamp <i>rm</i>	\$61.10	\$352.00	✓
10	1	Rear Boot Lid center moulding <i>can't</i>		\$50.00	30
11	10	Rear Boot Lid Inner Trim board clips <i>rm</i>	\$5.00	\$385.00	285
12	1	Rear Boot Lid Inner Trim board <i>can't</i>		\$770.00	✓
13	2	Rear tail lamp <i>ut</i>	\$385.00	\$430.00	X
14	2	tail lamp lower panel <i>Repair</i>	\$215.00	\$420.00	✓
15	1	Rear end panel <i>Distorted</i>		\$188.00	✓
16	1	Rear End Panel Top Garnish <i>Deformed</i>		\$845.20	✓
17	1	Rear Bumper <i>Deformed</i>		\$176.00	96
18	2	Rear Bumper Side Bracket <i>Neu</i>	\$88.00	\$350.00	200/50
19	1	Rear Bumper reverse sensor <i>Damaged</i>		\$40.00	✓
20	8	Rear bumper clips <i>Neu</i>	\$5.00	\$430.00	215
21	2	rear fender inner cowling plastic <i>RH Deformed</i>	\$215.00	\$855.00	597
22	1	Rear Exhaust <i>Bent</i>		\$122.00	X
23	1	Rear Exhaust aluminium cover <i>Not Neu</i>		\$158.00	✓
24	1	Rear windscreen moulding <i>Neu</i>		\$428.00	252
25	1	Rear spare tire panel lower cover <i>Deformed</i>		\$580.00	X
26	2	Rear spare tire panel lower pump <i>Neu</i>		\$200.00	X
27	1	Rear spare tire panel sealant <i>Neu</i>			

Tools Tray *Sponge*
Deformed

258 ✓

Subtotal :-

\$9,731.70

6856.50

S.N: 200

5485.20

Labour charges

To Remove & refix cushion		\$120.00 60
To Remove & refix rear windscreen		\$120.00 ✓
Gum		\$50.00 ✓
To Remove & refix rear exhaust		\$280.00 80
To Remove & refix reverse Sensor		\$120.00 50
Tuff kote		\$120.00 60
To Check Wiring System	2050	\$80.00 30
Panel beating		\$1,000.00 80
Spray painting		\$1,000.00 80
Subtotal :-		<u>\$2,890.00</u>
Total:-		<u>\$12,621.70</u>

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 7735.20

h/s: 6150 ✓

06 Days.