

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Mar 2020		01 Apr 2020 17:33 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	-, Co. Reg. No.: -								
Main Claimant:	LIM CHEE ENG , ID: S83843201								
Vehicle Reg. No.:	SMA4224K	Date of Loss:	07/03/2020 11:00 - :59 [21 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM20D201195C02	Policy/Cover Note No.:	DMCVSN31049619033						
Vehicle Reg. No. (Insured):	GBF4327B	Policy No. (Claimant):	1800061121						
		Excess:	S\$500.00						
RePAIRer:	Eco Automobile Claims And Repair Pte Ltd (HQ) 13 KAKI BUKIT ROAD 4, #03-29, 417807 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 13/04/2020]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS ☐			View All	Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMA4224K (SNM20D201195C02)**
[GBF4327B]

TP

LIM CHEE ENG

Mar 7 2020 11:00AM

[-]

Eco Automobile Claims And Repair Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)
▼

Assessment Reports				
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	1 per page ▼	☒
1	09/03/20 16:08	Accident Statement	Thumbnail	Print
			Load HTM	

Photos/Images				
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	3 per page ▼	☒
1	09/03/20 16:08	Accident Photo [Linked Accident Report Documents]	Thumbnail	Print
			Load JPG	☒
2	09/03/20 16:08	Accident Photo [Linked Accident Report Documents]	Thumbnail	Print
			Load JPG	☒
3	09/03/20 16:08	Accident Photo [Linked Accident Report Documents]	Thumbnail	Print
			Load JPG	☒
4	09/03/20 16:08	Accident Photo [Linked Accident Report Documents]	Thumbnail	Print
			Load JPG	☒
5	09/03/20 16:08	Accident Photo [Linked Accident Report Documents]	Thumbnail	Print
			Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
2	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
3	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
4	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
5	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
6	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
7	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
8	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
9	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
10	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
11	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
12	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
13	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
14	02/04/20 12:01	Odometer Reading	Thumbnail	Print
			Load JPG	☒
15	02/04/20 12:01	Chassis Number	Thumbnail	Print
			Load JPG	☒
16	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
17	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
18	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
19	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
20	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
21	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
22	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
23	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
24	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
25	02/04/20 12:01	General View	Thumbnail	Print
			Load JPG	☒
26	02/04/20 12:02	General View	Thumbnail	Print
			Load JPG	☒
27	02/04/20 12:02	General View	Thumbnail	Print
			Load JPG	☒
28	02/04/20 12:02	General View	Thumbnail	Print
			Load JPG	☒
29	02/04/20 12:02	General View	Thumbnail	Print
			Load JPG	☒
30	02/04/20 12:02	General View	Thumbnail	Print
			Load JPG	☒

Assessment Reports				1 per page ▼	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
31	02/04/20 12:02	General View		Load JPG	☒
32	02/04/20 12:02	General View		Load JPG	☒
33	02/04/20 12:02	General View		Load JPG	☒
34	02/04/20 12:02	General View		Load JPG	☒
35	02/04/20 12:02	General View		Load JPG	☒
36	02/04/20 12:02	General View		Load JPG	☒
37	02/04/20 12:02	General View		Load JPG	☒
38	02/04/20 12:02	General View		Load JPG	☒
39	02/04/20 12:02	General View		Load JPG	☒
40	02/04/20 12:02	General View		Load JPG	☒
41	02/04/20 12:02	General View		Load JPG	☒
42	02/04/20 12:02	General View		Load JPG	☒
43	02/04/20 12:02	General View		Load JPG	☒
44	02/04/20 12:02	General View		Load JPG	☒
45	02/04/20 12:02	General View		Load JPG	☒
46	02/04/20 12:02	General View		Load JPG	☒
47	02/04/20 12:02	General View		Load JPG	☒
48	02/04/20 12:02	General View		Load JPG	☒
49	02/04/20 12:02	General View		Load JPG	☒
50	02/04/20 12:02	General View		Load JPG	☒
51	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
52	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
53	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
54	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
55	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
56	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
57	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
58	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
59	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
60	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
61	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
62	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
63	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
64	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
65	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
66	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
67	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
68	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
69	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
70	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
71	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
72	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
73	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
74	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
75	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
76	02/04/20 12:02	DISMANTLE PHOTOS		Load JPG	☒
77	02/04/20 12:03	Photo After Spray		Load JPG	☒
78	02/04/20 12:03	Photo After Spray		Load JPG	☒
79	02/04/20 12:03	Photo After Spray		Load JPG	☒
80	02/04/20 12:03	Photo After Spray		Load JPG	☒
81	02/04/20 12:03	Photo After Spray		Load JPG	☒
82	02/04/20 12:03	Photo After Spray		Load JPG	☒
83	02/04/20 12:03	Photo After Spray		Load JPG	☒

Assessment Reports				1 per page ▼	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
84	02/04/20 12:03	Photo After Spray		Load JPG	☒
85	02/04/20 12:03	Photo After Spray		Load JPG	☒
86	02/04/20 12:03	Photo After Spray		Load JPG	☒
87	02/04/20 12:03	Photo After Spray		Load JPG	☒
88	02/04/20 12:03	Photo After Spray		Load JPG	☒
Documentation				1 per page ▼	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	09/03/20 16:07	Sketch Plan [Linked Accident Report Documents]		Load TIF	
2	09/03/20 16:07	Sketch Plan #2 [Linked Accident Report Documents]		Load TIF	
3	09/03/20 16:07	Driving License [Linked Accident Report Documents]		Load TIF	
4	09/03/20 16:07	CI [Linked Accident Report Documents]		Load TIF	

Linked Accident Report Documents

Assessment Reports				View	View in Browser ▼
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	09/03/20 16:08	Accident Statement		Load HTM	
Photos/Images				3 per page ▼	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	09/03/20 16:08	Accident Photo		Load JPG	☒
2	09/03/20 16:08	Accident Photo		Load JPG	☒
3	09/03/20 16:08	Accident Photo		Load JPG	☒
4	09/03/20 16:08	Accident Photo		Load JPG	☒
5	09/03/20 16:08	Accident Photo		Load JPG	☒
Documentation				1 per page ▼	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	09/03/20 16:07	Sketch Plan		Load TIF	
2	09/03/20 16:07	Sketch Plan #2 Click here & type to add comment...		Load TIF	
3	09/03/20 16:07	Driving License		Load TIF	
4	09/03/20 16:07	CI		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/CTI20003957/HYD3S2**Date:** 14/04/2020**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN31049619033
Claimant Vehicle No :	SMA4224K	Insured Vehicle No :	GBF4327B
Date of Loss:	07/03/2020	Nature of Claim:	TP
		Claim No:	SNM20D201195C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA4224K		
Make & Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Engine No:	FB20YD72221
Reg. Date:	26/05/2018 (Man. Year: 2018)	Chassis No:	JF1SJ5KC5JG109411
Colour:	Brown	Odometer:	49501 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	01/04/2020	
Date Inspected:	13/03/2020	Inspected At: Eco Automobile Claims And Repair Pte Ltd (HQ) 13 KAKI BUKIT ROAD 4, #03-29 Singapore 417807
Estimated Period of Repair:	4.0 days	

Adjuster: LEE HOCK ANN**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$5,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Apr 2020)
Parts:	M1-SUV	SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA4224K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >