



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

TP 1st Cap.
 Asher

Contact : 66550005-GRAB 90622833

ESTIMATE

Repair Code : CLM16124

Date in : 11/03/2020

Vehicle Num. : SLM4464H

Model : NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR

Chassis/Eng# : SJNFEAJ11U1773827/HRA2335094A

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Repld.</i>	1	717.00	✓ 717.00
REAR BUMPER INNER SPONGE <i>could</i>	1	126.40	✓ 126.40
REAR BUMPER REINFORCEMENT <i>Best</i>	1	619.20	✓ 619.20
REAR BUMPER REINFORCEMENT BRACKET L/R <i>Best</i>	2	126.00	✓ 252.00
REAR BUMPER SIDE RETAINER L/R <i>re</i>	2	35.90	✓ 71.80
REAR BUMPER TOW HOOK COVER <i>Repld</i>	1	16.80	✓ 16.80
REAR END PANEL <i>Dented</i>	1	482.60	✓ 482.60
REAR END PANEL ANTENNA SENSOR <i>could</i>	1	285.10	✓ 285.10
REAR END PANEL INNER TOP GARNISH <i>Repld</i>	1	63.50	✓ 63.50
REAR RH TAILLAMP <i>could</i>	1	323.70	✓ 323.70
REAR TAILGATE 'QASHQAI' EMBLEM	1	87.00	+ 87.00
REAR TAILGATE MECHANISM LOCK	1	116.70	+ 116.70
REAR TAILGATE WEATHER STRIP	1	158.70	+ 158.70
Subtotal before discount			3,320.50
Percentage discount 10%			332.05
Sub-total 1			2,988.45
REAR BUMPER CLIPS - SET <i>Nlec</i>	1	50.00	✓ 50.00
REAR BUMPER REVERSE SENSOR - SET <i>Damaged</i>	1	450.00	<i>300</i> 450.00

*** This is a computer-generated document which requires no signature.***

51 AUTOMOTIVE PTE LTD

13 Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 90622833

ESTIMATE

Repair Code : CLM16124
 Date in : 11/03/2020
 Vehicle Num. : SLM4464H
 Model : NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
 Chassis/Eng# : SJNFEAJ11U1773827/HRA2335094A

REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>Nu</i>	<i>370</i>	1	30.00	<i>10</i> 30.00
REAR RH TAILLAMP CLIPS - SET <i>Nu</i>		1	20.00	<i>10</i> 20.00
Subtotal before discount				550.00
Percentage discount 0%				0.00
Sub-total 2				550.00
Parts-total				3,538.45

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	50.00 ✓
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	120.00 <i>53</i>
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	900.00 <i>500</i>
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	<i>1230</i> 800.00 <i>600</i>
To apply anti-rust chemical on repaired and replaced panel.	50.00 ✓
Labour Total	1,920.00
Parts & Labour Total	5,458.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

*** This is a computer-generated document which requires no signature. ***

page 2

total: 4262.29 *Adrian Ling*
 L/S: 3.4K ✓ L/S 13/03/20
 05 days.