



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2005316
INV Date 30/07/2020
Reference CC4/FCI20003963/Gea3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SLU 5114U
Insured Veh. SHC 7990K
Claim No. D20001281MFSH
Policy No. D-20094921MFSH
Accident Date 02/03/2020
Inspection Date 13/03/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20003963/Gea3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 30-07-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7990K	Veh. Inspected	SLU 5114U	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D20001281MFSH	Excess (\$)	0.00	
Assign From	ERIC WOO	Assign Date	13/03/2020	
2. Vehicle Particulars & Condition				
Make & Model	BLUECAR	c.c	0	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VL4BCEB4RHT002977	Colour	WHITE	
Odometer	31432	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/65 R15	MICHELIN	6 mm	
L/H Front Tyre	175/65 R15	MICHELIN	6 mm	
R/H Rear Tyre	175/65 R15	MICHELIN	6 mm	
L/H Rear Tyre	175/65 R15	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS				
5. General Information				
Accident Date	02/03/2020	Inspection Date	13/03/2020	
Survey held at	INDECO ENGINEERS PTE LTD 39 DEFU LANE 12 . SINGAPORE 539139			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 5114U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER ASSY (WCP)	DEFORMED	1,364.00	1,364.00
10	REAR BUMPER SCREW @\$2.00 (WCP)	NECESSARY	20.00	20.00
1	REAR BUMPER REFLECTOR RH (WCP)	DISTORTED	122.00	122.00
1	REAR BUMPER REINFORCEMENT (WCP)	NOT NECESSARY	80.00	-
1	REAR BUMPER REINFORCEMENT BRACKET RH (WCP)	NOT NECESSARY	42.00	-
1	NUMBER PLATE LAMP LH (WCP)	BROKEN	38.00	38.00
1	NUMBER PLATE LAMP RH (WCP)	BROKEN	38.00	38.00
	COST PLUS 20%		340.80	-
	COST PLUS 15%		-	237.30
			2,044.80	1,819.30
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE W CASING (SN)	CRACKED	45.00	45.00
			45.00	45.00
<u>LABOUR</u>				
	TO REPAIR ,REPLACE REAR BUMPER ,REFLECTOR ,NUMBER PLATE LAMP AND AFFECTED AREA.		400.00	200.00
	TO APPLY TUFF KOTE.	NOT NECESSARY	150.00	-
	TO CHECK WIRING .		100.00	20.00
			650.00	220.00
GRAND TOTAL			2,739.80	2,084.30
RECOMMENDED COST OF REPAIRS				2,084.30

Report Ref No. CC4/FCI20003963/Gea3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLU 5114U

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLU 5114U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

