

**ACCIDENT REPAIR ESTIMATES**

Our Ref: TP/ SLU5114U

Type of Claim : TPVehicle No. : SLU5114UMake & Model : BLUECAR / BLUECARBLYear of Manufacture : 2017Chassis No. : VL4BCEB4RHT002977Ins Company : MS FIRST CAPITAL  
INSURANCE LIMITEDEngine No. : -921955Q16W381345632Excess : 0

Policy No. : \_\_\_\_\_

Date of Accident : 02/03/2020Time of Accident : 12:00:00Suggested Days of Repair : 3Case Owner : BLUECAR EAST ASIA PTE**Repair Estimates**TP Vehicle No. : SHC7990KParts (a) Cost / List Price Items \$ 1,704.00Plus/Less <sup>150%</sup> 20.0% \$ 340.80Total of Cost / List \$ 2,044.80(b) Nett Price Items \$ -Less \$ -Total of Nett Item \$ -(c) Special Nett Items \$ 45.00Total Parts Cost (Appendix A) \$ 2,089.80Labour (Appendix B) \$ 650.00Total Repair Cost \$ 2,739.80

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Guo Qiang - 82880282Company : LKKSurvey conducted on : 13/3/20 at \_\_\_\_\_**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 1 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_

*After repair photos*



VEHICLES &amp; EQUIPMENT DIVISION

No. 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

**ESTIMATED REPAIR COST DETAILS**

Vehicle No : SLU5114U Case Owner : BLUECAR EAST  
Make & Model : BLUECAR / BLUECARBLUECA Year Manufacture : 2017  
Chassis No : VL4BCEB4RHT002977 Engine No : -921955Q16W3813456  
Date & Time : \_\_\_\_\_ Supplier : \_\_\_\_\_  
Order By : \_\_\_\_\_ Type of Claim : TP

| S/No | Part Description                                  | QTY | Cost Price  |             | List Price | Nett Price | S/N      |
|------|---------------------------------------------------|-----|-------------|-------------|------------|------------|----------|
|      |                                                   |     | Unit        | Sub-Total   |            |            |          |
| 1    | REAR BUMPER ASSY / <i>re</i>                      | 1   | \$ 1,364.00 | \$ 1,364.00 |            |            |          |
| 2    | REAR BUMPER SCREW / <i>re</i>                     | 10  | \$ 2.00     | \$ 20.00    |            |            |          |
| 3    | REAR BUMPER REFLECTOR RH / <i>re</i>              | 1   | \$ 122.00   | \$ 122.00   |            |            |          |
| 4    | REAR BUMPER REINFORCEMENT <i>re</i> NN            | 1   | \$ 80.00    | \$ 80.00    |            |            |          |
| 5    | REAR BUMPER REINFORCEMENT BRACKET RH <i>re</i> NN | 1   | \$ 42.00    | \$ 42.00    |            |            |          |
| 6    | NUMBER PLATE LAMP LH <i>re</i> Br                 | 1   | \$ 38.00    | \$ 38.00    |            |            |          |
| 7    | NUMBER PLATE LAMP RH <i>re</i> Br                 | 1   | \$ 38.00    | \$ 38.00    |            |            |          |
| 8    | REAR NUMBER PLATE W CASING / <i>re</i>            | 1   |             |             |            |            | \$ 45.00 |
| 9    |                                                   |     |             |             |            |            |          |
| 10   |                                                   |     |             |             |            |            |          |
| 11   |                                                   |     |             |             |            |            |          |
| 12   |                                                   |     |             |             |            |            |          |
| 13   |                                                   |     |             |             |            |            |          |
| 14   |                                                   |     |             |             |            |            |          |
| 15   |                                                   |     |             |             |            |            |          |
| 16   |                                                   |     |             |             |            |            |          |
| 17   |                                                   |     |             |             |            |            |          |
| 18   |                                                   |     |             |             |            |            |          |
| 19   |                                                   |     |             |             |            |            |          |
| 20   |                                                   |     |             |             |            |            |          |
| 21   |                                                   |     |             |             |            |            |          |
| 22   |                                                   |     |             |             |            |            |          |
| 23   |                                                   |     |             |             |            |            |          |
| 24   |                                                   |     |             |             |            |            |          |
| 25   |                                                   |     |             |             |            |            |          |
| 26   |                                                   |     |             |             |            |            |          |
| 27   |                                                   |     |             |             |            |            |          |
| 28   |                                                   |     |             |             |            |            |          |
| 29   |                                                   |     |             |             |            |            |          |
| 30   |                                                   |     |             |             |            |            |          |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**TOTAL**

\$ 1,686.00 \$ 1,704.00 \$ - \$ - \$ 45.00

*1582.00**45.00*



Tel: (65) 382 2736 FAX: (65) 6382 2817

BLUECAR  
EAST ASIA  
PTE LTD  
2017

Make & Model : / BLUECARBLUECAR / BLUECAR Year of Manufacture

LKK Auto Consultants hence notify the-Repairer of the following:

- To resurvey before/after spray-painting
- To display damaged part(s) during resurvey
- Parts prices are subject-to-confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal-modification(s) is allowed
- Supplementary item(s) must be resurveyed and is-subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

220.00