

ACCIDENT REPAIR ESTIMATES

Our Ref: TP / SLU5114U

Type of Claim : TPVehicle No. : SLU5114UMake & Model : BLUECAR / BLUECARBLYear of Manufacture : 2017Chassis No. : VL4BCEB4RHT002977Ins Company : MS FIRST CAPITAL
INSURANCE LIMITEDEngine No. : -921955Q16W381345632Excess : 0

Policy No. : _____

Date of Accident : 02/03/2020Time of Accident : 12:00:00Suggested Days of Repair : 3Case Owner : BLUECAR EAST ASIA PTE**Repair Estimates**TP Vehicle No. : SHC7990KParts (a) Cost / List Price Items \$ 1,704.00Plus/Less ~~20.0%~~ 15% \$ 340.80Total of Cost / List \$ 2,044.80(b) Nett Price Items \$ -Less \$ -Total of Nett Item \$ -(c) Special Nett Items \$ 45.00Total Parts Cost (Appendix A) \$ 2,089.80Labour (Appendix B) \$ 650.00Total Repair Cost \$ 2,739.80**LKK Auto Consultants** hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Guo Qiang - 82880282Company : LKKSurvey conducted on : 13/3/20 at _____**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 1 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

After report photos



VEHICLES & EQUIPMENT DIVISION

No . 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

ESTIMATED REPAIR COST DETAILS

Vehicle No : SLU5114U Case Owner : BLUECAR EAST
Make & Model : BLUECAR / BLUECARBLUECA Year Manufacture : ASIA PTE LTD
Chassis No : VL4BCEB4RHT002977 Engine No : 2017
Date & Time : _____ Supplier : -921955Q16W3813456
Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
			Unit	Sub-Total			
1	REAR BUMPER ASSY / <i>de</i>	1	\$ 1,364.00	\$ 1,364.00			
2	REAR BUMPER SCREW / <i>de</i>	10	\$ 2.00	\$ 20.00			
3	REAR BUMPER REFLECTOR RH / <i>de</i>	1	\$ 122.00	\$ 122.00			
4	REAR BUMPER REINFORCEMENT ?	1	\$ 80.00	\$ 80.00			
5	REAR BUMPER REINFORCEMENT BRACKET RH ?	1	\$ 42.00	\$ 42.00			
6	NUMBER PLATE LAMP LH ?	1	\$ 38.00	\$ 38.00			
7	NUMBER PLATE LAMP RH ?	1	\$ 38.00	\$ 38.00			
8	REAR NUMBER PLATE W CASING / <i>de</i>	1					\$ 45.00
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL

\$ 1,686.00 \$ 1,704.00 \$ - \$ - \$ 45.00



Tel: (65) 382 2736 FAX: (65) 6382 2817

BLUECAR
EAST ASIA

Case Owner

: PTE LTD

2017

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.