



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2007460
INV Date 09/11/2020
Reference CC6/FCI20003965/Uba3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SMA 610E
Insured Veh. SHA 4749Y
Claim No. D20001486MFSH
Policy No. D-18088936MFSH
Accident Date 12/03/2020
Inspection Date 13/03/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC6/FCI20003965/Uba3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 09-11-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 4749Y	Veh. Inspected	SMA 610E
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D20001486MFSH	Excess (\$)	0.00
Assign From	VIC	Assign Date	13/03/2020

2. Vehicle Particulars & Condition

Make & Model	BMW 116 (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WBA1V72090V945606	Colour	GREY
Odometer	53490	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40 R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/40 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/40 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/40 R18	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	12/03/2020	Inspection Date	13/03/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 610E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR DOOR N/S	BENT / WARPED	1,660.00	1,145.32
1	REAR DOOR GLASS OUTER MOULDING N/S	NOT NECESSARY	266.00	-
1	REAR DOOR GLASS REGULATOR & MOTOR N/S	NOT NECESSARY	485.00	-
1	REAR DOOR INNER LOCK N/S	NOT NECESSARY	422.00	-
1	REAR DOOR INNER TRIM BOARD N/S	NOT NECESSARY	1,105.00	-
1	ROCKER PANEL GARNISH N/S	DEEP CUT	1,220.00	850.00
1	SET ROCKER PANEL GARNISH CLIPS N/S	NECESSARY	50.00	50.00
1	REAR FENDER N/S	TO REPAIR SEE LABOUR	1,125.00	-
1	REAR SHOCK ABSORBER N/S	NOT NECESSARY	299.30	-
1	REAR WHEEL HUB BEARING N/S	NOT NECESSARY	689.00	-
	LESS 5% DISCOUNT		-	-102.27
			7,321.30	1,943.05
	<u>SPECIAL NETT ITEMS</u>			
1	REAR SPORT RIM N/S (SN)	DENTED	1,080.00	750.00
			1,080.00	750.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	60.00
	TO DISMANTLE & REFIX REAR UNDER CARRIAGE.	NOT NECESSARY	180.00	-
	TO DISMANTLE & REFIX REAR DOOR MECHANISM.		100.00	60.00
	TO SPRAY RUST PROOFING.		50.00	30.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER N/S.		680.00	300.00
	TO PUTTY & SPRAY PAINTING.		1,200.00	600.00
			2,380.00	1,070.00
	GRAND TOTAL		10,781.30	3,763.05
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,000.00

Report Ref No. CC6/FCI20003965/Uba3q2



Report Ref No. CC6/FCI20003965/Uba3q2

A handwritten signature in black ink, appearing to be 'Ch' followed by a stylized flourish.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMA 610E

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMA 610E

RE-INSPECTION

