

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBC7795D200303

**Estimate****Customer**

Name: China Taiping Insurance (Singapore) Pte Ltd

Address: Motor Claims Department

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Date: 03-03-20

Vehicle No: GBC7795D

Model/Make: Toyota Hiace  
Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Rh Door "B" Pillar	\$ 465.10	X
2	Sliding Door	\$ 1,650.10	X
3	Sliding Door Lock	\$ 344.10	X
4	Sliding Door Cross Panel	\$ 514.60	X
5	Sliding Door Roller	\$ 208.80	X
6	Sliding Door Inner Lock	\$ 288.10	X
7	Body Panel	\$ 1,285.10	X
8	Body Panel Railing	\$ 388.20	X
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,000.00	300
	To putty & spray painting & including touch up paint on accident affected area	\$ 800.00	400
	To remove, replace and transfer Sliding door panel, fitting and mechanisms	\$ 100.00	60
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 80.00	30

Total Parts &amp; Labour of estimate for damaged vehicle

\$ 7,124.10

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Not Authorized  
Mark  
1/5 1600  
3 days  
the ph. the rep

P- 1615.4  
252  
1211.53  
2001.55  
1601.