

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 5-Mar-20

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHD4700X

INSURANCE:

First Capital

financed

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR TRUNK LID COVER <i>Dented / Bt</i>	1	\$1,647.30	\$1,647.30
REAR TRUNK LID LOCK <i>SVC</i>	1	\$457.90	\$457.90
REAR TRUNK LID COVER TRIM BOARD <i>NH</i>	1	\$216.50	\$216.50
REAR TRUNK LID RUBBER <i>damaged</i>	1	\$365.20	\$365.20
REAR TRUNK LID LAMP G5 <i>broken o/s</i>	1	\$636.80	\$636.80
REAR TRUNK LID OUTER GARNISH <i>Dented</i> <i>889.70</i>	1	\$2,237.50	\$2,237.50
REAR TRUNK LID GLASS (BLACK COLOR) <i>NH</i>	1	\$1,569.70	\$1,569.70
REAR TRUNK LID LOGO (PRIUS) <i>Nec</i>	1	\$60.80	\$60.80
REAR TRUNK LID LOGO (HYBRID) <i>Nec</i>	1	\$52.40	\$52.40
REAR TRUNK LID LOGO (TOYOTA STAR) <i>Nec</i>	1	\$52.90	\$52.90
REAR TRUNK LID HINGE (RH) <i>NH</i>	1	\$189.50	\$189.50
REAR TRUNK LID ABSORBER (RH) <i>NH</i>	1	\$287.50	\$287.50
REAR TRUNK LID ABSORBER BRACKET (RH) <i>NH</i>	1	\$127.90	\$127.90
REAR TRUNK LID STOPPER (RH) <i>NH</i>	1	\$84.80	\$84.80
SPOILERSUB-ASSY. REAR <i>NH</i>	1	\$953.70	\$953.70
REAR BUMPER <i>broken</i>	1	\$796.40	\$796.40
REAR BUMPER RE-INFORCEMENT <i>Dented / Bt</i>	1	\$318.80	\$318.80
REAR BUMPER UNDER COVER <i>Dented</i>	1	\$552.60	\$552.60
REAR BUMPER SIDE RETAINER <i>damaged NH</i>	1	\$112.70	\$112.70
REAR BUMPER UNDER SIDE CENTRE COVER <i>NH</i>	1	\$552.60	\$552.60
REAR BUMPER TOWING COVER <i>dislodged</i>	1	\$82.70	\$82.70
REAR BUMPER CLIPS <i>Nec</i>	1	\$22.00	\$22.00
REAR BUMPER SIDE CLIP <i>NH</i>	1	\$25.00	\$25.00
REAR BUMPER UPPER STOPPER <i>NH</i>	1	\$76.40	\$76.40
ARM SUB-ASSY, REAR BUMPER, RH <i>NH</i>	1	\$139.60	\$139.60
REAR BUMPER UNDER SIDE COVER (RH) <i>SVC</i>	1	\$232.00	\$232.00
SEAL, REAR BUMPER SIDE, RH <i>cut / Dented NH NS</i>	1	\$148.40	\$148.40
RETAINER, REAR BUMPER, SIDE, RH <i>NH</i>	1	\$94.80	\$94.80
RETAINER, REAR BUMPER, UPPER SIDE (RH) <i>crack</i>	1	\$30.70	\$30.70
TAIL LAMP ASSY (UPPER) G5 <i>broken o/s</i>	1	\$873.50	\$873.50
TAIL LAMP ASSY (LOWER) G5 <i>broken o/s</i>	1	\$814.70	\$814.70
TAIL LAMP QUARTER PANEL <i>Dented o/s</i>	1	\$216.00	\$216.00
TAIL LAMP SIDE COVER <i>broken / dislodged o/s</i>	1	\$256.00	\$256.00
REAR END PANEL <i>Dented</i>	1	\$602.10	\$602.10
REAR END PANEL GARNISH <i>damaged</i>	1	\$161.80	\$161.80
REAR SPARE TYRE PANEL <i>NH</i>	1	\$667.70	\$667.70
REAR FIBER TOOL BOX TRIM <i>o/s & SVC</i>	1	\$398.00	\$398.00
REAR EXHAUST PIPE <i>Bt</i>	1	\$1,163.40	\$1,163.40
REAR EXHAUST PIPE HANGER <i>NH</i>	1	\$40.70	\$40.70
REAR EXHAUST PIPE INSULATOR <i>NH</i>	1	\$314.60	\$314.60
REAR EXHAUST PIPE CENTRE INSULATOR <i>NH</i>	1	\$498.60	\$498.60

REAR WINDSCREEN GLASS W/ MOULDING <i>2 New</i>	1	\$1,778.30	\$1,778.30	<i>2 ✓</i>
REAR WINDSCREEN SEALANT <i>2 New</i>	1	\$46.00	\$46.00	<i>2 ✓</i>
SUB TOTAL				
<i>11420.10</i>			\$19,956.50	
LESS 20% <i>25%</i>			\$3,991.30	
DISCOUNTED TOTAL			\$15,965.20	
<i>8565.07</i>				
REAR BUMPER BLACK MAT <i>defunct</i> SN	1	\$50.00	\$50.00	<i>✓</i>
REAR TRUNK LID APPS STICKER <i>New</i> SN	1	\$40.00	\$40.00	<i>✓</i>
REAR TRUNK LID COMFORT & TEL NO. STICKER <i>New</i> SN	1	\$60.00	\$60.00	<i>✓</i>
SUB TOTAL			\$150.00	
<i>150.00</i>				
Labour Charge				
Panel Beating	1	\$1,600.00	\$1,600.00	<i>800/-</i>
Spray Painting Charge	1	\$1,400.00	\$1,400.00	<i>720/-</i>
Wiring Charge	1	\$120.00	\$120.00	<i>40/-</i>
Tuff Kote <i>1720.00</i>	1	\$180.00	\$180.00	<i>40/-</i>
Towing Charge	1	\$80.00	\$80.00	<i>40/-</i>
Remove/Refix Rear Windscreen Glass	1	\$120.00	\$120.00	<i>40/-</i>
Remove/Refix Reverse Sensor	1	\$120.00	\$120.00	<i>40/-</i>
Remove/Refix Exhaust Pipe	1	\$80.00	\$80.00	<i>60/-</i>
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	<i>40/-</i>
TOTAL LABOUR			\$4,250.00	
ESTIMATE TOTAL			\$20,365.20	
after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

13/03/2020 @ 1000hrs

NA Auction

P/P *2/3/20* 8 days.

you

LKK Auto

[Signature]

Photo after
reg
with
damaged
parts.

10435.07

Supp 1744.12

P/P 12179.19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 14-Mar-20

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHD4700X

INSURANCE: First Capital

DESCRIPTION	QTY	LIST PRICE	AMOUNT
SPARE TYRE LOCK NUT 44	1	\$123.76	\$123.76
REAR SPARE TYRE PANEL SIDE PANEL (LH/RH) o/s Deform	1	\$763.80	\$763.80
REAR FENDER, RH Deform 836.70	1	\$1,171.38	\$1,171.38
REAR FENDER TRIMBOARD (LH/RH) o/s deformed Rt	1	\$1,015.00	\$1,015.00
725.00			
SUB TOTAL			\$3,073.94
LESS 20% 25%			\$614.79
DISCOUNTED TOTAL			\$2,459.15
ESTIMATE TOTAL			\$2,459.15

X
✓
✓
✓
2325.50
1744.12

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

T
you

LKK Auto

8