OPTIMAMERH SINGAPORE

OPTIMA WERKZ PTE LTD Co. Reg. No. 201212455W

www.ow.sg

Noy Nothorse

[] /OptimaWerkz

/OptimaWerkz

Date:

11.03.2020

Vehicle No: SGW161P

Model:

TOYOTS WISH

Chassis:

ZNE100370321-2007

Reg. Year:

2007

Third Party Insurer:

Third Party Veh No: SJK9794G Date of Accident:

AIG

11.03.2020

4days

DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$		
REAR BUMPER	1	/	\$895.70		
REAR BUMPER CLIPS	8	\$5.50	Ma \$44.00		
REAR TAILGATE	1		By \$1,771.00		
REAR WINDSCREEN RUBBER 124	1	Mark T	na \$78.00		
REAR END PANEL	1		REPAIR		
	1 1 9	SUB TOTAL	\$2,788.70		
		LESS 25%	-\$697.18		
		PARTS TOTAL	\$2,091.53		
	REAR BUMPER REAR BUMPER CLIPS REAR TAILGATE REAR WINDSCREEN RUBBER REAR END PANEL	REAR BUMPER 1 REAR BUMPER CLIPS 8 REAR TAILGATE 1 REAR WINDSCREEN RUBBER 1 REAR END PANEL 1	REAR BUMPER REAR BUMPER CLIPS REAR TAILGATE REAR WINDSCREEN RUBBER REAR END PANEL SUB TOTAL LESS 25%		

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		Mr \$80.00
			S/N TOTAL	\$80.00

Yosa

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX & READJUST REAR ACCIDENT AREAS & ETC.

\$500.00 800

\$700.00 4001

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR END PANEL, REAR TAILGATE & ETC.

LABOUR CHARGES TO REMOVE & REPLACE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT, REAR WINDSCREEN RUBBER & ETC.

\$150.00 /201

LABOUR CHARGES TO REMOVE & REFIX REAR TAILGATE INNER MECHANISM & ETC. TO EFFECT REPLACE AT REAR TAILGATE.

\$120.00 601

LABOUR CHARGES TO CHECK WIRING & CENTRAL LOCKING SYSTEM & ETC.

\$50.00 15/

	LKK Auto Consultants hence notify the Repairer of the following:	LABOUR TOTA	L \$1,520.00
	To resurvey before/after spray painting To display damaged part(s) during resurvey		
ONG	Parts prices are subject to confirmation	TOTAL	\$3,691.53
	 Third party survey is on a "Without Prejudice" b No illegal modification(s) is allowed 	asis	
 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 		g pany	
Head office	Acknowledged by Repairer	Branch	
6 Kung Chong Road Singapo Tel: (+65) 6472 1313 Fax: (159 139 1312 9A Serangoon North Ave 5 Singapore 554500 159 16473 2312 Tel: (+65) 6484 9919 Fax: (+65) 6481 1011	551 Upper Thomson Road Singapore 574415 Tel: (+65) 6452 6868 Fax: (+65) 6452 9223	