

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9505K

AAD2003-068

*Not Authorized
Respray B4 paint*

Vehicle No.:
 Chassis No.:
 Vehicle Make: **12 MAR 2020**
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHD 9505K
 JTDKB3FU803077034
 TOYOTA
 PRIUS
 10.3.2020
CHINA TAIPING
 22/11/2018

PART	LIST	
1 MOULDING ASSY, BODY ROCKER PANEL, LH	\$ Pn	594.80
1 PANEL SUB-ASSY, QUARTER, LH	\$ Pn	871.50
1 REAR FENDER LINER	\$ Pn	139.80
1 DUCT ASSY, QUARTER VENT, LH	\$ Pn	67.00
1 SEAL, REAR BUMPER SIDE, LH	\$ Pn	88.50
1 REAR BUMPER	\$ Pn	442.60
1 REAR BUMPER UNDER COVER (BLACK)	\$ Pn	576.30
1 REAR BUMPER SIDE RETAINER LH	\$ Pn	116.50
1 TAILLAMP LOWER LH	\$ Pn	502.00
1 TAILLAMP UPPER LH	\$ Pn	443.30
1 REAR BUMPER SIDE LH	\$ Pn	123.70
1 PANEL SUB-ASSY, REAR DOOR, LH	\$ <i>nd/warp</i>	1,294.90
1 TAPE, BLACK OUT, NO.1 LH	\$ Nn	21.90
1 TAPE, BLACK OUT, NO.2 LH	\$ Nn	34.90
1 TAPE, BLACK OUT, NO.3 LH	\$ Nn	15.40
1 REAR WHEEL RIM	\$ Pn	1,879.40 X
1 REAR WHEEL RIM COVER	\$ Pn	211.50 X

TOTAL	\$	7,424.00
25%	\$	1,856.00
	\$	5,568.00

Special Nett		
1 REAR DOOR STICKER '6555-3333'	\$	Nn 100.00 <i>605a</i>
1SET REAR BUMPER CLIP	\$	Nn 66.00 X
2 REAR WINDSCREEN SEALANT	\$	Nn 100.00 X

Trans-cab Auto Services Pte Ltd

AAD2003-068

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9505K

1 WINDSCREEN MOULDING	\$	<i>na</i>	150.00	} X
1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	
1SET REAR FENDER LINER CLIP	\$	<i>na</i>	33.00	
1 REAR TYRE 195/65/15	\$	<i>na</i>	350.00	
1SET REAR BUMPER RETAINER CLIP	\$	<i>na</i>	35.00	
1SET ROCKER PANEL MOULDING CLIP	\$	<i>na</i>	35.00	
1SET TAILLAMP LOWER CLIP	\$	<i>na</i>	25.00	
1SET TAILLAMP UPPER CLIP	\$	<i>na</i>	25.00	
TOTAL	\$		1,019.00	
TOTAL PARTS	\$		6,587.00	

LABOUR

To transfer of Rear Fender fittings, attachments and perform water seepage test.	\$	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>4000</i>

Trans-cab Auto Services Pte Ltd

AAD2003-068

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9505K

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	6601
To Check Electrical Lighting Concerned.	\$	170.00	201
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	601
TOTAL	\$	14,340.00	
Over All Total	\$	20,927.00	

(PART-BY-PART) Repair Days

20 DAYS

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: