



Kd

方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

EZORA SIGNATURES PTE LTD
APT BLK 130 CLARENCE LANE
#02-38
SINGAPORE 140130
Dear sir

Not authorized
11hry @ 2300h
Murray After Party
4 days

Estimate cost of repair to vehicle no. SLR 3757T

To supply

1. Rear tail boot	885	Bz	1,073.00	✓
2. Rear boot reflector x2		Sm	560.00	X
3. Rear Tail lamp x2		Sm	640.00	X
4. Rear tail boot rubber		Sm	201.00	✓
5. Rear tail boot lock		Al	240.00	X
6. Rear tail boot logo		Sm	45.00	✓
7. Rear tail boot badge FORTEK		Sm	65.00	✓
8. Rear tail boot badge CERTO		Sm	55.00	✓
9. Rear bumper		Bur	668.00	✓
10. Rear bumper lower		Al	347.00	✓
11. Rear bumper sensor	98	Al	350.00	2000
12. Rear bumper retainer x2		Sm	60.00	X
13. Rear bumper reflector x2		Sm	50.00	X
14. W/s glass moulding	108	Sm	120.00	X

Labour charge
Rust proofing
Number plate
Penal beating
Spray painting

100.00 300
Sm 50.00 X
980.00 400
900.00 400

Total

6504

Your faithfully

ALBERT POON

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

0. 0

885. +

45. +

65. +

55. +

668. +

347. =

2,065. *

2,065. x

90. %

1,858.5 *

200. +

=

200. *

4/5 - \$2300

30. +

400. +

400. =

830. *

1,858.5 +

200. +

830. =

2,888.5 *

2,888.5 x

80. %

2,310.8 *

0. 0