



方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

EZORA SIGNATURES PTE LTD
APT BLK 130 CLARENCE LANE
#02-38
SINGAPORE 140130
Dear sir

*Not Authark
11/12/8?
Murray After Rain
4 days*

Estimate cost of repair to vehicle no. SLR 3757T

To supply

1. Rear tail boot	Ry	1,073.00	✓
2. Rear boot reflector x2	Sm	560.00	X
3. Rear Tail lamp x2	Sm	640.00	X
4. Rear tail boot rubber	Sm	201.00	X
5. Rear tail boot lock	Al	240.00	X
6. Rear tail boot logo	Sm	45.00	—
7. Rear tail boot badge FORTEK	Sm	65.00	—
8. Rear tail boot badge CERTO	Sm	55.00	—
9. Rear bumper	Bm	668.00	—
10. Rear bumper lower	Ad	347.00	—
11. Rear bumper sensor	Ad	350.00	2 cars
12. Rear bumper retainer x2	Sm	60.00	X
13. Rear bumper reflector x2	Sm	50.00	X
14. W/s glass moulding	Sm	120.00	X

10/8

Labour charge
Rust proofing
Number plate
Penal beating
Spray painting

	100.00	301
Sm	50.00	X
	980.00	4001
	900.00	4001

Total

Your faithfully

AS7

ALBERT POON

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: