

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SBQ2883S

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES2090252

Date: 13 Mar 2020

Policy No: 5108349707

Veh Reg No: SBQ2883S

Make/Model: MAZDA MAZDA 3 4-DOOR SEDAN 1.5L SP. 6EAT

WS Ref: TP-AIG

Claim Type: Third Party

Accident Date: 11/03/2020

TP Veh Reg No: SMA53M

Chassis No: JM6BM42A8G0301483

Engine No: P520262860

Reg. Date: 26/03/2015

Estimate Repair Cost to Vehicle No :SBQ2883S

PAGE:1/2

Description	U/Price	Quantity	List Price SS	Amount SS
List Price				
1 REAR BUMPER	1,127.00	1 PC	1,127.00	✓
2 REAR BUMPER REFLECTOR	52.60	2 PCS	105.20	✓
3 REAR BUMPER RETAINER	37.90	2 PCS	75.80	✓
4 REAR BUMPER CLIPS	4.80	6 PCS	28.80	✓
5 REAR BUMPER TOW	16.80	2 PCS	33.60	✓
6 REAR BUMPER REINFORCEMENT	563.80	1 PC	563.80	✓
7 REAR BOOT	1,004.80	1 PC	1,004.80	✓
8 REAR BOOT EMBLEM '3'	56.07	1 PC	56.07	✓
9 REAR BOOT EMBLEM 'SKY'	66.30	1 PC	66.30	✓
10 REAR BOOT INNER LOCK	185.80	1 PC	185.80	✓
11 REAR BOOT INNER RUBBER	135.40	1 PC	135.40	✓
12 REAR BOOT SPONGE (INNER SPONGE)	135.30	1 PC	135.30	✓
13 REAR BOOT LOGO	77.60	1 PC	77.60	✓
14 TAIL LAMP	534.40	2 PCS	1,068.80	✓
15 TAIL LAMP PANELS	395.60	2 PCS	791.20	✓
16 REAR PANEL	530.20	1 PC	530.20	✓
17 REAR PANEL INNER TOP GARNISH	99.75	1 PC	99.75	✓
18 REAR LH FENDER	1,232.70	1 PC	1,232.70	✓
19 REAR WINDSCREEN MOULDING	77.10	1 PC	77.10	✓
			7,395.22	
		Less 20%	1,479.04	5,916.18
Special Net				
20 REVERSE SENSOR	200.00	1 PC	200.00	✓
21 REAR WINDSCREEN GUM	40.00	1 PC	40.00	✓
22 REAR NUMBER PLATE	35.00	1 PC	35.00	✓
			275.00	275.00
Labour				
23 TOWING	50.00	1 LA	50.00	✓
24 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
25 REMOVE AND REFIX SEAT, CARPET, GARNISH, TOP ROOF LINING	120.00	1 LA	120.00	✓

Supp =

2pc rear fender inner garnishs ?

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

Estimate No: ES2090252
Date: 13 Mar 2020
Policy No: 5108349707
Veh Reg No: SBQ2883S
Make/Model: MAZDA MAZDA 3 4-DOOR SEDAN 1.5L SP. 6EAT
Chassis No: JM6BM42A8G0301483
Engine No: P520262860
Reg. Date: 26/03/2015


WS Ref: TP-AIG
Claim Type: Third Party
Accident Date: 11/03/2020
TP Veh Reg No: SMA53M

Estimate Repair Cost to Vehicle No :SBQ2883S

PAGE:2/2

Description	U/Price	Quantity	List Price S\$	Amount S\$
26 REMOVE AND REFIX REAR BUMPER ASSY, TAIL LAMP, REAR BOOT, REFLECTORS. TO STRAIGHTEN, KNOCK AND REPAIR REAR BOTH CHASSISS, CUTTING, WELDING AND RENEW REAR PANEL, TAIL LAMP PANELS, REAR LH FENDER AND REALIGN THE SAME	1,300.00	1 LA	1,300.00	1200
27 PUTTY AND RESPRAY ON REAR BOOT, HINGES, REAR PANEL, REAR BOTH FENDERS, REAR SPARE TYRE COMPARTMENT, REAR BUMPER AND REAR AFFECTED AREA.	1,100.00	1 LA	1,100.00	1000
28 RUSTPROOFING	60.00	1 LA	60.00 2,750.00	✓ 2,750.00
			Total	S\$ 8,941.18
			Add GST @ 7%	625.88
			Total Amount Payable	S\$ 9,567.06

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: