

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 32238

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0263/2020/NS
Date : 11-Mar-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Hu Jun
Address : BLk 856B Tampines Street 82
#08-158
Singapore 522856
Telephone : HP +65 82230238
Type of Claim : Own Damage Claims
Policy No. : 1900010052
Vehicle No : **SMH 2956 H**
Model Code : Audi A4 Sedan 2.0 TFSI 8W
Model / Year : Jan-19
Engine No : CVK 072219
Chassis No : WAUZZZF47KN000866
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Mar-20
Place of Accident : Along PIE (Nearby Adam Rd)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMH 2956 H

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓
2	To dismantle and renew front bumper, bonnet and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,450.00	1000
3	To respray front bumper, bonnet and hinges.	\$ 2,500.00	1100
4	To carry out diagnostic check.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: <u>\$ 5,622.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 2956 H

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Rehd</i>	\$ 2,068.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 553.00	+
3	FRONT BUMPER GRILLE - CENTRE <i>new</i>	\$ 185.00	+
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 198.00	+
5	FRONT BUMPER AIR GUIDE - LH <i>new</i>	\$ 59.00	+
6	RADIATOR GRILLE <i>new</i>	\$ 1,254.00	✓
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>?</i>	\$ 127.00	?
8	FRONT BUMPER CARRIER <i>new</i>	\$ 757.00	+
9	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	\$ 117.00	+
10	FRONT BUMPER COVER <i>new</i>	\$ 120.00	✓
11	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	\$ 34.00	+
12	CAUTION SIGN STICKER <i>?</i>	NEC \$ 13.00	✓
13	AIRCON STICKER <i>?</i>	NEC \$ 7.00	✓
14	LOCK CARRIER BRACKET <i>new</i>	\$ 129.00	✓
15	FRONT BUMPER SUPPORT - LH / RH <i>?</i>	2 \$ 54.00	?
16	HORN - LH HIGH TONE <i>?</i>	\$ 38.00	+
17	SPRING SHACKLE - LH <i>new</i>	2 \$ 27.00	+
18	FRONT PARKING AID SENSOR - INNER / OUTER <i>?</i>	2 TBC	+
19	FRONT PARKING AID SEAL RING <i>14</i>	4 \$ 14.00	+
20	BONNET <i>Buckled</i>	\$ 2,634.00	✓
SUB TOTAL SPARE PARTS CHARGES		: \$ 8,388.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 2956 H

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	BONNET ATTACHMENT PARTS	\$ 388.00	+
22	BONNET LID HINGE - LH / RH	2 \$ 574.00	+
23	BONNET IMPACT PROTECTION - CENTRE	\$ 26.00	—
24	BONNET IMPACT PROTECTION - LH	\$ 26.00	✓
25	BONNET IMPACT PROTECTION - RH	\$ 26.00	✓
26	BONNET GAS FILLED STRUT	2 \$ 224.00	+
27	BONNET STRIKER - LH / RH	2 \$ 94.00	+
28	BONNET LID LOCK	2 \$ 403.00	+
29	BONNET BOWDEN CABLE - CENTRE	\$ 54.00	+
30	BONNET RELEASE CABLE	\$ 54.00	+
31	BONNET RELEASE LEVER	\$ 13.00	+
32	BONNET LID LOCK CABLE	\$ 69.00	+
33	LED HEADLIGHT - LH	\$ 7,321.00	+
34	LIFT CYLINDER - LH	\$ 198.00	+
35	RADIATOR AIR GUIDE - LH OUTER	\$ 27.00	+
36	RADIATOR AIR GUIDE - LH INNER	\$ 12.00	+
37	RADIATOR AIR GUIDE - UPPER	\$ 15.00	+
38	RADIATOR AIR GUIDE - LOWER	\$ 21.00	+
39	FRONT NO PLATE	S/N \$ 60.00	✓
40	SUNDRIES	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		: \$ 18,293.00	
TOTAL LABOUR CHARGES		: \$ 5,622.00	
GRAND TOTAL		: \$ 23,915.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 13/03/20
Authorised Date :
Excess Cost :
Liability :
Remarks : All Authorised, 04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant