

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 32238

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0263/2020/NS
Date : 11-Mar-20

Vehicle NOT IN workshop. Please arrange for survey

Xiao Chen . 6 days

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

17480-80

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Hu Jun
Address : BLk 856B Tampines Street 82
#08-158
Singapore 522856
Telephone : HP +65 82230238
Type of Claim : Own Damage Claims
Policy No. : 1900010052
Vehicle No : **SMH 2956 H**
Model Code : Audi A4 Sedan 2.0 TFSI 8W
Model / Year : Jan-19
Engine No : CVK 072219
Chassis No : WAUZZZF47KN000866
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Mar-20
Place of Accident : Along PIE (Nearby Adam Rd)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMH 2956 H

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓
2	To dismantle and renew front bumper, bonnet and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,450.00	1000 1250
3	To respray front bumper, bonnet and hinges.	\$ 2,500.00	1100 ✓
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 5,622.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 2956 H

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>deduct</i>	\$ 2,068.00	✓ 1654.40
2	FRONT BUMPER FIXING PARTS <i>not nee</i>	\$ 553.00	+
3	FRONT BUMPER GRILLE - CENTRE <i>not nee</i>	\$ 185.00	+
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>not nee</i>	\$ 198.00	+
5	FRONT BUMPER AIR GUIDE - LH <i>not nee</i>	\$ 59.00	+
6	RADIATOR GRILLE <i>included</i>	\$ 1,254.00	✓ 1003.20
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Not nee</i>	\$ 127.00	✗
8	FRONT BUMPER CARRIER <i>deduct</i>	\$ 757.00	+ 605.20 ✓
9	FRONT BUMPER FOAM FILLER PIECE <i>included</i>	\$ 117.00	+ 93.60 ✓
10	FRONT BUMPER COVER <i>included</i>	\$ 120.00	✓ 96
11	FRONT BUMPER GUIDE SECTION - LH <i>not nee</i>	\$ 34.00	+
12	CAUTION SIGN STICKER <i>per</i>	NEC \$ 13.00	✓ 10.24
13	AIRCON STICKER	NEC \$ 7.00	✓ 5.36
14	LOCK CARRIER BRACKET <i>included</i>	\$ 129.00	✓ 103.20
15	FRONT BUMPER SUPPORT - LH / RH <i>Not nee</i>	2 \$ 54.00	✗
16	HORN - LH HIGH TONE <i>per</i>	\$ 38.00	+
17	SPRING SHACKLE - LH <i>per</i>	2 \$ 27.00	+
18	FRONT PARKING AID SENSOR - INNER / OUTER <i>per</i>	2	TBC +
19	FRONT PARKING AID SEAL RING <i>per</i>	4 \$ 14.00	+
20	BONNET <i>Buckled</i>	\$ 2,634.00	✓ 2107.20
SUB TOTAL SPARE PARTS CHARGES		: <u>\$ 8,388.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 2956 H

		Damage Parts & Prices		
S/N	Parts Description		S/Nett	Remarks
21	BONNET ATTACHMENT PARTS	3	\$ 388.00	
22	BONNET LID HINGE - LH / RH	2	\$ 574.00	
23	BONNET IMPACT PROTECTION - CENTRE		\$ 26.00	20.56
24	BONNET IMPACT PROTECTION - LH		\$ 26.00	20.80
25	BONNET IMPACT PROTECTION - RH		\$ 26.00	20.56
26	BONNET GAS FILLED STRUT	2	\$ 224.00	
27	BONNET STRIKER - LH / RH	2	\$ 94.00	
28	BONNET LID LOCK	2	\$ 403.00	
29	BONNET BOWDEN CABLE - CENTRE		\$ 54.00	
30	BONNET RELEASE CABLE		\$ 54.00	
31	BONNET RELEASE LEVER		\$ 13.00	
32	BONNET LID LOCK CABLE		\$ 69.00	
33	LED HEADLIGHT - LH		\$ 7,321.00	5856.80 ✓
34	LIFT CYLINDER - LH		\$ 198.00	
35	RADIATOR AIR GUIDE - LH OUTER		\$ 27.00	21.04 ✓
36	RADIATOR AIR GUIDE - LH INNER		\$ 12.00	8.88 ✓
37	RADIATOR AIR GUIDE - UPPER		\$ 15.00	
38	RADIATOR AIR GUIDE - LOWER		\$ 21.00	
39	FRONT NO PLATE	S/N	\$ 60.00	✓
40	SUNDRIES		\$ 300.00	2.24 ✓
TOTAL SPARE PARTS CHARGES		:	\$ 18,293.00	
TOTAL LABOUR CHARGES		:	\$ 5,622.00	
GRAND TOTAL		:	\$ 23,915.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 13/03/20
Authorised Date :
Excess Cost :
Liability :
Remarks : no authorised, off days

06 Days
// [Signature]

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0263/2020/NS

Date

21-Apr-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SMH 2956 H

Model No

Audi A4 Sedan 2.0 TFSI 8V

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Liquid coolant	\$ 176.00	134.72

Labours

- 1 To remove and reinstall aircond condenser, charged air cooler and radiator. Check electrical fans and control unit. To pressurise cooling system. To carry out vacuum and regas.

S/N \$ 1,200.00



[Signature]
22/4/20

TOTAL

\$ 1,376.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0263/2020/NS

Date

21-Apr-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SMH 2956 H

Model No

Audi A4 Sedan 2.0 TFSI 8W

Quantity Description

Unit Price Amount

Parts

- | | |
|---|----------------------------|
| 1 | Temperature sensor bracket |
| 2 | Reinforcement bracket LHS |

\$	18.00	ca	13.68
\$	214.00	bf	171.20

Labours

- | | |
|---|---|
| 1 | To dislodge front lock carrier to facilitate renewal for reinforcement bracket LHS. |
|---|---|

\$	2,100.00	1250	✓
----	---------------------	------	---

TOTAL

\$ -

For Premium Automobiles Pte Ltd

Paul
21/04/2020

Subject to
insurance approval

Authorised Signature