



凱 摩 哆 服 務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Attn: The Motor Claims Department

Your Insured veh no : SFS 9936 U

AIG ASIA PACIFIC INSURANCE PTE LTD.

78 Shenton Way

07-16 Chartis Building

Singapore 079120

WITHOUT PREJUDICE

(By Email Only)

Date : 13/03/2020

Dear Sir / Madam

Final Cost of repair Toyota Yaris No SGK 4972 C & SLL 6663 S on 05/03/2020@14:20:00

To Supply:-

We have been authorised by M/s COOKING ART INDUSTRIES PTE LTD , the owner of vehicle claim against the party / parties responsible for the damages arising from number SGK 4972 C, to the above mentioned accident.

Our records show that you are the insurers of vehicle numbe (SLL 6663 S) at the material time of the accident with the driver of our client's vehicle, (M/s COOKING ART INDUSTRIES PTE LTD).

As a result of the accident caused by your insured driver's negligent driving and/or management of your insured's vehicle number (SLL 6663 S) , our client's vehicle was damaged and we have been put to loss and damage as follows:

(1) Cost of repair	\$ 4,280.00
(2) Loss of use X 6	\$ 480.00
(3) PIR 2days	\$ 160.00
(4) LTA Search Fee	\$ 7.45
	<u>\$ 4,927.45</u>

A cope of each of the following supporting documents is enclosed:

- (a) Final repair bill
- (b) GIA report with sketch plan of (our client's veh number)
- (c) LTA Search





凱 摩 哆 服 務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Attn: The Motor Claims Department

Your Insured veh no : SLL 6663 S

AIG ASIA PACIFIC INSURANCE PTE LTD.

78 Shenton Way

07-16 Chartis Building

Singapore 079120

WITHOUT PREJUDICE

(By Email Only)

Date : 13/03/2020

Dear Sir / Madam

Final Cost of repair Toyota Yaris No SGK 4972 C & SLL 6663 S on 05/03/2020@14:20:00

To Supply:-

Total Lumpsum As Of Repair Costs Recommended By Surveyor And

Agreed By Ourselves : \$ 4,000.00

GST 7% \$ 280.00

\$ 4,280.00

