

# ESTIMATE TO REPAIR

VEHICLE NO. : YP 1804 K  
MAKE : MITSUBISHI  
MODEL : CANTER FEB21ER4SDEB  
YEAR : 2015  
CHASSIS NO : FEB21EA20241

SURVEYOR NAME : *Lee*  
DATE OF SURVEY :  
TIME OF SURVEY : *17 MAR 2020*

DATE : 11-Mar-20  
DATE OF ACCIDENT : 24-Feb-20  
THIRD PARTY REF : YP 3140 D  
THIRD PARTY REF : EQ INSURANCE CO LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
	n/s rear door film , 'door gasket , 'door lock bar , 'checker plate and glue		<i>P.7</i>	<i>Bill</i> \$1,800.00	\$ 2,400.00
	To putty & spray paint			\$	800.00
TG/VL	TOTAL			\$	3,200.00
<div><p><i>Not Notified</i></p><p><i>Uly 87</i></p><p><i>Reamy After Point</i></p><p><i>3 days</i></p></div> <div><p>LKK Auto Consultants hence notify the Repairer of the following:</p><ul style="list-style-type: none"><li>• To resurvey before/after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Parts prices are subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modification(s) is allowed</li><li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li></ul><p>Acknowledged by Repairer</p><p>Signature:</p><p>Date:</p></div>					