

MotorImage

19 Lorong 8 Toa Payoh
Singapore 319255



ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

| | |
|---------------------------|---------------------------------|
| REG NO: SMC3503B | MODEL : FORESTER 2.0I-L AWD CVT |
| REF: INS/IC/CHI/0067/2020 | YEAR: 29-JUN-2018 |
| ENGINE NO: FB20YE11318 | CHASSIS NO: JF1SJ5KC5JG110790 |
| DOA: 04/03/2020 | TOA: 1815HRS |
| TYPE OF CLAIM: ODR | INS COMPANY: AIG |

| S/N | NATURE OF JOB | AMOUNT | |
|---------------------|--|-------------------|----------------------|
| 1. | REPAIR/REPLACE REAR BUMPER, END PANEL, FLOOR PAN, TAILGATE AND PANEL | \$ 1750.00 | 600-1000. |
| 2. | RESPRAY REAR BUMPER, END PANEL, FLOOR PAN, TAILGATE AND PANEL | \$ 1400.00 | 750 |
| 3. | DISMANTLE & REFIX UNDERCARRIAGE TO FACILITATE REPAIRS | \$ 684.00 | X NN |
| 4. | REMOVE & REFIX EXHAUST | \$ 114.00 | X NN |
| 5. | TRANSFER TAILGATE MECHANISM | \$ 95.00 | X NN |
| 6. | TO CONDUCT 4 WHEEL ALIGNMENT | \$ 171.00 | X NN |
| 7. | REMOVE & REFIX CARPET, SEATS TO FACILITATE REPAIRS | \$ 342.00 | X NN |
| 8. | REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIRS | \$ 114.00 | X NN |
| 9. | TO REMOVE & REFIX FUEL TANK | \$ 171.00 | X NN |
| 10. | TO CONDUCT ANTI RUST COATING | \$ 290.00 | X NN |
| 11. | TO REMOVE & INSTALL REAR WINDSCREEN | \$ 300.00 | X NN |
| 12. | TO CONDUCT REAR LIGHTING TEST | \$ 28.00 | ✓ |
| 13. | TO SUPPLY & INSTALL REVERSE SENSOR - 2 EYES | \$ 300.00 | X NN |
| 14. | SUNDRIES | \$ 100.00 | X NN |
| Total Labour | | \$ 5859.00 | |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

| | |
|----------------|---------------|
| DATE APPROVAL: | |
| TIME APPROVAL: | |
| SURVEY BY: | Kenneth (LKK) |
| HP / EMAIL: | 969106631 |
| BEFORE PAINT: | Yes MIE |
| DAYS GIVEN: | |

Acknowledged by Repairer
Signature:

10
0
Rear

Not Authorized
Resurvey before paint
6-12 days

Estimate

Date 03 / 05 / 2020

001 / 002

| | | | |
|---------------------|----------|---------------|-------------------|
| Invoice Number | SMC3503B | Tel(Home) | |
| Registration Number | | Tel(Office) | |
| E-Mail | | Tel(Portable) | |
| | | Fax | |
| | | Model Name | S13 |
| | | Body Model | SJ5EK7C |
| | | Vin-Code | JF1SJ5KC5JG110790 |

| Part Number | Part Code Name | Part Code | Q'ty | Price | |
|--------------|---------------------------------|----------------|------|----------|---|
| 59122SG060 | MUD GUARD,REAR RIGHT | FIG-541 59112 | 1 | 57.60 | X |
| 59122SG070 | MUD GUARD,REAR LEFT | FIG-541 59112A | 1 | 57.60 | X |
| 63516SG001 | WEATHER STRIP-REAR GATE | FIG-901 63516 | 1 | 111.60 | X |
| 57731SG010NN | COVER-REAR BUMPER | FIG-591 57731C | 1 | 12.60 | ✓ |
| 57704SG012 | BUMPER-FACE,REAR | FIG-591 57704A | 1 | 540.00 | ✓ |
| 57707SG080 | BRACKET-REAR BUMPER SIDE,RIGHT | FIG-591 57707H | 1 | 14.40 | X |
| 57707SG090 | BRACKET-REAR BUMPER SIDE,LEFT | FIG-591 57707I | 1 | 14.40 | X |
| 57711SG0219P | BACK BEAM COMPLETE-REAR | FIG-591 57711D | 1 | 288.00 | ✓ |
| 52401SG0109P | SKIRT COMPLETE-REAR | FIG-505 52411 | 1 | 288.00 | ✗ |
| 52129SG0019P | FLOOR PAN COMPLETE-REAR,REAR | FIG-505 52110 | 1 | 432.00 | ✗ |
| 84281SC000 | REFLEX REFLECTOR ASSEMBLY-RIGHT | FIG-842 84281 | 2 | 40.80 | X |
| 84281SC010 | REFLEX REFLECTOR ASSEMBLY-LEFT | FIG-842 84281A | 1 | 20.40 | X |
| 93079SG000 | LETTER MARK-REAR | FIG-919 93073Y | 1 | 39.60 | X |
| 93079SG030 | LETTER MARK-REAR | FIG-919 93073Y | 1 | 64.80 | X |
| 44370FG002 | TAIL PIPE CUTTER | FIG-440 44371 | 1 | 72.00 | X |
| 44300SG010 | MUFFLER ASSEMBLY-RIGHT | FIG-440 44300A | 1 | 601.20 | X |
| Page-Total | | | | 2,655.00 | |

| |
|------|
| Memo |
| |

| |
|-------------|
| Grand Total |
| 3,905.80 |

| |
|--|
| |
|--|

| |
|-----|
| Tel |
|-----|

Estimate

Date 03 / 05 / 2020

002 / 002

| | | | |
|---------------------|----------|---------------|-------------------|
| Invoice Number | SMC3503B | Tel(Home) | |
| Registration Number | | Tel(Office) | |
| E-Mail | | Tel(Portable) | |
| | | Fax | |
| | | Model Name | S13 |
| | | Body Model | SJ5EK7C |
| | | Vin-Code | JF1SJ5KC5JG110790 |

| Part Number | Part Code Name | Part Code | Q'ty | Price |
|-------------|----------------------------|-----------------|------|------------------------|
| 44011SG000 | GASKET A | FIG-440 44011A | 1 | NN 7.20 X |
| 44200SG080 | EXHAUST PIPE ASSEMBLY-REAR | FIG-440 44200 | 1 | A 745.20 X |
| 44022AA123 | GASKET-EXHAUST PIPE REAR | FIG-440 44284 | 1 | S _h 24.00 X |
| 57731SG060 | COVER-REAR BUMPER | FIG-591 57731CA | 1 | S _h 14.40 X |
| E7710SG000 | CARGO STEP PANEL S/S] | FIG-591 57707AD | 1 | M 460.00 ✓ |
| | | Page-Total | | 1,250.80 |
| | | Sub-Total | | 3,905.80 |
| | | Total | | 3,905.80 |
| | | Tax | | 0.00 |
| | | Grand Total | | 3,905.80 |

| |
|------|
| Memo |
| |

| |
|-------------|
| Grand Total |
| 3,905.80 |

10,180.10

| |
|--|
| |
|--|

| |
|-----|
| Tel |
| |



Motor Image Enterprises Pte Ltd
 19 Lorong 8 Toa Payoh
 Singapore 319255
 Tel: (65) 6703 8101/8102
 Fax: (65) 6253 5535
www.motorimage.net
 Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY LABOUR FOR VEHICLE REGISTRATION NO SMC-3503-B

Surveyor: _____

LABOUR DESCRIPTION AMOUNT

1 TO CONDUCT ANTI RUST COATING ✓ \$290.00

2 _____

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

3 _____

4 _____

Acknowledged by Repairer
 Signature: _____
 Date: _____

5 _____

6 _____

7 _____

8 _____

9 _____

10 _____

11 _____

12 _____



Motor Image Enterprises Pte Ltd
 19 Lorong 8 Toa Payoh
 Singapore 319255
 Tel: (65) 6703 8101/8102
 Fax: (65) 6253 5535
www.motorimage.net
 Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY PARTS FOR VEHICLE REGISTRATION NO SMC-3503-B

Surveyor: _____

| DESCRIPTION | PART NO | AMOUNT |
|--------------------------------|-------------------|-----------------|
| 1 <u>COILER REAR Bump</u> ✓ BT | <u>5773186060</u> | <u>\$14,40</u> |
| 2 <u>BOLT</u> ✓ BT | <u>901720002</u> | <u>\$10,10</u> |
| 3 <u>HOLDER JACK</u> ✓ CRA | <u>970356J050</u> | <u>\$100,80</u> |
| 4 _____ | _____ | _____ |
| 5 _____ | _____ | _____ |
| 6 _____ | _____ | _____ |
| 7 _____ | _____ | _____ |
| 8 _____ | _____ | _____ |
| 9 _____ | _____ | _____ |
| 10 _____ | _____ | _____ |
| 11 _____ | _____ | _____ |
| 12 _____ | _____ | _____ |
| 13 _____ | _____ | _____ |
| 14 _____ | _____ | _____ |
| 15 _____ | _____ | _____ |
| 16 _____ | _____ | _____ |
| 17 _____ | _____ | _____ |
| 18 _____ | _____ | _____ |
| 19 _____ | _____ | _____ |
| 20 _____ | _____ | _____ |
| 21 _____ | _____ | _____ |
| 22 _____ | _____ | _____ |
| 23 _____ | _____ | _____ |
| 24 _____ | _____ | _____ |

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____