

ASS. REC. BY:

REF: CS/SMO 20004030/Kyf302

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Irene Hui

of

SMO

Date/Time: 13.3.2020 5:05p.m.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMA 9737P

Insured: SLL 6089A

at Workshop n/s: Tong Luck

Tel: 625 00088

of 160 Sin Ming Drive #07-01/06 Sin Ming Awdry

Policy No:

Claim No: CMTD 2000408 / LOR

Sum Insured:

Excess:

Make of Veh:

D.O.A. 23.1.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

RP"

Date/Time: 16.3.2020 10.42a.m.

Person Contacted:

Yu Ling

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (V) Estimate
	SMA 9737P - X
	SLL 6089A - CS/SMO 190170004/Kyf302 Ref - 15/11/2019
23/3	Sent Preli by email

ASS. REQ. BY:

REF: SMO /

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

1.81 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMA 9737P

Yr Regn:

06, 18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M. Silver

c.c.

1991

Colour

A/C: Insured / Std / NI / NA

Sp. Reading

73935

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

W00 2130 4 22A 456779

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45R18

R:

275/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

mm

Rear

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

23/1/20

D.O.I.

16/3/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25/3

PIP \$5659-40

confirm by Candy (Red \$3413-20, 37%)

RECEIVED 26 MAR 2020

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

26/3/20 Typist

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

240

Transportation:

\$ - RS. \$

F. & T. \$

Others

TOTAL

240

Report Format:

Lump Sum / I.B.I. (\$

PIP \$5659-40



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD2000408/LOR

Date: 20 Mar 2020

Our Ref: CS/SMO20004030/Kyf3

The Motor Claims Department
SOMPO INSURANCE SINGAPORE PL


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SMA9737P

Please be informed that we had conducted the inspection of the abovementioned vehicle on 16/03/2020 at the premises of M/s TONG LUCK AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>9,120.25</u>
Revised Estimate Amount	: S\$ <u>5,080.40</u>
"Check" Items Amount	: S\$ <u>1,007.00</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the rear body.



Yours faithfully

Kenneth Kong
Licensed Appraiser

Nivitha (LKK Auto)

From: Henry, Irene James <irene.henry@sompo.com.sg>
Sent: Friday, 13 March 2020 5:05 PM
To: assignments@lkkauto.com
Cc: sur@lkkauto.com; Nivitha (LKK Auto); Operation / Yu Ching
Subject: RE: SOMPO REF:CMTD2000408/LOR/RE: ACCIDENT INVOLVING VEHICLE NO.: SMA9737P & SLL6089A ON 23/01/2020 @ 0820 HRS ALONG DUNEARN RD AFTER SHELFORD RD
Attachments: SMA9737P - NOA.pdf

Aside to LKK AUTO CONSULTANTS PTE LTD,

Kindly contact the undersigned for conduct of the motor survey.

Best Regards
Irene Henry
Claims Division
D: 6322 4618 | T: 6461 6555



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Operation / Yu Ching <operation@tlauto.com.sg>
Sent: Friday, 13 March, 2020 4:51 PM
To: Henry, Irene James <irene.henry@sompo.com.sg>
Cc: Wong, Lorriance <lorriance.wong@sompo.com.sg>
Subject: RE: SOMPO REF:CMTD2000408/LOR/RE: ACCIDENT INVOLVING VEHICLE NO.: SMA9737P & SLL6089A ON 23/01/2020 @ 0820 HRS ALONG DUNEARN RD AFTER SHELFORD RD

Dear Irene,

Please refer to our reply below.

We hereby confirm and agreed to nominate LKK Auto Consultants (Mr. Kenneth Kong) to conduct the PRI survey of our client's vehicle

Thanks & regards,
Yu Ching



Tong Luck Auto Pte Ltd

160 Sin Ming Drive

#07-01/06 Sin Ming Autocity

Singapore 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

From: Henry, Irene James <irene.henry@sompo.com.sg>

Sent: Friday, 13 March, 2020 3:23 PM

To: Operation / Yu Ching <operation@tlauto.com.sg>

Cc: Wong, Lorriance <lorriance.wong@sompo.com.sg>

Subject: SOMPO REF:CMTD2000408/LOR/RE: ACCIDENT INVOLVING VEHICLE NO.: SMA9737P & SLL6089A ON 23/01/2020 @ 0820 HRS ALONG DUNEARN RD AFTER SHELFORD RD

Our Reference : CMTD2000408/LOR

Your Reference: SMA 9737P

Date: 13th March 2020

Without Prejudice
EMAIL ONLY

Attention:

M/S TONG LUCK AUTO PTE LTD

ACCIDENT INVOLVING SLL 6089A & SMA 9737P ON 23.01.2020

Dear Sir/ Madam,

We refer to your notice of accident dated 13.03.2020 via email.

Please be informed that **Lorriance Wong** is the handler of this case who can be contacted at 6329 5175/
lorriance.wong@sompo.com.sg.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	✓
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or

legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompoo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Operation / Yu Ching <operation@tlauto.com.sg>

Sent: Friday, 13 March, 2020 2:00 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Cc: Teo, Grace <grace.teo@sompo.com.sg>

Subject: ACCIDENT INVOLVING VEHICLE NO.: SMA9737P & SLL6089A ON 23/01/2020 @ 0820 HRS
ALONG DUNEARN RD AFTER SHELFORD RD

Dear All,

We have our client's instruction to notify you the above accident

Please find attached documents for your information and necessary action

The vehicle is now garage at our workshop

Kindly arrange your to inspect the vehicle at an earlier date

Thanks & regards,
Yu Ching



Tong Luck Auto Pte Ltd

160 Sin Ming Drive

#07-01/06 Sin Ming Autocity

Singapore 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623
Attn: MOTOR CLAIMS DEPT

13 March 2020

Dear Sirs / Madam,

RE: ACCIDENT INVOLVING VEHICLE NO.: SMA9737P & SLL6089A ON 23/01/2020 @ 08:20 HRS ALONG
DUNEARN RD AFTER SHELFORD RD

We hereby authorized by our client **DAIMLER FLEET MANAGEMENT S'PORE PTE LTD**, the owner/driver of the above mentioned vehicle No.: **SMA9737P**

We notice that the above accident was caused by your insured/driver negligent driving and/or management of motor vehicle No.: **SLL6089A**

Therefore we are instructed by our client to claim against you/your insured driver in connection with the above captioned accident involving our client's vehicle No.: **SMA9737P** and vehicle No.: **SLL6089A** by your insured/driver at the material time. As a result, our client's vehicle was damaged and our client has been put to loss and expenses. Please assign your surveyor to inspect the above mentioned vehicle in the next 48hrs. Filling which, we will proceed to the repair of the vehicle. Details of claim will submitted to you in due course.

The vehicle is now garage at: **TONG LUCK AUTO PTE LTD**
160 Sin Ming Drive
#07-01/06 Sin Ming Autocity
Singapore 575722
Tel: 6250 0088

Your kind attention to the matter would be much appreciated.

Yours faithfully,

TONG LUCK AUTO PTE LTD



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :
ATTN : ACCOUNTS DEPT

YOUR REF NO : SLL6089A
CLAIM TYPE : THIRD PARTY
TP INS. CO. : SOMPO INSURANCE SINGAPORE PTE LTD
ACCIDENT DATE : 23/01/2020
TP VEH REG NO : SLL6089A

ESTIMATE

NO : QUOT202003-000037(00)
DATE : 12/03/2020
POLICY NO : 999995580
VEH REG NO : SMA9737P
MAKE/MODEL : MERCEDES BENZ E200
EXCLUSIVE (R18 LED)
CHASSIS NO : WDD2130422A454779
ENGINE NO : 27492031463962
REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SMA9737P

Description	Quantity	Unit Price	Amount
		S\$	S\$
LIST PRICE			
1 Bootlid	1	2,402.00	2,402.00
2 Bootlid weatherstrip	1	325.00	325.00
3 Bootlid lock	1	295.00	295.00
4 Bootlid centre logo	1	55.00	55.00
5 Bootlid 'E200' emblem	1	94.00	94.00
6 Bootlid '9G-TRONIC' emblem	1	120.00	120.00
7 Bootlid trimboard clips	10	10.00	100.00
8 Bootlid centre chrome	1	145.00	145.00
9 Rear bumper	1	1,530.00	1,530.00
10 Rear bumper reinforcement	1	835.00	835.00
11 Rear bumper sensor	2	188.00	376.00
12 Rear bumper sensor seals	6	12.00	72.00
13 Rear bumper clips	15	9.00	135.00
			6,484.00
		Less 10%	648.40
			5,835.60
SPECIAL NET			
14 Bootlid 'C & C' emblem	1	38.00	38.00
			38.00
LABOUR			
15 To transfer damaged bootlid interior mechanism to new bootlid	1	150.00	150.00
16 To remove and refit rear bumper sensor	1	100.00	100.00
17 To check and rectify wiring system	1	80.00	80.00
18 To remove and refit rear interior garnishes and trimboard to facilitates the repairs	1	120.00	120.00
19 To panel beat and straighten rear chassis frame, rear floor board panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
20 To putty and spray paint on affected areas	1	1,200.00	1,200.00
			2,650.00



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :
ATTN : ACCOUNTS DEPT

YOUR REF NO : SLL6089A
CLAIM TYPE : THIRD PARTY
TP INS. CO. : SOMPO INSURANCE SINGAPORE PTE LTD
ACCIDENT DATE : 23/01/2020
TP VEH REG NO : SLL6089A

ESTIMATE


NO : QUOT202003-000037(00)
DATE : 12/03/2020
POLICY NO : 999995580
VEH REG NO : SMA9737P
MAKE/MODEL : MERCEDES BENZ E200
EXCLUSIVE (R18 LED)
CHASSIS NO : WDD2130422A454779
ENGINE NO : 27492031463962
REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SMA9737P

Description	Quantity	Unit Price	Amount
		S\$	S\$
		TOTAL	S\$ 8,523.60
		ADD GST @ 7%	596.65
		GRAND TOTAL	S\$ 9,120.25

SINGAPORE DOLLAR NINE THOUSAND ONE HUNDRED TWENTY AND CENTS TWENTY-FIVE ONLY

FOR TONG LUCK AUTO PTE LTD


AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/01/2020 23:02
Date Of Accident	23/01/2020 08:20
Exact Location Of Accident	ALONG DUNEARN RD AFTER SHELFORD RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA9737P
Insured/Policyholder	
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Co Reg No	1XXXXX778Z
Email Address	KATHRYN.ADRIANO@DAIMLER.COM
Mobile Phone No	
Alternative Phone No	OFFICE-68498118

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200 EXCLUSIVE (R18 LED)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE

Are you claiming under your own insurance policy for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995580
Cover Note Number	

Driver

Name of Driver	WEE KENG KOON
NRIC No	SXXXX675Z
Date Of Birth	18/12/1951
Occupation	INDOOR
Date Of Driving Pass	05/06/1972
Driving Experience	47 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97551159
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Traffic flows was heavy along DUNEARN RD. Front vehicle slowed down and stopped ,followed by my vehicle. Suddenly I felt an impact from behind and saw a vehicle had already hit onto my rear portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL6089A
Vehicle Make/Model/Colour	HONDA / SHUTTLE 1.5G CVT / RED
Details Of Properties	NA
Vehicle Category	PRIVATE CAR
Name of Driver	TAY LILING
NRIC/Passport Number	SXXXX530C
Contact Number	92391310
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
AIZAM BIN ATAN

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

A: SMA 4737P
B: SLL 6089A



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
AIZAM BIN ATAN

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:

ACCIDENT STATEMENT (2000 characters)

Traffic flows was heavy along DUNEARN RD.
Front vehicle slowed down and stopped ,followed by my vehicle.
Suddenly I felt an impact from behind and saw a vehicle had already hit onto my rear
portion.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
AIZAM BIN ATAN

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

23 January 2020 at 3:30 PM

Date/Time:

23 January 2020 at 3:30 PM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/01/2020 23:02
Date Of Accident	23/01/2020 08:20
Exact Location Of Accident	ALONG DUNEARN RD AFTER SHELFORD RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA9737P
Insured/Policyholder	
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Co Reg No	1XXXXX778Z
Email Address	KATHRYN.ADRIANO@DAIMLER.COM
Mobile Phone No	
Alternative Phone No	OFFICE-68498118

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200 EXCLUSIVE (R18 LED)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995580
Cover Note Number	

Driver

Name of Driver	WEE KENG KOON
NRIC No	SXXXX675Z
Date Of Birth	18/12/1951
Occupation	INDOOR
Date Of Driving Pass	05/06/1972
Driving Experience	47 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97551159
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Traffic flows was heavy along DUNEARN RD. Front vehicle slowed down and stopped, followed by my vehicle. Suddenly I felt an impact from behind and saw a vehicle had already hit onto my rear portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL6089A
Vehicle Make/Model/Colour	HONDA / SHUTTLE 1.5G CVT / RED
Details Of Properties	NA
Vehicle Category	PRIVATE CAR
Name of Driver	TAY LILING
NRIC/Passport Number	SXXXX530C
Contact Number	92391310
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
 AIZAM BIN ATAN

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

A: SMA 9137P
B: SL 6089A



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
AIZAM BIN ATAN

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:

ACCIDENT STATEMENT (2000 characters)

Traffic flows was heavy along DUNEARN RD.
Front vehicle slowed down and stopped ,followed by my vehicle.
Suddenly I felt an impact from behind and saw a vehicle had already hit onto my rear portion.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
AIZAM BIN ATAN

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

23 January 2020 at 3:30 PM

Date/Time:

23 January 2020 at 3:30 PM



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX : *Not withash*

ATTN : ACCOUNTS DEPT

YOUR REF NO : SLL6089A

CLAIM TYPE : THIRD PARTY

TP INS. CO. : SOMPO INSURANCE SINGAPORE PTE LTD

ACCIDENT DATE : 23/01/2020

TP VEH REG NO : SLL6089A

ESTIMATE

NO : QUOT202003-000037(00)

DATE : 12/03/2020

POLICY NO : 999995580

VEH REG NO : SMA9737P

MAKE/MODEL : MERCEDES BENZ E200
EXCLUSIVE (R18 LED)

CHASSIS NO : WDD2130422A454779

ENGINE NO : 27492031463962

REG. DATE : 2018

Polay

Estimate Repair Cost to Vehicle No : SMA9737P

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
LIST PRICE			
1 Bootlid	1	2,402.00 <i>B</i>	2,402.00 ✓
2 Bootlid weatherstrip	1	325.00 <i>B</i>	325.00 x
3 Bootlid lock	1	295.00 <i>B</i>	295.00 x
4 Bootlid centre logo	1	55.00 <i>B</i>	55.00 —
5 Bootlid 'E200' emblem	1	94.00 <i>B</i>	94.00 —
6 Bootlid '9G-TRONIC' emblem	1	120.00 <i>B</i>	120.00 —
7 Bootlid trimboard clips	<i>NEW</i> 10	<i>SN</i> 10.00 <i>30</i>	100.00 ✓
8 Bootlid centre chrome	1	145.00 <i>B</i>	145.00 x
9 Rear bumper	1	1,530.00 <i>B</i>	1,530.00 —
10 Rear bumper reinforcement	1	<i>R</i> 835.00	835.00 x
11 Rear bumper sensor	2	188.00 <i>B</i>	376.00 x
12 Rear bumper sensor seals	6	<i>NN</i> 12.00	72.00 x
13 Rear bumper clips	15	9.00 <i>B</i>	135.00 —
			6,484.00
		Less 10%	648.40
			5,835.60
SPECIAL NET			
14 Bootlid 'C & C' emblem	1	38.00 <i>B</i>	38.00 —
			38.00
LABOUR			
15 To transfer damaged bootlid interior mechanism to new bootlid	1	150.00	150.00 <i>601</i>
16 To remove and refit rear bumper sensor	1	100.00	100.00 <i>601</i>
17 To check and rectify wiring system	1	80.00	80.00 <i>201</i>
18 To remove and refit rear interior garnishes and trimboard to facilitates the repairs	1	120.00 <i>B</i>	120.00 x
19 To panel beat and straighten rear chassis frame, rear floor board panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 <i>5001</i>
20 To putty and spray paint on affected areas	1	1,200.00	1,200.00 <i>5001</i>
			2,650.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SLL6089A

CLAIM TYPE : THIRD PARTY

TP INS. CO. : SOMPO INSURANCE SINGAPORE PTE LTD

ACCIDENT DATE : 23/01/2020

TP VEH REG NO : SLL6089A

ESTIMATE

NO : QUOT202003-000037(00)

DATE : 12/03/2020

POLICY NO : 999995580

VEH REG NO : SMA9737P

MAKE/MODEL : MERCEDES BENZ E200
EXCLUSIVE (R18 LED)

CHASSIS NO : WDD2130422A454779

ENGINE NO : 27492031463962

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SMA9737P

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
		TOTAL	S\$ 8,523.60
		ADD GST @ 7%	596.65
		GRAND TOTAL	<u>S\$ 9,120.25</u>

SINGAPORE DOLLAR NINE THOUSAND ONE HUNDRED TWENTY AND CENTS TWENTY-FIVE ONLY

9071 60

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX : *Not with*

ATTN : ACCOUNTS DEPT

YOUR REF NO : SLL6089A

CLAIM TYPE : THIRD PARTY

TP INS. CO. : SOMPO INSURANCE SINGAPORE PTE LTD

ACCIDENT DATE : 23/01/2020

TP VEH REG NO : SLL6089A

Referring to 16/3/2020

85659.40

ESTIMATE

NO : QUOT202003-000037(00)

DATE : 12/03/2020

POLICY NO : 999995580

VEH REG NO : SMA9737P

MAKE/MODEL : MERCEDES BENZ E200
EXCLUSIVE (R18 LED)

CHASSIS NO : WDD2130422A454779

ENGINE NO : 27492031463962

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SMA9737P

Description	Quantity	Unit Price	Amount
LIST PRICE		SS	SS
1 Bootlid	1	2,402.00	2,402.00 ✓
-2 Bootlid weatherstrip	1	325.00	325.00 X
-3 Bootlid lock	1	295.00	295.00 X
4 Bootlid centre logo	1	55.00	55.00 -
5 Bootlid 'E200' emblem	1	94.00	94.00 -
6 Bootlid '9G-TRONIC' emblem	1	120.00	120.00 -
7 Bootlid trimboard clips <i>necessary</i>	<i>10</i>	<i>SN</i> 10.00	<i>30</i> 100.00 ✓
-8 Bootlid centre chrome	1	145.00	145.00 X
9 Rear bumper	1	1,530.00	1,530.00 -
-10 Rear bumper reinforcement	1	835.00	835.00 X
-11 Rear bumper sensor	2	186.00	376.00 X
-12 Rear bumper sensor seals	6	12.00	72.00 X
13 Rear bumper clips	15	9.00	135.00 -
			6,484.00
		Less 10%	648.40
			5,835.60
SPECIAL NET			
14 Bootlid 'C & C' emblem	1	38.00	38.00 -
			38.00
LABOUR			
15 To transfer damaged bootlid interior mechanism to new bootlid	1	150.00	150.00 601
16 To remove and refit rear bumper sensor	1	100.00	100.00 601
17 To check and rectify wiring system	1	80.00	80.00 201
18 To remove and refit rear interior garnishes and trimboard to facilitates the repairs	1	120.00	120.00 X 601
19 To panel beat and straighten rear chassis frame, rear floor board panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 5001
20 To putty and spray paint on affected areas	1	1,200.00	1,200.00 5001
			2,650.00 1200



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :
ATTN : ACCOUNTS DEPT

YOUR REF NO : SLL6089A
CLAIM TYPE : THIRD PARTY
TP INS. CO. : SOMPO INSURANCE SINGAPORE PTE LTD
ACCIDENT DATE : 23/01/2020
TP VEH REG NO : SLL6089A

ESTIMATE

NO : QUOT202003-000037(00)
DATE : 12/03/2020
POLICY NO : 999995580
VEH REG NO : SMA9737P
MAKE/MODEL : MERCEDES BENZ E200
EXCLUSIVE (R18 LED)
CHASSIS NO : WDD2130422A454779
ENGINE NO : 27492031463962
REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SMA9737P

Description	Quantity	Unit Price	Amount
		S\$	S\$
		TOTAL	S\$ 8,523.60
		ADD GST @ 7%	596.65
		GRAND TOTAL	S\$ 9,120.25

SINGAPORE DOLLAR NINE THOUSAND ONE HUNDRED TWENTY AND CENTS TWENTY-FIVE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SLL6089A

CLAIM TYPE : THIRD PARTY

TP INS. CO. : SOMPO INSURANCE SINGAPORE PTE LTD

ACCIDENT DATE : 23/01/2020

TP VEH REG NO : SLL6089A

ESTIMATE

NO : QUOT202003-000037(00)

DATE : 12/03/2020

POLICY NO : 999995580

VEH REG NO : SMA9737P

MAKE/MODEL : MERCEDES BENZ E200
EXCLUSIVE (R18 LED)

CHASSIS NO : WDD2130422A454779

ENGINE NO : 27492031463962

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SMA9737P

Description	Quantity	Unit Price	Amount
SUPPLEMENTARY LIST PRICE		S\$	S\$
1 Rear bumper lower spoiler	1	285.00 <i>nd</i>	285.00 ✓
2 Rear bumper lower chrome	1	325.00 <i>cm</i>	325.00 ✓
			610.00
		Less 10%	61.00
			549.00
		TOTAL	S\$ 549.00
		ADD GST @ 7%	38.43
		GRAND TOTAL	S\$ 587.43

SINGAPORE DOLLAR FIVE HUNDRED EIGHTY-SEVEN AND CENTS FORTY-THREE ONLY

parts : \$ 4,451.40

S/N : \$ 68.00

Labour : \$ 1,200.00

\$ 5,719.40 5659.40

+ 7% 400.36

\$ 6,119.76

FOR TONG LUCK AUTO PTE LTD

Uecking
AUTHORISED SIGNATURE




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20004030/Kyf3e2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 26-03-2020		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLL 6089A	Veh. Inspected	SMA 9737P	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2000408/LOR	Excess (\$)	0.00	
Assign From	IRENE HENRY	Assign Date	13/03/2020	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E200 (A)	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WDD2130422A454779	Colour	METALLIC SILVER	
Odometer	73935	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45 R18	GOODYEAR	8 mm	
L/H Front Tyre	245/45 R18	GOODYEAR	8 mm	
R/H Rear Tyre	275/40 R18	GOODYEAR	8 mm	
L/H Rear Tyre	275/40 R18	GOODYEAR	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/01/2020	Inspection Date	16/03/2020	
Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 9737P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID	BENT	2,402.00	2,402.00
1	BOOTLID WEATHERSTRIP	SERVICEABLE	325.00	-
1	BOOTLID LOCK	TO REPAIR SEE LABOUR	295.00	-
1	BOOTLID CENTRE LOGO	NECESSARY	55.00	55.00
1	BOOTLID 'E200' EMBLEM	NECESSARY	94.00	94.00
1	BOOTLID '9G-TRONIC' EMBLEM	NECESSARY	120.00	120.00
1	BOOTLID CENTRE CHROME	SERVICEABLE	145.00	-
1	REAR BUMPER	BUCKLED	1,530.00	1,530.00
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	835.00	-
2	REAR BUMPER SENSOR @\$188.00	SERVICEABLE	376.00	-
6	REAR BUMPER SENSOR SEALS @\$12.00	NOT NECESSARY	72.00	-
15	REAR BUMPER CLIPS @\$9.00	NECESSARY	135.00	135.00
1	REAR BUMPER LOWER SPOILER	DENTED	285.00	285.00
1	REAR BUMPER LOWER CHROME	CRACKED	325.00	325.00
	LESS 10% DISCOUNT		-699.40	-494.60
			6,294.60	4,451.40
10	BOOTLID TRIMBOARD CLIPS @\$10.00 (SN)	NECESSARY	100.00	30.00
	LESS 10% DISCOUNT		-10.00	-
			90.00	30.00
SPECIAL NETT ITEMS				
1	BOOTLID 'C&C' EMBLEM (SN)	NECESSARY	38.00	38.00
			38.00	38.00
LABOUR				
	TO TRANSFER DAMAGED BOOTLID INTERIOR MECHANISM TO NEW BOOTLID.		150.00	60.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		100.00	60.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	20.00

Report Ref No. CS/SMO20004030/Kyf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT REAR INTERIOR GARNISHES AND TRIMBOARD TO FACILITATES THE REPAIRS.	NOT NECESSARY	120.00	-
	TO PANEL BEAT AND STRAIGHTEN REAR CHASSIS FRAME, REAR FLOOR BOARD PANEL, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME. INCLUSIVE OF THE REPAIR OF BOOTLID LOCK AND REAR BUMPER REINFORCEMENT.		1,000.00	500.00
	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS.		1,200.00	500.00
			2,650.00	1,140.00
GRAND TOTAL			9,072.60	5,659.40
RECOMMENDED COST OF REPAIRS				5,659.40

Report Ref No. CS/SMO20004030/Kyf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.