





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 20/03/2020

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB5894P
Case Reference Number	BUS/03/20/1027
Registration Date	23/11/2015
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95
Name of Driver	Soo Teck Lie
Type of Accident	Head to Rear
Accident Date and Time	12/3/2020 9:06 AM
Accident Reported Date and Time	12/3/2020 11:45 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24106145
Special Instruction to ARC,if any	SMB5894P-FRONT RIGHT PORTION FBE758Y (TP) INSURED WITH NTUC
Prepared Date and Time	12/3/2020 6:16 PM
Chassis Number	WMAA95ZZXG7003050
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$530.00
Total Spray Cost	\$878.00	\$786.00
Total Spare Part Cost	\$120.00	\$120.00
Total Other Cost	\$0.00	(\$263.20)
TOTAL COST	\$2,058.00	\$1,172.80
Lump Sum Total	\$2,050.00	\$1,150.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Boon Chew Tay	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	13/03/2020 10:31 AM	13/03/2020 4:15 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 20/03/2020

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$1,060.00				\$530.00		
Total Labour			\$1,060.00				\$530.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$878.00				\$786.00		
Total Spray Painting & Panel Beating			\$878.00				\$786.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Lump Sum Adjustment by Surveyor			\$0.00				(\$263.20)		
Total Other Costs			\$0.00				(\$263.20)		
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			NUMBER PLATE	1.00	\$75.00	0.00	\$75.00	Replace	Replace
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	Replace
		F01001-CW263	FRONT FLAP	1.00	\$1,625.00	100.00	\$0.00	Repair	Repair
			FRONT HEADLAMP PANEL RH	1.00	\$847.50	100.00	\$0.00	Repair	Repair
	INTERIOR		FRONT DOME	1.00	\$2,500.00	100.00	\$0.00	Repair	Repair
Total					\$5,122.50		\$150.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									