

# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

DATE: 13-Mar-20

INSURANCE: First Capital

MODEL: HYUNDAI IONIC

VEHICLE NO.: SH9922M

Description	Qty	List Price	Amount
Front Fender(LH) <i>Painted</i> <i>Photo</i>	1	\$ 490.70	\$ 490.70
Front Fender Retainer <i>NH</i>	1	\$ 41.40	\$ 41.40
Frt Door(LH) <i>Enc</i>	1	\$ 1,797.20	\$ 1,797.20
Frt Door Rubber <i>SVC</i>	1	\$ 250.00	\$ 250.00
Front Door Gear / Regulator ( LH) <i>not money broken</i>	1	\$ 250.40	\$ 250.40
Front Door Hinge Upper (LH) <i>NH</i>	1	\$ 65.76	\$ 65.76
Front Door Hinge Lower (LH) <i>NH</i>	1	\$ 65.76	\$ 65.76
Front Door Check (LH) <i>NH</i>	1	\$ 72.98	\$ 72.98
Front Door Inner Lock (LH) <i>NH</i>	1	\$ 285.60	\$ 285.60
Front Door Outer Handle (LH) <i>cut</i>	1	\$ 198.60	\$ 198.60
Front Door Power Motor, LH <i>NH</i>	1	\$ 289.20	\$ 289.20
Front Door Trim Board (LH) <i>not money broken</i>	1	\$ 796.80	\$ 796.80
Front Door Protector(LH) <i>cut</i> <i>1st</i>	1	\$ 116.20	\$ 116.20
Rear Door (LH) <i>Enc</i>	1	\$ 1,789.90	\$ 1,789.90
Rear Door Rubber(LH) <i>SVC</i>	1	\$ 270.00	\$ 270.00
Rear Door Outer Handle (LH) <i>NH</i>	1	\$ 124.80	\$ 124.80
Rear Door Gear/Regulator(LH) <i>not money broken</i>	1	\$ 367.84	\$ 367.84
Rear Door Power Motor (LH) <i>NH</i>	1	\$ 256.80	\$ 256.80
Rear Door Lock Assy <i>NH</i>	1	\$ 306.40	\$ 306.40
Rear Door Hinge Upper (LH) <i>NH</i>	1	\$ 73.88	\$ 73.88
Rear Door Hinge Lower (LH) <i>NH</i>	1	\$ 73.88	\$ 73.88
Rear Door Check(LH) <i>NH</i>	1	\$ 85.92	\$ 85.92
Rear Door Trim Board (LH) <i>not money broken</i>	1	\$ 613.60	\$ 613.60
Door Centre Pillar Outer (LH) <i>Painted</i>	1	\$ 3,764.90	\$ 3,764.90
Rear Bumper <i>repair cut</i> <i>money crack</i>	1	\$ 459.40	\$ 459.40
Rear Bumper Stay <i>NH</i>	1	\$ 138.10	\$ 138.10
Rear Bumper Side Bracket (LH) <i>NH</i>	1	\$ 55.80	\$ 55.80
Rear Bumper Cover Clips <i>absent</i> <i>Nec</i>	1	\$ 22.00	\$ 22.00
Rear Bumper Side Under(LH) <i>NH</i>	1	\$ 33.10	\$ 33.10
Rear Fender(LH) <i>tova</i> <i>Painted</i>	1	\$ 1,768.30	\$ 1,768.30
Rear Tyre Rim (LH) <i>not 1st</i>	1	\$ 1,124.20	\$ 1,124.20
Rear Wheel Hup-Cap (LH) <i>cut</i>	1	\$ 346.40	\$ 346.40
Rear Wheelbearing ING & Hub <i>to Dore</i>	1	\$ 454.00	\$ 454.00
Rear Trailing Arm(LH) <i>not disturbed</i>	1	\$ 265.40	\$ 265.40
Rear Assist (LH) <i>not disturbed</i>	1	\$ 227.90	\$ 227.90
Rear shock Absorber(LH) <i>not disturbed</i>	1	\$ 230.50	\$ 230.50
Rear Shock Absorber Mounting (LH) <i>NH</i>	1	\$ 133.10	\$ 133.10
Rear Absorber stopper (LH) <i>NH</i>	1	\$ 137.60	\$ 137.60
Rear Absorber Cover (LH) <i>NH</i>	1	\$ 175.60	\$ 175.60
Rear Crossmember <i>NH</i>	1	\$ 1,468.70	\$ 1,468.70
Stabilizer Bar <i>NH</i>	1	\$ 387.30	\$ 387.30
Stabilizer Link <i>NH</i>	1	\$ 147.30	\$ 147.30

Rear Upper Arm(LH) <del>dist</del> <i>dist</i>	1	\$ 239.50	\$ 239.50	
Rear Lower Arm(LH) <del>dist</del> <i>dist</i>	1	\$ 393.10	\$ 393.10	
Rear Knuckle Arm (LH) <del>dist</del> <i>dist</i>	1	\$ 538.10	\$ 538.10	
16397.74			<b>SUB TOTAL</b>	\$ 21,193.92
			<b>LESS 20%</b>	\$ 4,238.78
13118.19			<b>DISCOUNTED TOTAL</b>	\$ 16,955.14
Emblem-Blue Drive (LH) <i>hcc</i>	List SN	1	\$ 26.60	\$ 26.60
Front Door Comfort Logo (LH) <i>hcc</i>	SN	1	\$ 75.00	\$ 75.00
Rear Door Protector(LH) <i>cut kit</i>	List SN	1	\$ 116.20	\$ 116.20
Rear Door Tel No.Sticker(LH) <i>hcc HS</i>	SN	1	\$ 10.00	\$ 10.00
Rear Door Comfortdelgro & Apps Sticker(LH) <i>hcc</i>	SN	1	\$ 80.00	\$ 80.00
Rear Tyre(LH) <i>hcc</i>	SN	1	\$ 216.00	\$ 216.00
155.00			<b>SUB TOTAL</b>	\$ 523.80
<b>Labour Charge</b>				
Panel Beating		1	\$1,800.00	\$1,800.00
Spray Painting Charge		1	\$1,600.00	\$1,600.00
Wiring Charge	LKK Auto Consultants hence notify the Repairer of the following:	1	\$120.00	\$120.00
Tuff Kote	• To resurvey before/after spray painting	1	\$160.00	\$160.00
Towing Charge	• To display damaged panels during surveys	1	\$80.00	\$80.00
Remove/Refix Reverse Sensor	• Parts prices are subject to change	1	\$120.00	\$120.00
Remove/Refix Undercarriage (RR)	• Third party survey is on a "final approved basis"	1	\$400.00	\$400.00
Re-set Rear ABS System	• No illegal modifications is allowed	1	\$400.00	\$400.00
Remove/Refix Fuel Tank	• Supplementary items must be received and is subject to final approval from insurance company	1	\$80.00	\$80.00
Remove/Refix Exhaust Pipe	Acknowledged by Repairer	1	\$80.00	\$80.00
Transfer of Door Mechanism FRONT	Signature:	1	\$80.00	\$80.00
Re-set Frt Power Window System	Date:	1	\$200.00	\$200.00
Transfer of Door Mechanism REAR		1	\$80.00	\$80.00
Re-set Rear Power Window System	2550.00	1	\$200.00	\$200.00
Four Wheel Alignment		1	\$120.00	\$120.00
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00
<b>TOTAL LABOUR</b>				\$6,070.00
<b>ESTIMATE TOTAL</b>				\$ 23,548.94
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared				

16/03/2020 e 1700h

NA Antena

2 Panel 9 days.

Man

LKK Auto

15823.19

Supp 699.04

16522.23

1/3 13000/-

