

11/03/2001

ASS. REC. BY:

REF: CS/CTI 20004051/ Uq-f3

Special Instruction:

SURVEYOR: WAT/US

ASSIGNMENT (Office)

From (Person): Pauline Thomof CTIDate/Time: 16/2/20 15:00 PM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMA 86028Insured: SLV 5543Jat Workshop m/s Automobil HubTel: 9786 4483of 1 KAK Bukit N 15 11 2-11 AutobayPolicy No: PNPCCSNA 00000622000Claim No: SVM 2012201308

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 10.3.2018

CA / REV / REP. / REV 24 HRS

H.O.D Endorsement:

Date/Time: 16.2.20 3:47 PMPerson Contacted: Ah SangVehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMA 86028 X
	SLV 5543J - YAT 186 20.6.2024 DPA 2104/2024

(08/11/13) wed

ASS. REC. BY: *MARUS*

REF:

CTI / POST / U / F3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SMA8602B*
 at Workshop m/s *Autobank*
 of _____

Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: *2* days Res.: Yes or NoLum Sum: *2* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 34700

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *SMA8602B* Yr Regn: *618*
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *CA*Make: *Honda Shuttle* c.c. *1496*Colour: *Silver* A/C: Insured / Std / NI / NASp Reading: *39826* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *GK81202016*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: *Nil* / S/Rim / STD A/Rim orTyre Size: F: *H5 / 60215*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. *6* mm R/Bal. *6* mmL/Bal. *6* mm L/Bal. *6* mmD.O.A. D.O.I. *27/3/20*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rep.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

30/3/20 1/5 \$2400 Confirmed with OH X-ray (Ref \$9447, 80%).

RECEIVED 31 MAR 2020

Date/Time, File Pass to?

☐ : Preli. Report1) *31/3 11:55 AM*☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: *2*Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

)

TOTAL

*220*Report Format: *MEX-TP*Lump Sum / I.B.I. (\$) *2400*Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Mar 2020		16 Mar 2020 15:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

LIAUW CHIANG SIOE

Main Claimant:

TAY GUAN MING, ID: S8818427J

Vehicle Reg. No.:

SMA8602B

Date of Loss:

10/03/2020 00:00 - :59

Claim Type:

TP / SNM20D201308

Policy/Cover Note No.:

DMPCSNAD0000622000 (Comprehensive)

Vehicle Reg. No. (Insured):

SLV5543J

Policy No. (Claimant):

Excess:

S\$0.00

Repairer:

Automobile Hub Enterprise () 1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Pauline Tham]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/03/2020]

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Pauline Tham <pauline.tham@sg.cntaiping.com>
Sent: Monday, 16 March 2020 3:08 PM
To: alfred_ng@juseq.com.sg
Cc: Claims Dept of CTI; sur@lkkauto.com; assignments@lkkauto.com; admin-a@lkkauto.com
Subject: RE: ACCIDENT INVOLVING SMA8602B AND SLV5543J AT 601 RIFLE RING ROAD OPEN SPACE CARPARK ON 10 MARCH 2020., ORef : SNM20D201308

Importance: High

Without Prejudice

Dear Alfred,

Thanks for the reply.

Dear LKK

Please take note of PRS.

Thanks.

Pauline Tham
Senior Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6541 | F: (65) 6224 7175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

From: alfred_ng@juseq.com.sg <alfred_ng@juseq.com.sg>
Sent: Monday, March 16, 2020 2:56 PM
To: Pauline Tham <pauline.tham@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: ACCIDENT INVOLVING SMA8602B AND SLV5543J AT 601 RIFLE RING ROAD OPEN SPACE CARPARK ON 10 MARCH 2020.

Your ref: SNM20D201308
Our ref: JEQ/SMA8602B/AHE

Dear Pauline,

We refer to your email today.

Our client is agreeable to appoint the following surveyor as our single joint expert.

Mr. Marcus Chua

Please be informed that our client's vehicle is available for inspection at the under stated workshop:-

AUTOMOBILE HUB ENTERPRISE
1 Kaki Bukit Ave 6
#02-11, Autobay @Kaki Bukit
Singapore 417883
Person In Charge: Ah Siong Hp:9786-4483

With Regards

Alfred Ng
Executive
Legal Division
On behalf of Mr. Michael Yap
M/s JusEquity Law Corporation
No. 133 New Bridge Road
Chinatown Point
#10-03 Singapore 059413
Tel : 6536 9339
Fax: 6536 5368

IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

New Car Reviews by Experts

Getting a new car soon? Find out more before you buy today!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an AdAdvertiser LoginWays of Selling

2010 Golf Sport 158hp, Twincharge.



Low Mileage, Flawless Owner.
Direct Owner - StarAd



Browse by Category

Sort by Date Posted20 results/page

19 vehicles

Honda Shuttle

Advanced SearchSubmit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Shuttle	Any	Any	2018	Any	Any	Any	Available
	Honda Shuttle Hybrid 1.5A Fuel Type: Petrol-Electric Elegant Black, Low Fuel Consumption With Hybrid, Powerful Drive With 135 BHP, One Owner Only, Low Maintenance Cost, Very Well Ma... Prime Motor & Leasing Posted: 25-Mar-2020Tags: 2018 Honda Shuttle, Honda Shuttle, Honda, Shuttle	\$73,800	\$8,690 /yr	28-May-2018	1,496 cc	-	Stationwagon	Available
	Honda Shuttle 1.5A G 1 Owner, LED Headlight Model. Perfect Condition. High Loan Available. Trade-In Welcome. Please Call Now To Have A Ride. Before It's... Posted: 25-Mar-2020Tags: 2018 Honda Shuttle, Honda Shuttle, Honda, Shuttle	\$70,800	\$8,080 /yr	14-Jun-2018	1,496 cc	14,000 km	Stationwagon	Available
	Honda Shuttle 1.5A G Low Depreciation At \$21 Per Day! Monthly Repayment \$769. 1 Owner, Under Utilised, Mileage Done Only 8,800km, Accident Free, Ongi... Horizon Motoring Posted: 25-Mar-2020Tags: 2018 Honda Shuttle, Honda Shuttle, Honda, Shuttle	\$67,800	\$7,780 /yr	20-Jun-2018	1,496 cc	9,000 km	Stationwagon	Available
	Honda Shuttle Hybrid 1.5A Fuel Type: Petrol-Electric Full Loan Available, 1 Owner, Elegant Silver, Low Fuel Consumption With Hybrid, Powerful Drive With 135Bhp, Easy To Maintenance, Ver... 1axis Posted: 25-Mar-2020Tags: 2018 Honda Shuttle, Honda Shuttle, Honda, Shuttle	\$73,800	\$8,700 /yr	05-Jun-2018	1,496 cc	23,256 km	Stationwagon	Available
	Edwin Garage - Specialist for Honda Car repair, servicing & maintenance Edwin Garage Present to you the strongest team in car aircon, Japanese/ Korean car make and continental cars engine specialist. More info about this shop							
	Honda Shuttle Hybrid 1.5A Fuel Type: Petrol-Electric Elegant Red, Low Fuel Consumption With Hybrid, Powerful Drive With 135Bhp, One Owner Only, Low Maintenance Cost, Very Well Maint... Prime Motor & Leasing Posted: 21-Mar-2020Tags: 2018 Honda Shuttle, Honda Shuttle, Honda, Shuttle	\$71,500	\$8,800 /yr	11-Jan-2018	1,496 cc	-	Stationwagon	Available
	Honda Shuttle Hybrid 1.5A Fuel Type: Petrol-Electric 1 Owner Only! Drive Away With 2 Years Complimentary Warranty For Peace Of Mind! Auspicious Number Plate X888! Selling At The Sam... Posted: 21-Mar-2020Tags: 2018 Honda Shuttle, Honda Shuttle, Honda, Shuttle	\$77,800	\$8,460 /yr	04-Oct-2018	1,496 cc	19,000 km	Stationwagon	Available
Compare	Honda Shuttle 1.5A G	\$67,800	\$7,630 /yr	25-May-2018	1,496 cc	35,087 km	Stationwagon	Available

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 427J

Vehicle Details

Vehicle No.: SMA8602B

Vehicle to be Exported: No

Intended Deregistration Date: 27 Mar 2020

Vehicle Make: HONDA

Vehicle Model: SHUTTLE 1.5G CVT

Primary Colour: Silver

Manufacturing Year: 2018

Engine No.: L15B5462360

Chassis No.: GK81202016

Maximum Power Output: 97.0 kW (130 bhp)

Open Market Value: \$18,825.00

Original Registration Date: 21 Jun 2018

First Registration Date: 21 Jun 2018

Transfer Count: 0

Actual ARF Paid: \$8,825.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 20 Jun 2028

PARF Rebate Amount: \$6,618.00

Intended COE Rebate Details

COE Expiry Date: 20 Jun 2028

COE Category: E - Open - all except motorcycle

COE Period(Years): 10

QP Paid: \$34,400.00

COE Rebate Amount: \$28,082.00

Total Rebate Amount: \$34,700.00

The information contained herein is correct as at 27 Mar 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/03/2020 16:05
Date Of Accident	10/03/2020 13:30
Exact Location Of Accident	BLK 601 RIFLE RINGE RD OPEN SPACE CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA8602B
Insured/Policyholder	
Name Of Registered Owner	TAY GUAN MING
NRIC No	SXXXX427J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92721406
Alternative Phone No	OFFICE-92721406

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE 1.5G CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5101455613-01
Cover Note Number	

Driver

Name of Driver	TAY GUAN MING
NRIC No	SXXXX427J
Date Of Birth	30/05/1988
Occupation	INDOOR
Date Of Driving Pass	18/04/2008
Driving Experience	11 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92721406
Fax Number	
Contact Number	OFFICE-92721406
Email Address	NOEMAIL

Address	BLK 278A COMPASSVALE BOW #08-545
Postcode	541278
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	KAKI BUKIT NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 526 BEDOK NORTH STREET 3 #01-448 , POSTCODE: 460526 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4429999 - FAX NO: 62444377
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20200313/2096.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV5543J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	


Accident Sketch Plan

SKETCH PLAN

Sketch of accident scene on grid paper.


Vehicle A: JMA8602B
Vehicle B: J6V5543

Handwritten notes: Kik Gw Ringe Ronge Rd, uph. space car park



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Refer to police report - 7/2003/246.




DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Police Report



**SINGAPORE
POLICE FORCE**



T/20200313/2096

Police Station Of Origin:
Kaki Bukit NPP
526 Bedok North Street 3 #01-448
SINGAPORE 460526
Tel No: 1800-4429999

1 of 3

Report No. T/20200313/2096

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/03/2020 15:19		Vide Report No.:		Station Diary No.: 29	
Informant's Particulars					
Name of Informant: TAY GUAN MING			Address: APT BLK 278A COMPASSVALE BOW #08-545 SINGAPORE 541278		
ID Type / ID No.: NRIC NO / S8818427J			Contact No.: Home/Office: Mobile: 92721406		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 31	Date of Birth: 30/05/1988	Type of Informant: Vehicle Owner		
Race: Chinese			Language: English		Institution / School Name:
Occupation: SENIOR TECHNICIAN			Driving Licence Information: Class: 2B,3,4,5 Date of Expiry:		

General Information of the Accident					
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 10/03/2020 13:30	Type of Location: Car Park	
Location: Along Road 1 RIFLE RANGE ROAD OPENSOURCE CARPARK INFRONT OF 601 RIFLE RANGE ROAD					
Weather: Clear		Road Surface: Dry		Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passengers
SLV5543J	Car	BENTLEY		Grey	No Damage	0
SMA8602B	Car	HONDA	SHUTTLE	Grey	Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Report



**SINGAPORE
POLICE FORCE**



T/20200313/2096

Police Station Of Origin:
Kaki Bukit NPP
526 Bedok North Street 3 #01-44B
SINGAPORE 480526
Tel No: 1800-4429999

2 of 3

Report No. T/20200313/2096

CONTINUATION OF REPORT

Vehicle Owner			
Name	TAY GUAN MING		ID No. S8818427J
Related Vehicle	SMA8602B (Car)		Contact No. 92721406
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 2B,3,4,5 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL


Brief Details.

On the 13/03/2020, at about 0650hrs, I discovered some scratches on the front left portion of my vehicle's bumper. I then went to retrieve my in-car camera recordings and discovered that on the 10/03/2020, at about 1330hrs, there was a Grey Bentley, bearing registration no. SLV5543J, that side swiped my vehicle whilst exiting from a parking lot. The driver did not stop and leave down her particulars, and drove off. The entire incident was captured by my in-car camera.

Police Report



**SINGAPORE
POLICE FORCE**



T/20200313/2096

Police Station Of Origin:
Kaki Bukit NPP
526 Bedok North Street 3 #01-448
SINGAPORE 460526
Tel No: 1800-4429999

3 of 3

Report No. T/20200313/2096

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Staff Sgt SHAWN YUEN CHI WENG

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

13/03/2020 15:19

Officer In Charge Of Case:

TP / HRT /

SI NOR AFFENDY BIN JAFFAR

Contact No.: 65476368

Classification Of Case:

Authentication Stamp

NP168

Repair Estimate

Automobile Hub Enterprise


1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883
Tel: (65) 9786 4483 Fax: (65) 6509 6584 Email: autohub325@gmail.com

Make/Model: HONDA SHUTTLE
Engine/Chassis No.: GK81202016
Date of accident:
Damaged area: N/S Front

Date: 14/03/2020

Claim Type: TP

VRN: SMA86028



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Bonnet	1	\$ 1,379.00	\$ 1,379.00
2	Bonnet insulator	1	\$ 238.00	\$ 238.00
3	Bonnet hinge	2	\$ 84.00	\$ 168.00
4	Front Bumper	1	\$ 1,135.00	\$ 1,135.00
5	Front Bumper side retainer	2	\$ 65.00	\$ 130.00
6	Front Bumper impact absorber	1	\$ 180.00	\$ 180.00
7	Front Bumper reinforcement	1	\$ 650.00	\$ 650.00
8	Radiator grille	1	\$ 587.00	\$ 587.00
9	Radiator grille "HONDA" emblem	1	\$ 160.00	\$ 160.00
10	Radiator grille chrome garnish	1	\$ 280.00	\$ 280.00
11	Front Bumper centre lower grille	1	\$ 475.00	\$ 475.00
12	Support panel	1	\$ 498.00	\$ 498.00
13	Headlamp support n/s	1	\$ 369.00	\$ 369.00
14	Headlamp n/s	1	\$ 2,942.00	\$ 2,942.00
15	Front foglamp n/s	1	\$ 655.00	\$ 655.00
16	Front foglamp garnish n/s	1	\$ 448.00	\$ 448.00
17	Front fender n/s	1	\$ 918.00	\$ 918.00
18	Front fender inner cowling n/s	1	\$ 238.00	\$ 238.00
Subtotal				\$ 11,450.00
List discount				20.00%
Total				\$ 9,160.00

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Bonnet insulator clips	6	\$ 6.50	\$ 39.00
2	Front Bumper clips	10	\$ 6.50	\$ 65.00
3	Front support top panel garnish clips	4	\$ 6.50	\$ 26.00
4	Front fender inner cowling n/s clips	8	\$ 6.50	\$ 52.00
5	Front licence plate & frame	1	\$ 55.00	\$ 55.00
6	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 287.00

Not Approved
L/S \$ 2400
2 days
Take full charge

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.5	\$ 100.00
3	Supply spray paint material and necessary items to respray front bumper, bonnet, n/s front fender and other affected area / panel.	5	\$ 1,000.00
4	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 2,400.00
Estimate Grand Total			\$ 11,847.00

$$\begin{array}{r} 9-3155-60 \\ 207 \\ \hline 9-2524-48 \\ 1-240-00 \\ 4-470-00 \\ \hline 3034-48 \\ 2427- \end{array}$$

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20004051/UQF3N2
Date: 01/04/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00000622000
Claimant Vehicle No: SMA8602B Insured Vehicle No: SLV5543J
Date of Loss: 10/03/2020 Nature of Claim: TP Claim No: SNM20D201308

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMA8602B
Make & Model: HONDA SHUTTLE, 1.5 G CVT (A) Engine No: L15B5462360
Reg. Date: 21/06/2018 (Man. Year: 2018) Chassis No: GK81202016
Colour: Silver Odometer: 39826 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,447.00	2,564.48	6,882.52	72.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	470.00	1,930.00	80.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,847.00	3,034.48	8,812.52	74.39
Approved Total (Overridden) (S\$)		2,400.00		
Nett Amount (S\$)	11,847.00	2,400.00	9,447.00	79.74

INSPECTION

Date of Assignment: 16/03/2020
Date Inspected: 27/03/2020 Inspected At: Automobile Hub Enterprise
1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT
Singapore 417883
Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Apr 2020)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA8602B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	1,379.00 FL	*- FL
2	1		*BONNET INSULATOR	Not Necessary	238.00 FL	*- FL
3	2		*BONNET HINGE	Not Necessary	168.00 FL	*- FL
4	1		*FRONT BUMPER	Deep Cut	1,135.00 FL	*862.90 FL
5	1		*FRONT BUMPER SIDE RETAINER	N/s Bent	130.00 FL	*65.00 FL
6	1		*FRONT BUMPER IMPACT ABSORBER	Not Necessary	180.00 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	650.00 FL	*- FL
8	1		*RADIATOR GRILLE	Not Necessary	587.00 FL	*- FL
9	1		*RADIATOR GRILLE HONDA EMBLEM	Not Necessary	160.00 FL	*- FL
10	1		*RADIATOR GRILLE CHROME GARNISH	Not Necessary	280.00 FL	*- FL
11	1		*FRONT BUMPER CENTRE LOWER GRILLE	Not Necessary	475.00 FL	*- FL
12	1		*SUPPORT PANEL	Not Necessary	498.00 FL	*- FL
13	1		*HEADLAMP SUPPORT N/S	Not Necessary	369.00 FL	*- FL
14	1		*HEADLAMP N/S LED	Scratched	2,942.00 FL	*2,227.70 FL
15	1		*FRONT FOGLAMP N/S	Not Necessary	655.00 FL	*- FL
16	1		*FRONT FOGLAMP GARNISH N/S	Not Necessary	448.00 FL	*- FL
17	1		*FRONT FENDER N/S	Not Necessary	918.00 FL	*- FL
18	1		*FRONT FENDER INNER COWLING N/S	Not Necessary	238.00 FL	*- FL
19	6		*BONNET INSULATOR CLIPS	Not Necessary	39.00 FS	*- FS
20	10		*FRONT BUMPER CLIPS	Necessary	65.00 FS	*40.00 FS
21	4		*FRONT SUPPORT TOP PANEL GARNISH CLIPS	Not Necessary	26.00 FS	*- FS
22	8		*FRONT FENDER INNER COWLING N/S CLIPS	Not Necessary	52.00 FS	*- FS
23	1		*FRONT LICENCE PLATE & FRAME	Not Necessary	55.00 FS	*- FS
24	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,737.00	3,195.60
- List Item Discount on L Items 20.00/20.00% (S\$)	2,290.00	631.12

Total Parts (S\$)	9,447.00	2,564.48
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW ACCIDENT DAMAGED PORTIONS.TO PANEL BEAT,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,200.00	200.00
2	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS	New	100.00	20.00
3	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY FRONT BUMPER AND OTHER AFFECTED AREA/PANEL	New	1,000.00	250.00
4	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	0.00
Gross Labour Cost (S\$)			2,400.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >