

**Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre**

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

**Steve (LKK)
Without Prejudice
17/03/20, 1.00 pm
P/P
8 repair days
Resurvey before spray**

VEHICLE ESTIMATE

CHINA TAIPING

QUOTE NO :
ACCIDENT DATE 09/03/2020@1850HRS

ATTN: MOTOR CLAIMS DEPT

VRN : GBG9027D
MODEL : Nissan Cabstar
TP VRN : SMC9347X

PARTS REPLACEMENT

1. Body Repair

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
1 Front Bumper W Reinforcement ✓ CUT	1	\$ 945.10	\$ 945.10 ✓	
2 Front Bumper Clips ✓ NEC	10	\$ 15.00	\$ 150.00 40 ✓	
3 Front Bumper Bolt ✗ NN	2	\$ 25.00	\$ 50.00 ✗	
4 Front Centre Panel ✓ DD	1	\$ 1,412.70	\$ 1,412.70 ✓	
5 Front Radiator Grille ✓ CRU	1	\$ 438.70	\$ 438.70 ✓	
6 Front Radiator Grille Spacer ✓ NEC	1	\$ 45.00	\$ 45.00 35 ✓	
7 Centre Upper Finisher ✗ NN	1	\$ 450.40	\$ 450.40 ✗	
8 Upper Finisher LH/RH ✗ NN	2	\$ 28.90	\$ 57.80 ✗	
9 Front Fender Undercover LH/RH ✗ NN	2	\$ 287.90	\$ 575.80 ✗	
10 Front Protector Corner Panel LH/RH ✗ NN	2	\$ 85.90	\$ 171.80 ✗	3368.70
11 Front Corner Panel LH/RH ✗ NN	2	\$ 389.00	\$ 778.00 ✗	-30%
12 Rear Gate ✗ Repair	1	\$ 1,399.70	\$ 1,399.70 ✗	2358.09
13 Rear Body Side ✗ Repair	1	\$ 2,600.60	\$ 2,600.60 ✗	
14 Taillamp LH/RH ✓ BR/Cut	2	\$ 248.60	\$ 497.20 ✓	
15 Rear Reverse Sensor ✓ BR s/nett	1	\$ 295.00	\$ 295.00 200 ✓	
16 Front License Plate ✓ BT s/nett	1	\$ 45.00	\$ 45.00 35 ✓	235
List - 30%			\$ (2,826.72)	
TOTAL			\$ 6,935.68	

2. Labor Charges

1 Remove & repair & replace parts for the affected areas	\$ 1,200.00	1000
2 Spray paint on the affected areas	\$ 1,200.00	600
3 check wiring, re-align taillamps & ensure proper functioning	\$ 100.00	30
4 Remove & Refit Dashboard & related parts	\$ 200.00	150
5 Remove & reinstall 2 pieces of bumper sensors	\$ 150.00	30
Sub Total	\$ 2,850.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Grand Total : \$ 9,785.68 1810
Add 7% GST : \$ 685.00
Nett Total : \$ 10,470.68

No. of repair days: 14

Acknowledged by Repairer
Signature: _____
Date: _____

2358.09
235
1810
4403.09

**Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre**

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

SUPPLEMENTARY VEHICLE ESTIMATE

CHINA TAIPING

QUOTE NO :
ACCIDENT DATE 09/03/2020@1850HRS

ATTN: MOTOR CLAIMS DEPT

VRN : GBG9027D
MODEL : Nissan Cabstar
TP VRN : SMC9347X

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 Heater ✓ BR	1	\$ 1,800.30	\$ 1,800.30 ✓	
2 Wiper Arm RH ✓ SCR	1	\$ 115.20	\$ 115.20 ✓	
3 Side Mirror Small Cover RH ✓ MIS	1	\$ 35.30	\$ 35.30 ✓	2738
4 Headlamp LH/RH ✓ CRA	2	\$ 393.60	\$ 787.20 ✓	-30%
5. SANKYU sticker		Nett 85.60	85.60 ✓	1916.60
List - 30%			\$ (821.40)	85.60
				2002.20
			TOTAL	\$ 1,916.60
<u>2. Labor Charges</u>				
1 Remove & Replace Heater		Repeated item 4		\$ 200.00 ✕
			Sub Total :	\$ 200.00
			Grand Total :	\$ 2,116.60
			Add 7% GST :	\$ 148.16
			Nett Total :	\$ 2,264.76

No. of repair days: _____ 1

Main - 4403.09
Supp - 2002.20
6405.29

CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)