

D'Garage LLP

8 Burn Road #09-16 Singapore 369977
HP: 9144 4556 Email: dgaragellp@gmail.com
Business Registration No: T16LL0019J

Not Wholesaler ESTIMATE

Date: 16/3/2020
DOA: 13/3/2020

6/Rep & ?

Running After Pain

3-4 days

Vehicle No: SKA5748H

Make & Model: Toyota Allion 1.5 A

S/N	Qty	Item Description	Parts Price	Surveyor
1	1	Rear Boot Lid	\$ 937.80	X
2	1	Rear Boot Lid Centre Logo	\$ 68.50	✓
3	1	Rear Boot Lid Lock Mechanism	\$ 272.70	X
4	1	Rear Boot Lid Lock Striker	\$ 52.50	X
5	1	Rear Boot Lid Weatherstrip	\$ 109.60	X
6	1	Rear L/H Tail Lamp	\$ 415.90	?
7	1	Rear L/H Tail Lamp Lower Retainer	\$ 67.70	?
8	1	Rear L/H Tail Lamp Base Panel	\$ 133.20	X
9	1	Rear L/H Tail Lamp Gasket	\$ 67.30	?
10	1	Rear End Panel	\$ 677.70	?
11	1	Rear End Panel Top Garnish	\$ 493.70	X
12	1	Rear Bumper	\$ 1,400.00	✓
13	2	Rear Bumper Bracket <i>old x</i>	\$ 101.10	
14	2	Rear Bumper Reflector <i>old x</i>	\$ 341.20	
15	2	Rear Bumper Side Retainer	\$ 212.80	✓
16	1	Rear Exhaust Assy	\$ 1,039.40	X
17	2	Rear Exhaust Mounting	\$ 69.90	X
	1	Rear Boot Lid "ALLION" Emblem	\$ 6,461.00	
	1	Less 25% "AIS" Emblem	\$ 1,615.25	
			\$ 4,845.75	
		<u>Special Nett Items</u>		
1		Sundries	\$ 50.00	X
2	1 set	Rear L/H Tail Lamp Clips	\$ 50.00	?
3	1	Rear L/H Tail Lamp Sealant	\$ 60.00	?
4	1	Rear L/H Tail Lamp Base Panel Sealant	\$ 60.00	X
5	1	Rear End Panel Sealant	\$ 120.00	?
6	1 set	Rear End Panel Top Garnish Clips	\$ 50.00	X
7	1 set	Rear Bumper Clips	\$ 50.00	✓
8	1	Rear Reverse Sensor	\$ 300.00	2000
			\$ 740.00	
		Total parts	\$ 5,585.75	
S/N	Labour Description		Amount	Amount
1	Labour for panel beating, cut, weld, straighten rear fenders and replace rear damaged parts.		\$ 1,200.00	?
2	To putty and spray painting rear portion.		\$ 1,000.00	600
3	To check rear lighting and wiring.		\$ 80.00	200
4	To remove and install rear boot lid lock mechanism.		\$ 120.00	X
5	To remove and install inner garnish and trim to facilitate the repair.		\$ 350.00	?
6	To apply anti rust proofing to rear affected area.		\$ 250.00	X
7	To remove and install rear reverse sensor.		\$ 150.00	500

	8	To remove & refit boot lid componenet to replace bootlid, check & re-adjust the close gap and alignment and water seepage	\$ ~ 60.00	X
		Total labour :	\$ 3,210.00	
		Total parts :	\$ 5,585.75	
		Total labour :	\$ 3,210.00	
		Total repair cost : (Before GST)	\$ 8,795.75	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: