



QUOTATION

NO. : 35822

Customer :

INDIA INTERNATIONAL INSURANCE P.L.
64 CECIL STREET
#04-00 & #06-00
IOB BUILDING
SINGAPORE 049711
INDIA INTERNATIONAL INSURANCE P.L.

DATE : 12/03/2020
CLAIM NO. : 11528
POLICY NO. : AVFMSB0000651901

FROM : HASRIANAH

VEHICLE NO. : FBN1758T
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BELLY PAN (lower cover) ✓ <i>scr</i> P/N: 58094	REPLACE	1.00	\$34.00	34.00
2	BOARD FOOTREST LH ✓ <i>scr</i> P/N: 59588	REPLACE	1.00	\$52.00	52.00
3	BOARD FOOTREST RH ✓ <i>scr</i> P/N: 59589	REPLACE	1.00	\$52.00	52.00
4	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220 ✓ <i>scr</i>	REPLACE	1.00	\$222.00	222.00
5	BRACKET BOX REAR (GIVI) P/N: 55428 ✓ <i>at</i>	REPLACE	1.00	\$62.00	62.00
6	COVER CLUTCH OUTER (holding cover outer) P/N: 58147 ✓ <i>scr</i>	REPLACE	1.00	\$28.00	28.00
7	COVER RADIATOR ✓ <i>scr</i> P/N: 63127	REPLACE	1.00	\$12.00	12.00
8	COVER SIDE CENTRE RH (WHITE) ✓ <i>scr</i> P/N: 58117	REPLACE	1.00	\$30.00	30.00
9	COVER SIDE REAR LH (WHITE) ✓ <i>scr</i> P/N: 58170	REPLACE	1.00	\$40.00	40.00
10	COVER SIDE REAR RH (WHITE) ✓ <i>scr</i> P/N: 58102	REPLACE	1.00	\$40.00	40.00
11	ENGINE BRACKET COMP ? <i>photo</i> P/N: 61969	REPLACE	1.00	\$70.00	70.00
12	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	6.00	\$63.00	378.00 <i>260</i>
13	LAMP SIGNAL FRONT LH ✓ <i>scr</i> P/N: 59587	REPLACE	1.00	\$35.00	35.00

*35822 *



S/N	Description	Action	Qty	Unit Price	Amount
14	LEVER BRAKE LH ✓ P/N: 58145	REPLACE	1.00	\$18.00	18.00
15	LEVER BRAKE RH ✓ P/N: 58185	REPLACE	1.00	\$18.00	18.00
16	MUDGUARD FRONT (WHITE) ✓ <i>scr</i> P/N: 58087	REPLACE	1.00	\$52.00	52.00
17	MUDGUARD REAR ✓ <i>scr</i> P/N: 63129	REPLACE	1.00	\$47.00	47.00
18	PIPE EXHAUST ASSY ✓ <i>BT</i> P/N: 58083	REPLACE	1.00	\$407.00	407.00
19	PROTECTOR EXHAUST ✓ <i>CR4</i> P/N: 58086	REPLACE	1.00	\$38.00	38.00
20	RIVET ✓ <i>new</i> P/N: 56583	REPLACE	7.00	\$2.00	14.00
21	SHAFT PIVOT (Bolt) ? <i>plus</i> P/N: 61967	REPLACE	1.00	\$12.00	12.00
22	SPRAY PAINT COVER SIDE REAR LH (Lacquer)	Spray	1.00	\$63.00	63.00
23	SPRAY PAINT COVER SIDE REAR RH (Lacquer)	Spray	1.00	\$63.00	63.00
24	SPRAY PAINT MUDGUARD FRONT (Lacquer)	Spray	1.00	\$49.00	49.00
25	STAND MAIN ✓ <i>scr</i> P/N: 58138	REPLACE	1.00	\$66.00	66.00
26	STICKER (CERTIS CISCO) SIDE REAR RH NEW MODEL ✓ <i>new</i> P/N: 61181	REPLACE	1.00	\$44.00	44.00
27	STICKER (CERTISCISCO) NEW LOGO ✓ <i>new</i> P/N: 60971	REPLACE	2.00	\$44.00	88.00
28	STICKER (CISCO) MUDGUARD FRONT ✓ <i>new</i> P/N: 58618	REPLACE	1.00	\$37.00	37.00
29	STICKER (CISCO) SIDE REAR LH NEW MODEL ✓ <i>new</i> P/N: 61573	REPLACE	1.00	\$15.00	15.00
30	STOPPER MAINSTAND ? <i>plus</i> P/N: 54930	REPLACE	1.00	\$17.00	17.00
31	STOPPER, MAIN STAND ? <i>plus</i> P/N: 61968	REPLACE	1.00	\$7.00	7.00
32	TRANSPORT CHARGES P/N: 07169 - FOR COLLECTION OF ACCIDENT BIKE AND DELIVER BIKE BACK TO BASE ONCE REPAIR DONE.		1.00	\$56.00	112.00 50
33	COVER SIDE CENTRE LH (WHITE) ✓ <i>scr</i> P/N: 58097	REPLACE	1.00	\$30.00	30.00
				SUB TOTAL	\$2,252.00
				GST @ 7 %	\$157.64

*35822 *



S/N	Description	Action	Qty	Unit Price	Amount
GRAND TOTAL					\$2,409.64

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



HASRIANAH

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*PIP repair
 without pre-judge -
 Resurvey before point
 check item (?)
 4 day 3.45pm
 16/3/20 Hock ANW (1/K/L)
 Hock ANW@lkkAuto.com
 853/1983 / 674/8934*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

*35822 *

