

Re: FBN 1758T FINALIZED CLOSE CASE.

Hock Ann (LKK Auto) <HockAnn@lkkauto.com>

Tue 5/19/2020 11:16 AM

To: raymond@bhh.com.sg <raymond@bhh.com.sg>

Cc: hasrianah@bhh.com.sg <hasrianah@bhh.com.sg>; Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Dear raymond , hasrianah,

Good day, o.k will be process base on finalized total amount COR \$1829.30 (non include GST 7%) PART&PART REPAIR and DOR 4 days close.

Noted : All finalized document > LOA ,LOD,DV,LTA and parts order invoice need direct send to lkk in charge person handler hsiao tong (chewht@lkkauto.com)

Thanks.

Best Regards,
Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: raymond@bhh.com.sg <raymond@bhh.com.sg>
Sent: Tuesday, May 19, 2020 10:51 AM
To: Hock Ann (LKK Auto) <HockAnn@lkkauto.com>
Cc: hasrianah@bhh.com.sg <hasrianah@bhh.com.sg>; Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: RE: FBN 1758T FINALIZED CLOSE CASE MARKING ESTIMATE.

Dear Hock Ann,

Noted with thanks

Best Regards,
Raymond
Ban Hock Hin Co., Pte Ltd
Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969
Visit us at <http://www.bhh.com.sg>
Facebook: <http://www.facebook.com/bhhsg>



No. 6 Detu Lane 4, Singapore 539410

www.bhh.com.sg | facebook.com/bhhsg



MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES



From: Hock Ann (LKK Auto) <HockAnn@lkkauto.com>
Sent: Tuesday, 19 May 2020 10:48 AM
To: raymond@bhh.com.sg
Cc: hasrianah@bhh.com.sg; Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: Re: FBN 1758T FINALIZED CLOSE CASE MARKING ESTIMATE.

Dear raymond,hasrianah,

Good day, kindly refer vehicle FBN 1758T YAMAHA NMAX 155 after management audit checking marking updated .

finalized total PART/PART repair amount ,

COR - \$ 1829.30 (non include GST 7%)

DOR - 4 DAYS



QUOTATION

Customer :

NO. : 35822

- Rev. 1

INDIA INTERNATIONAL INSURANCE P.L.
64 CECIL STREET
#04-00 & #06-00
IOB BUILDING
SINGAPORE 049711
INDIA INTERNATIONAL INSURANCE P.L.

DATE : 12/03/2020
CLAIM NO. : 11528
POLICY NO. : AVFMSB0000651901

FROM : HASRIANAH

VEHICLE NO. : FBN1758T
MAKE/MODEL : YAM / NMAX155 ABS

Final list

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BELLY PAN (<i>Lower cover</i>) P/N: 58094	REPLACE	1.00	\$34.00 Disc %: 10.00	30.60 ✓
2	BOARD FOOTREST LH P/N: 59588	REPLACE	1.00	\$52.00 Disc %: 10.00	46.80 ✓
3	BOARD FOOTREST RH P/N: 59589	REPLACE	1.00	\$52.00 Disc %: 10.00	46.80 ✓
4	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220	REPLACE	1.00	\$222.00 Disc %: 10.00	199.80 ✓
5	BRACKET BOX REAR (GIVI) P/N: 55428	REPLACE	1.00	\$62.00 Disc %: 10.00	55.80 ✓
6	COVER CLUTCH OUTER (<i>belting cover outer</i>) P/N: 58147	REPLACE	1.00	\$28.00 Disc %: 10.00	25.20 ✓
7	COVER RADIATOR P/N: 63127	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80 ✓
8	COVER SIDE CENTRE RH (WHITE) P/N: 58117	REPLACE	1.00	\$30.00 Disc %: 10.00	27.00 ✓
9	COVER SIDE REAR LH (WHITE) P/N: 58170	REPLACE	1.00	\$40.00 Disc %: 10.00	36.00 ✓
10	COVER SIDE REAR RH (WHITE) P/N: 58102	REPLACE	1.00	\$40.00 Disc %: 10.00	36.00 ✓
11	ENGINE BRACKET COMP P/N: 61969	REPLACE	1.00	\$70.00 Disc %: 10.00	63.00 ✓
12	LABOUR (<i>LABOUR</i>) P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	1.00	\$260.00	260.00 ✓
13	LAMP SIGNAL FRONT LH P/N: 59587	REPLACE	1.00	\$35.00 Disc %: 10.00	31.50 ✓

*35822 *

bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
14	LEVER BRAKE LH P/N: 58145	REPLACE	1.00	\$18.00 Disc %: 10.00	16.20 ✓
15	LEVER BRAKE RH P/N: 58185	REPLACE	1.00	\$18.00 Disc %: 10.00	16.20 ✓
16	MUDGUARD FRONT (WHITE) P/N: 58087	REPLACE	1.00	\$52.00 Disc %: 10.00	46.80 ✓
17	MUDGUARD REAR P/N: 63129	REPLACE	1.00	\$47.00 Disc %: 10.00	42.30 ✓
18	PIPE EXHAUST ASSY P/N: 58083	REPLACE	1.00	\$407.00 Disc %: 10.00	366.30 ✓
19	PROTECTOR EXHAUST P/N: 58086	REPLACE	1.00	\$38.00 Disc %: 10.00	34.20 ✓
20	RIVET P/N: 56583	REPLACE	7.00	$\times \$2.00 = 14$ Disc %: 10.00	12.60 ✓
21	SPRAY PAINT COVER SIDE REAR LH (Lacquer)	Spray	1.00	\$45.00	45.00
22	SPRAY PAINT COVER SIDE REAR RH (Lacquer)	Spray	1.00	\$45.00	45.00 ✓ <i>120</i>
23	SPRAY PAINT MUDGUARD FRONT (Lacquer)	Spray	1.00	\$30.00	30.00
24	STAND MAIN P/N: 58138	REPLACE	1.00	\$66.00 Disc %: 10.00	59.40 ✓
25	STICKER (CERTIS CISCO) SIDE REAR RH NEW MODEL P/N: 61181	REPLACE	1.00	\$44.00	44.00
26	STICKER (CERTISCISCO) NEW LOGO P/N: 60971	REPLACE	2.00	\$44.00	88.00
27	STICKER (CISCO) MUDGUARD FRONT P/N: 58618	REPLACE	1.00	\$37.00	37.00 ✓ <i>184</i>
28	STICKER (CISCO) SIDE REAR LH NEW MODEL P/N: 61573	REPLACE	1.00	\$15.00	15.00
29	TRANSPORT CHARGES <i>add on to labor</i> P/N: 07169 - FOR COLLECTION OF ACCIDENT BIKE AND DELIVER BIKE BACK TO BASE ONCE REPAIR DONE.		1.00	\$35.00	35.00 ✓
30	COVER SIDE CENTRE LH (WHITE) P/N: 58097	REPLACE	1.00	\$30.00 Disc %: 10.00	27.00 ✓

SUB TOTAL
GST @ 7 %

\$1,829.30
\$128.05

GRAND TOTAL

\$1,957.35

50% deposit required before ordering of parts.

Validity: 30 days

*35822 *

bizSAFE₃



③

S/N Description

Action

Qty Unit Price

Amount

For & on Behalf of

Acknowledge & Accepted By

BAN HOCK HIN CO PTE LTD



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

parts 1367

parts less 10%

1230.30

labour 295

spray 120

stickers 184

total → \$1829.30 #
P/p Amt

4 day mpr

*35822 *

bizSAFE₃





QUOTATION

NO. : 35822

Customer :

INDIA INTERNATIONAL INSURANCE P.L.
64 CECIL STREET
#04-00 & #06-00
IOB BUILDING
SINGAPORE 049711
INDIA INTERNATIONAL INSURANCE P.L.

DATE : 12/03/2020
CLAIM NO. : 11528
POLICY NO. : AVFMSB0000651901

FROM : HASRIANAH

VEHICLE NO. : FBN1758T
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
✓1	BELLY PAN (lower cover) ✓ <i>scr</i> P/N: 58094	REPLACE	1.00	\$34.00	34.00
✓2	BOARD FOOTREST LH ✓ <i>scr</i> P/N: 59588	REPLACE	1.00	\$52.00	52.00
✓3	BOARD FOOTREST RH ✓ <i>scr</i> P/N: 59589	REPLACE	1.00	\$52.00	52.00
✓4	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220 ✓ <i>scr</i>	REPLACE	1.00	\$222.00	222.00
✓5	BRACKET BOX REAR (GIVI) P/N: 55428 ✓ <i>BT</i>	REPLACE	1.00	\$62.00	62.00
✓6	COVER CLUTCH OUTER (locking cover ordered) P/N: 58147 ✓ <i>scr</i>	REPLACE	1.00	\$28.00	28.00
✓7	COVER RADIATOR ✓ <i>scr</i> P/N: 63127	REPLACE	1.00	\$12.00	12.00
✓8	COVER SIDE CENTRE RH (WHITE) ✓ <i>scr</i> P/N: 58117	REPLACE	1.00	\$30.00	30.00
✓9	COVER SIDE REAR LH (WHITE) ✓ <i>scr</i> P/N: 58170	REPLACE	1.00	\$40.00	40.00
✓10	COVER SIDE REAR RH (WHITE) ✓ <i>scr</i> P/N: 58102	REPLACE	1.00	\$40.00	40.00
✓11	ENGINE BRACKET COMP ✓ <i>BT</i> P/N: 61969	REPLACE	1.00	\$70.00	70.00
✓12	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	6.00	\$63.00	378.00 260
✓13	LAMP SIGNAL FRONT LH ✓ <i>scr</i> P/N: 59587	REPLACE	1.00	\$35.00	35.00

*35822 *

*bizSAFE*₃



S/N	Description	Action	Qty	Unit Price	Amount
✓ 14	LEVER BRAKE LH ✓ CRM P/N: 58145	REPLACE	1.00	\$18.00	18.00
✓ 15	LEVER BRAKE RH ✓ CRM P/N: 58185	REPLACE	1.00	\$18.00	18.00
✓ 16	MUDGUARD FRONT (WHITE) ✓ SCR P/N: 58087	REPLACE	1.00	\$52.00	52.00
✓ 17	MUDGUARD REAR ✓ SCR P/N: 63129	REPLACE	1.00	\$47.00	47.00
✓ 18	PIPE EXHAUST ASSY ✓ BT P/N: 58083	REPLACE	1.00	\$407.00	407.00
✓ 19	PROTECTOR EXHAUST ✓ CRM P/N: 58086	REPLACE	1.00	\$38.00	38.00
✓ 20	RIVET ✓ new P/N: 56583	REPLACE	7.00	\$2.00	14.00
21	SHAFT PIVOT (Both) X (svc)	REPLACE	1.00	\$12.00	12.00
✓ 22	SPRAY PAINT COVER SIDE REAR LH (Lacquer)	Spray	1.00	\$63.00	63.00
✓ 23	SPRAY PAINT COVER SIDE REAR RH (Lacquer)	Spray	1.00	\$63.00	63.00
✓ 24	SPRAY PAINT MUDGUARD FRONT (Lacquer)	Spray	1.00	\$49.00	49.00
✓ 25	STAND MAIN ✓ SCR P/N: 58138	REPLACE	1.00	\$66.00	66.00
✓ 26	STICKER (CERTIS CISCO) SIDE REAR RH NEW MODEL P/N: 61181 ✓ new	REPLACE	1.00	\$44.00	44.00
✓ 27	STICKER (CERTISCISCO) NEW LOGO P/N: 60971 ✓ new	REPLACE	2.00	\$44.00	88.00
✓ 28	STICKER (CISCO) MUDGUARD FRONT P/N: 58618 ✓ new	REPLACE	1.00	\$37.00	37.00
✓ 29	STICKER (CISCO) SIDE REAR LH NEW MODEL P/N: 61573 ✓ new	REPLACE	1.00	\$15.00	15.00
30	STOPPER MAINSTAND X (svc) P/N: 54930	REPLACE	1.00	\$17.00	17.00
31	STOPPER, MAIN STAND X (svc) P/N: 61968	REPLACE	1.00	\$7.00	7.00
✓ 32	TRANSPORT CHARGES P/N: 07169 - FOR COLLECTION OF ACCIDENT BIKE AND DELIVER BIKE BACK TO BASE ONCE REPAIR DONE.		1.200	\$56.00	112.00
✓ 33	COVER SIDE CENTRE LH (WHITE) ✓ SCR P/N: 58097	REPLACE	1.00	\$30.00	30.00

1204 {
63.00
63.00
49.00

112.00
35 ✓

SUB TOTAL
GST @ 7 %

\$2,252.00
\$157.64

*35822 *

bizSAFE₃



CERT NO : 2002-1-0363
ISO 9001 : 2015

Quotation Nos. : 35822

S/N	Description	Action	Qty	Unit Price	Amount
GRAND TOTAL					\$2,409.64

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



HASRIANAH

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*P/P repair
without prejudice
Resurvey before paint
check item(?)
4 day 3.45pm
16/3/23
Hock ANN (1/K/L)
Hock ANN@MclAuto.com
PS3/1993 / 674/8934*

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*35822 *

bizSAFE₃

