

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SKC2355S

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

Estimate No: ES2090273/YISHUN
 Date: 17 Mar 2020
 Policy No: D19MTPV01012269
 Veh Reg No: SKC2355S
 Make/Model: BMW BMW 730LI AT
 ABS D/AB 2WD 4DR
 NAV HID SR

WS Ref: TP/AIG
 Claim Type: Third Party
 Accident Date: 08/03/2020
 TP Veh Reg No: SMF7318C

Not authorized

11 Reg B

Repair After Pain

Chassis No: WBAKB22040CN74771
 Engine No: 09997626N52B30AF
 Reg. Date: 24/02/2011

2 days

Estimate Repair Cost to Vehicle No :SKC2355S

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	1,770.00	1 PC	<i>bu</i> 1,770.00	<i>✓</i>
2 REAR BUMPER REINFORCEMENT	710.00	1 PC	710.00	<i>?</i> X NN
3 REAR BUMPER LOWER SKIRT	285.00	1 PC	285.00	<i>?</i> X NN
4 REVERSE SENSORS	328.00	2 PCS	656.00	<i>?</i> X NN
			3,421.00	
		Less 5%	171.05	3,249.95
Labour				
5 REMOVE & REFIX REAR BUMPER ASSY, REVERSE SENSOR, KNOCK & REPAIR REAR PANEL & REALIGN THE SAME	350.00	1 LA	350.00	<i>250</i>
6 PUTTY & RESPRAY ON REAR BUMPER, REAR PANEL	350.00	1 LA	350.00	<i>300</i>
			700.00	700.00
Total				SS 3,949.95
Add GST @ 7%				276.50
Total Amount Payable				SS 4,226.45

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: